

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMO20007793/4+f3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

GBJ1690A

at Workshop m/s

Asienwahr

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

45214

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

1

594A

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

GBJ1690A

Yr Regn:

1/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or (m)

Make:

Toyota hiace

c.c 2982

Colour

silver

A/C:

Insured / Std / NI / NA

Sp.Reading

34243

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTFHT029800246905

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

BS / DUN / EXNOVA / GY / FS / EIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Rear

R/Bal.

L/Bal.

D.O.I.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

LTA # 21784

20/8/20 4/5 @ 11,000 confirmed with AH long

RED:14824.8;57%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 8

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) \$ + RS. SI

) Photos

) Others

TOTAL

Not Authorized
LHK

L/S @ 11,000
8 days

Take photos after 1 year

Submit to insurance.

VEHICLE NO. GBJ 1690A TOYOTA HIACE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	PARTS (LIST ITEMS)			
1	Front bumper 685.10	DO/OE	1450.00	✓
2	Front bumper brackets @98.20	Self	196.40	✓
2	Front bumper side cover garnish @172.00	11	344.00	X
1	Front bumper lower grille (centre) 145.80	11	428.00	✓
1	Front bumper reinforcement	11	682.00	X
1	Front bumper reinforcement foam	NS	112.00	X
1	Front centre grille upper panel	CNE	298.00	✓
1	Front centre grille lower panel	CNE	372.00	✓
2	RHS & LHS Headlamp @984.50 795.10 X2	holder cr2	1960.00	✓ 1590.20
2	RHS & LHS Headlamps mounting @80.00	11	160.00	X
1	Front centre panel (bonnet) 655.10	DO/Self	1225.00	✓
1	Front bonnet inner lock 185.40	11	238.00	✓
1	Front bonnet inner lock catch	NS	48.00	X
2	Front bonnet hinges @72.50	11	145.00	X
1	Front brace panel	Self	98.00	✓
1	Front centre panel (bonnet) badge 68.50	11	72.00	✓
2	Front corner panel RH & LH @540.00	R	1080.00	X
1	Front wiper arm garnish	11	242.00	X
1	Radiator	Self/Pan	1020.00	✓
1	Air con condensor	Self/Pan	1420.00	✓
1	Inter cooler (auxilliary radiator)	11	1540.00	X
1	Front support panel 645.30	Self	782.00	✓
1	Wiper washer tank	11	492.00	X
1	Tailgate 2201.10	body	2250.00	✓
1	Tailgate (compartment) edge weatherstrip	11	375.20	✓
1	Tailgate centre garnish	11	289.50	X
1	Tailgate lock (top)	DO/11	295.20	✓
1	Tailgate lock (lower) catch	11	142.60	X
2	Tailgate damper @322.70	11	645.40	X
2	Tailgate hinges @ 98.50	11	197.00	X
1	Tailgate Third brake light	REFIX 11	0.00	X
1	Tailgate Inner trim board	11	250.00	X
2	Tailgate side rubber @48.00	11	96.00	X
1	Rear wiper washer nozzle	REFIX 11	0.00	X
1	Rear wiper blade	REFIX 11	0.00	X
1	Rear wiper motor	REFIX 11	0.00	X
1	Rear windscreen	REFIX 11	0.00	X
1	Rear windscreen rubber	NS	298.20	X
2	Rear number plate lamp @58.00	11	116.00	X
	PARTS C/F		19359.50	

VEHICLE NO. GBJ 1690A

TOYOTA HIACE

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>	PARTS B/F	19359.50	
1	Rear bumper <i>681.10</i>		<i>7.5</i> 1120.00	
2	Rear bumper side retainer @98.40		<i>11</i> 196.80	X
2	Rear RHS & LHS Corner panel @389.50 <i>168 x 2 = 330.00</i>		<i>201/3.1</i> 779.00	
2	RHS & LHS Taillamp @695.80 <i>388.10 x 2 = 776.20</i>		<i>scap/ra</i> 1391.60	
1	Rear floor panel	REPAIR	<i>12</i> 0.00	X
1	Rear floor panel top protector plate		<i>11</i> 198.00	X
1	Rear end panel (inner)		<i>body 650</i> 782.00	
1	Rear end panel (outer) <i>611.10</i>		<i>body 650</i> 658.00	
1	Spare tyre holder		<i>11</i> 185.50	X
1	Rear exhaust pipe		<i>11</i> 782.00	X
4	Rear exhaust silencer pipe mountings		<i>11</i> 98.00	X
			25550.40	
		less 25%	6387.60	25%
			19162.80	
	<u>SPECIAL NETT ITEMS</u>			
1	Toyota Badge rear		<i>nu</i> 72.00	<i>45</i>
1	70km/hr Sticker		<i>nu</i> 30.00	<i>10</i>
1	Reverse Parking Sensors <i>1 set</i>		<i>shock</i> 280.00	<i>200</i>
1	Rear Windscreen Sealant		<i>nu</i> 100.00	<i>40</i>
1	Rear end panel sealant		<i>nu</i> 100.00	<i>50</i>
1	Rear Licence Plate		<i>set</i> 50.00	<i>15</i>
1	Front Licence Plate		<i>set</i> 50.00	<i>15</i>
1	Radiator coolant		<i>na</i> 40.00	<i>30</i>
	TOTAL PARTS		19884.80	

P-13431.7
25%

P-10073.77

S.V-405.00

L-3300.00

13778.77

20%

11013

VEHICLE NO. GBJ 1690A TOYOTA HIACE

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
	LABOUR		
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components.(Front & Rear)	2400.00	1500
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired (Front & Rear)	2000.00	1400
3	To remove, refix wiring system at accident damaged areas and check for proper function & focus headlamp beam	250.00	30
4	To remove / refix inner trims, fittings, garnish etc at rear compartment so as to facilitate repairs at rear.	250.00 11	X
5	To remove and refix rear windscreen	140.00	100
6	To remove and replace reverse sensors and test for proper function	100.00	50
7	To remove and replace rear exhaust silencer assembly realign to fit and check system function	250.00 11	X
8	To remove and replace radiator & inter cooler pressure test and refill coolant	100.00	> 100
9	To remove and replace air con condensor, vacuum and refill gas	180.00	
10	To perform anti-rust treatment on affected areas	270.00	120
	Labour Total :	5940.00	
	TOTAL (PARTS & LABOUR):	25824.80	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: