

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG20007800/GGA3Q2

Date:

17/05/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800133983

Claimant Vehicle No : SMA4079M**Insured Vehicle No :**

SMF4056C

Date of Loss: 27/07/2020

Nature of Claim:

TP

Claim No:

8218763329SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMA4079M**

Make & Model: TOYOTA VOXY HYBRID, 1.8 X CVT (A)

Engine No: 2ZR0B71101

Reg. Date: 06/06/2018 (Man. Year: 2018)

Chassis No:

ZWR800324959

Colour: Black

Odometer:

148848 km

Engine Capacity: 1797 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: KAPSEN 6 mm

Rear Left Side:

KAPSEN 6 mm

Front Right Side: KAPSEN 6 mm

Rear Right Side:

KAPSEN 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,563.00	538.42	2,024.58	78.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,600.00	900.00	700.00	43.75
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,163.00	1,438.42	2,724.58	65.45
+ GST 7.00/7.00% (S\$)	291.41	100.69	190.72	65.45

Nett Amount (S\$)	4,454.41	1,539.11	2,915.30	65.45
+ Car Rental (6.0 x S\$120.00/day) (S\$)		720.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,261.11		

INSPECTION

Date of Assignment: 28/07/2020

Date Inspected: 29/07/2020

Estimated Period of Repair: 3.0 days

Inspected At: Allswell Motor Traders (HQ)
25 Defu Lane 9
Singapore 539266

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RH FENDER	Buckled	729.00 F	*630.00 FL
2	1		*FRONT BUMPER	Repair	1,719.00 F	*- FL
3	1		*HYBRID LOGO	Necessary	65.00 F	*47.90 FL
4	1		*CLIPS & RETAINER STUDS	Necessary	50.00 FS	*30.00 FS
					Sub Total (\$\$)	707.90
					- List Item Discount on L Items 0.00/25.00% (\$\$)	169.48
					Total Parts (\$\$)	538.42

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	DISMANTLE /ASSEMBLY OF FENDER /BUMPER PANEL KNOCKING ON SUPPORT PANEL	New	800.00	400.00
2	SPRAY PAINTING OF ALL PARTS AFFECTED MOULDING POLISH & WASH	New	800.00	500.00
Gross Labour Cost (\$\$)			1,600.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >