

ASS. REC. BY:

REF:

EQ/ 20007801/Kg

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s Poh Hock

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: 12/23 Person Contacted: _____ Vehicle: IN / OUTVeh No: SDW 2224 Yr Regn: 12, 08Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: BMW 325i c.c. 2497Colour: M. Gray A/C: Insured / Std / NI / NASp. Reading: 110537 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBAWB 32040PV53578Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD / A/Rlm orTyre Size: F: 235/35ZR19R: 265/30ZR19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Nexen

Front

R/Bal. 8 mmL/Bal. 8 mmD.O.A. 24/7/20

Survey held at

Rear

R/Bal. 8 mmL/Bal. 8 mmD.O.I. 30/7/2020

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Acc. O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

18/11/2018 8:24am Car found

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

POH HOCK MOTOR TRADING CO

7A Ontario Ave #03-08, Singapore 576197

Tel: 96696997 Fax: 64594569

Email: boonhockang@hotmail.com

GST No: MX-0468931-E

27.07.2020

KWEK ZHENG NING

4J Marigold Drive

Singapore 576349

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE COST OF REPAIR TO M/CAR SDW222H BMW 325 COUPE

SUPPLY OF PARTS:

1. 1 PC rear bumper	dis. B	1,250.15	✓
2. 2 pc rear bumper side retainer @\$50.20 x 2		100.40	✓
3. 2 pc rear bumper bracket @\$50.20 x 2	R	100.40	X
4. 1 pc rear bumper beam	B	460.85	✓
5. 1 pc rear bumper towing cover	M	39.15	✓
6. / 4 pc rear bumper sensor @\$238.05 x 4	M	952.20	✓
7. 1 pc rear tail lamp	CM	413.00	✓
8. 1 pc rear tail lamp lower garnish	R	55.00	X
9. 1 pc rear boot lid reflector	R	289.10	X

3,660.25

183.01

Less 5%

3,477.24

600.00 2801

LABOUR CHARGE & MISC

To dismantle & replace rear bumper, reverse sensors, Bumper beam, brackets, retainers, garnish, tail lamps, Reflector & reshape /align rear bumper.

600.00 4001

PAINTING:

To putty and spray painting on rear bumper cover and accident affected area.


4,677.24

327.40

GST 7%

Total :

S \$ 5,004.64



Not Authored
11 Sep @ 2400h
Recovery After Paint

3 days