

Reliable Carz Pte Ltd

No.8 Kaki Bukit Ave 4 #05-50 Premier@Kaki Bukit Singapore 415875

H/P : 8166 9797

Name : Reliable Rides Pte Ltd
Address : c/o No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

Date : 16-Jun-20

Final repair bill for vehicle no. SLT 1769 L

To supply and replace parts, labour charges for
repairing, knocking, welding and to respray painting
(Lump Sum Repair)

\$ 9,600.00

Dollar : Nine Thousand And Six Hundred Only

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Invoice No 06-20001/AY

Billing Name & Address

Reliable Rides Pte Ltd

c/o No.8 Kaki Bukit Ave 4

#05-50 Premier@Kaki Bukit

Singapore 415875

Date 16 Jun 2020

Vehicle No : SLT 1769 L

Model : Honda Shuttle

Item	Descriptions	Amount S\$
1	Date of inspection : <u>3 Jun 2020</u> A copy of the inspection / survey report Correspondence, postages and etc.	
2	Photography Services - Purchase of films, develop negatives - Storage of negatives - Submission of photographs <u>145</u> copies	
3	Transportation Charges	
4	2nd Inspection & Final Inspection	
	Total	<u>\$ 870.00</u>
	SDLS : EIGHT HUNDRED AND SEVENTY ONLY	

Notes :

1. All cheque payment should be "Crossed" and made payable to "Pal's Appraiser Pte. Ltd."
2. All cheque should have our "Invoice No." written on the reverse side of the cheque
3. For further enquiries on this invoice, please feel free to contact us



Official Stamp

E & O. E

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883

Tel: 81818802 Fax: 67471017 Registration No: 201000268D

Report Reference : TP / 06-20001/AY / 2020

Date of Report : 16 Jun 2020

Reliable Rides Pte Ltd
c/o No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

THIRD PARTY SURVEY

ACCIDENT HAPPENED ON 2 Jun 2020

As per your instruction dated 3 Jun 2020 with regard to the above matter. We have carried out a physical inspection on the said vehicle SLT 1769 L. We enclosed herewith our report and findings as follows:

1. VEHICLE PARTICULARS

Registration No : SLT 1769 L
Model : Honda Shuttle
Year / Capacity : 2017/1496
Chassis No : GP71121025
Engine No : LEB6325926
Mileage : 192495
Colour : Black

2. TYRES CONDITION

			<u>Size</u>	<u>Made</u>	<u>Balance</u>		<u>Rim</u>
FRONT	O/S	:	185/60 R15	Neuton	5.00	mm	Normal
REAR	O/S	:	185/60 R15	Achilles	5.00	mm	Normal
FRONT	N/S	:	185/60 R15	Neuton	5.00	mm	Normal
REAR	N/S	:	185/60 R15	Achilles	5.00	mm	Normal

PAL'S

APPRAISER PTE LTD

No. 1 Kaki Bukit Ave 6 #01-53 AutoBay @ Kaki Bukit Singapore 417883
Tel: 81818802 Fax: 67471017 Registration No: 201000268D

3. DESCRIPTION OF DAMAGES

At the time of inspection, we noted that the vehicle has sustained an impact damages on the rear portion(s). For more detail of the damages, please see photograph attached.

4. Workshop Address : Reliable Carz Pte Ltd
No.8 Kaki Bukit Ave 4
#05-50 Premier@Kaki Bukit
Singapore 415875

5. Estimated normal period of repair : **10** working days to complete.

6. Enclosed number of photograph : **145** copies.

7. In accordance to your instruction, we have **Not Authorised** repair to the vehicle and the survey was done on a "**Without Prejudice**" basis. We hope that this report will be of assistance to you in dealing with the matter.

8. Should you discover any discrepancy in the report, please kindly notify us **within 2 weeks**, or the report will be treated as correct.

Disclaimer

The rates and assessment of damages as stated in this report is to be used solely for legal proceedings in relation to the surveyed vehicle and the accident in which the surveyed vehicle was involved in. The rates and assessment of damages must not be used in any circumstances for comparison with other vehicles and/or other accidents in other legal proceedings.

Vehicle No: **SLT 1769 L**
 Report No: **TP/ 06-20001/AY / 2020**

SPARE PARTS

Qty	Parts Description	Condition	Workshop's Estimation	Our Revised Estimation
<u>List Items</u>				
1	Rear windscreen moulding	Necessary	\$ 95.60	\$ 95.60
1	Rear tailgate	Damage	\$ 1219.00	\$ 1219.00
2	Rear tailgate dampers	Damage	\$ 330.00	\$ 330.00
1	Rear tailgate inner board	Intact	\$ 320.00	\$
2	Rear tailgate lamps	Damage	\$ 828.00	\$ 828.00
1	Rear tailgate lock	Damage	\$ 126.50	\$ 126.50
1	Rear tailgate logo	Damage	\$ 38.00	\$ 38.00
1	Rear tailgate outer garnish	Damage	\$ 383.00	\$ 383.00
1	Rear tailgate outer chrome handle	Damage	\$ 506.10	\$ 506.10
1	Rear tailgate inner handle	Damage	\$ 27.00	\$ 27.00
1	Rear tailgate rubber	Damage	\$ 168.50	\$ 168.50
1	Rear tailgate 'SHUTTLE' emblem	Damage	\$ 69.00	\$ 69.00
1	Rear tailgate 'HYBRID' emblem	Damage	\$ 45.00	\$ 45.00
1	Rear o/s taillamp	Damage	\$ 520.50	\$ 520.50
1	Rear end panel	Damage	\$ 560.80	\$ 560.80
1	Rear end panel inner garnish	Damage	\$ 155.50	\$ 155.50
2	Rear end side panels	Damage	\$ 252.00	\$ 252.00
1	Rear bumper	Damage	\$ 1072.50	\$ 1072.50
1	Rear bumper o/s inner sponge	Damage	\$ 81.90	\$ 81.90
1	Rear bumper o/s reflector	Damage	\$ 74.10	\$ 74.10
1	Rear bumper o/s reflector cover	Damage	\$ 33.20	\$ 33.20
2	Rear bumper side retainers	Necessary	\$ 75.00	\$ 75.00
1	Rear bumper towing cover	Damage	\$ 25.00	\$ 25.00
1	Rear spare tyre panel	Damage	\$ 1980.00	\$ 1980.00
1	Rear spare tyre tools tray	Damage	\$ 285.00	\$ 285.00
1	Rear exhaust silencer	Damage	\$ 794.00	\$ 794.00
2	Rear exhaust silencer mountings	Necessary	\$ 64.00	\$ 64.00
1	Rear o/s fender	Repair	\$ 1326.10	\$
1	Rear o/s fender inner garnish	Damage	\$ 460.30	\$ 460.30
			\$ 11915.60	\$ 10269.50
	Discount	20.0%	\$ 2383.12	\$ 2053.90
			\$ 9532.48	\$ 8215.60
<u>Special Nett Items</u>				
1	Rear windscreen sealant	Necessary	\$ 100.00	\$ 50.00
1	Rear bumper clip (1 set)	Necessary	\$ 39.00	\$ 39.00
1	Rear reverse sensor (1 set)	Damage	\$ 280.00	\$ 280.00
1	Rear reverse camera	Damage	\$ 450.00	\$ 450.00
			\$ 869.00	\$ 819.00
	Spare Parts Total		\$ 10401.48	\$ 9034.60

Vehicle No: **SLT 1769 L**
 Report No: **TP/ 06-20001/AY / 2020**

LABOUR COST

S/No	Job Descriptions	Workshop's Estimation	Our Revised Estimation
	Spare Parts Total c/f	\$ 10401.48	\$ 9034.60
1	To remove and refit rear electrical wiring, replaced damaged lamps and test for proper functioning.	\$ 50.00	\$ 40.00
2	To remove and refit inner trims, inner garnishes, to facilitate the repairs.	\$ 150.00	\$ 100.00
3	To remove and refit rear bumper sensor.	\$ 150.00	\$ 80.00
4	To remove and refit rear windscreen glass.	\$ 200.00	\$ 120.00
5	To remove and refit, straighten and re-adjust exhaust pipe and replace rear exhaust silencer and mountings.	\$ 100.00	\$ 80.00
6	To remove and replace the above damaged parts, straighten, knock out, realign and repair including cut and weld body panels. To re-adjust to the original position using power tools.	\$ 1800.00	\$ 1320.00
7	To spray paint on the replaced and repaired parts, prepare spray such as masking tape the unaffected areas with paper, cleaning and sanding of surfaces, final polishing and waxing are also available.	\$ 1800.00	\$ 1100.00
8	To apply undercoating on the repaired and replaced panels for rust protection.	\$ 150.00	\$ 90.00
Total		\$ 14801.48	\$ 11964.60

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair Contract of:

\$ 9600.00

SDLS: NINE THOUSAND SIX HUNDRED ONLY


 Qualified Appraiser





































