Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20007812/AEA3Q2

Date: 14/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700047595

Claimant
Vehicle No: GBH7952R Insured Vehicle No: SKK1472B

Date of Loss: 26/07/2020 Nature of Claim: TP Claim No: 3898821469SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBH7952R

Make & Model: TOYOTA HIACE, 3.0 (A) Engine No: 1KD2827109

Reg. Date: 28/09/2018 (Man. Year: 2018) Chassis No: JTFHT02P100245269

Colour: Green Odometer: 44999 km

Engine Capacity: 2982 cc
Market Value/New Car
N/A

Price: N//

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15C Rear Tyre Size: 195 R15C
Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,749.32	4,282.42	466.90	9.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,310.00	1,350.00	960.00	41.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,059.32	5,632.42	1,426.90	20.21
Approved Total (Overridden) (S\$)		4,500.00		
(S\$)	7,059.32	4,500.00	2,559.32	36.25
+ GST 7.00/7.00% (S\$)	494.15	315.00	179.15	36.25
Nett Amount (S\$)	7,553.47	4,815.00	2,738.47	36.25
+ Car Rental (6.0 x S\$100.00/day +	7.00% GST) (S\$)	642.00		
+ Doc	Search Fee (S\$)	2.00		
N	ett Liability (S\$)	5,459.00		

INSPECTION

Date of Assignment: 28/07/2020

Date Inspected: 28/07/2020 Inspected At: Kang Car Repairers Pte Ltd (HQ)

No 1 Kaki Bukit Ave 6, #02-06

AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster Report Page 2 of 4

Adjuster: ADRIAN LING Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT DOOR RH	Dented	1,794.10 FL	*1,794.10 FL
2	1		*FRT DOOR HINGE RH	Lower Bent	170.40 FL	*85.20 FL
3	1		*FRT DOOR RUBBER RH	Not Necessary	185.80 FL	*- FL
4	1		*FRT DOOT TRIM RH	Cracked	751.10 FL	*751.10 FL
5	1		*FRT RH STEP GARNISH	Cut	182.70 FL	*182.70 FL
6	1		*FRT BUMPER	Deformed	487.10 FL	*487.10 FL
7	1		*FRT BUMPER SIDE RETAINER RH	Necessary	193.30 FL	*193.30 FL
8	1		*FRT FOG LAMP COVER RH	Not Necessary	58.20 FL	*- FL
9	1		*HEADLAMP RH	Cut	898.70 FL	*898.70 FL
10	1		*AIR CLEANER BOX	Cracked	637.70 FL	*637.70 FL
11	1		*FRT DOOR COMPANY INFO STICKER RH	Necessary	30.00 FS	*30.00 FS
12	1		*FRT DOOR STICKER	Necessary	300.00 FS	*200.00 FS
13	1		*FRT BUMPER STICKER	Necessary	250.00 FS	*200.00 FS
14	1		*FRT RH STEP GARNISH STICKER	Necessary	150.00 FS	*80.00 FS
F=Fra	anchise	part. S=Spc	Nett. L=ListItemDisc.	,		
				Sub Total (S\$)	6,089.10	5,539.90
	- List Item Discount on L Items 25.00/25.00% (S\$)			1,339.78	1,257.48	
				Total Parts (S\$)	4,749.32	4,282.42
				,		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount					
Lab	<u>Labour Items</u>								
1	TO CHECK WIRING	New	50.00	30.00					
2	(FRONT) TO SPRAY PAINTING	New	1,000.00	600.00					
3	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS A FOR CUTTING/WELDING WORKS	New ND	1,000.00	600.00					
4	TO REPLACE STICKERS	New	200.00	120.00					
5	HEADLAMP ALIGNMENT	New	60.00	0.00					
	Gross Lab	2,310.00	1,350.00						
	Report was unsubmitted du	ring this print-out.							

< END OF ESTIMATES >