Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

Our File No: CS/CTI20007814/KQF3E2

3 Anson Road, #16-00 Springleaf Tower Singapore 079909

Date: 02/11/2020

REFERENCE

Insured/Claimant: DMPCSNW00055642003 LIM KHIM SONG Policy No:

Date of Loss: 13/07/2020 Nature of Claim: Claim No: SNM20D202430C01

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: **SLD2982P** 

VOLVO S60, 1.5 T2 (A) Make & Model: Engine No: B4154T51581604 Reg. Date: 10/06/2016 (Man. Year: 2016) Chassis No: YV1FS28C0G2413428 Odometer: 50295 km

Colour: Metallic Grey

**Engine Capacity:** 1498 cc Market Value/New Car Price: S\$71,000.00

Sum Insured (S\$): **Market Value/New Car Price** 

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

Front Tyre Size: 215/55 R16 Rear Tyre Size: 215/55 R16 Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm Front Right Side: Rear Right Side: Yokohama 7 mm Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,065.50	2,893.00	172.50	5.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,865.00	1,110.00	755.00	40.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,930.50	4,003.00	927.50	18.81
Approved Total (Overridden) (S\$)		3,200.00		
- Excess (S\$)	500.00	500.00	0.00	0.00
(S\$)	4,430.50	2,700.00	1,730.50	39.06
+ GST 7.00/7.00% (S\$)	310.14	189.00	121.14	39.06
Nett Amount (S\$)	4,740.64	2,889.00	1,851.64	39.06

**INSPECTION** 

Date of Assignment: 29/07/2020

Date Inspected: 04/08/2020 Inspected At: Alan's United Auto Pte Ltd (HQ)

Blk 7 Sin Ming Industrial Estate, #01-76

Singapore 575642

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: KENNETH KONG Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

Reference				
Part Source:	: MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2020)		
Parts:	143	VOLVO S60 1.5 T2 (A) (Catalogue:Merimen Singapore 1.0)		
Labour:	Repairer's	(Price-denominated Standard List)		
Print Code:	(Unsubmitted, no print-code for SLD2982P)			
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page			
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.				

## **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT N/S FENDER (WCP)	Bent	850.00 F	*850.00 F
2	1		*FRONT N/S FENDER INNER SHIELD (WCP)	Serviceable	150.00 F	*-F
3	1		*FRONT N/S SIDE MIRROR HOUSING (WCP)	Cracked	500.00 F	*500.00 F
4	1		*FRONT N/S MIRROR COVER (WCP)	Missing	200.00 F	*200.00 F
5	1		*FRONT N/S MIRROR COVER LAMP (WCP)	Missing	90.00 F	*90.00 F
6	1		*FRONT N/S MIRROR GLASS (WCP)	Mtg Cracked	180.00 F	*180.00 F
7	1		*FRONT N/S SPORT RIM	Dented	800.00 FS	*800.00 FS
F=Fra	F=Franchise part. S=SpcNett.  Sub Total (S\$)  + Margin on L,N Items 15.00/15.00% (S\$)			<b>2,770.00</b> 295.50	<b>2,620.00</b> 273.00	
Total Parts (S\$)			3,065.50	2,893.00		

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	65.00	60.00
2	TO PUTTY AND SPRAY REPLACED PARTS	New	1,000.00	550.00
3	TO REMOVE, CUT-OUT DAMAGED PARTS, PANEL BEATING, WELDING, ALIGN, REFIX AND TO RENEW ABOVE PARTS	New	800.00	500.00
	Gross Labou	r Cost (S\$)	1,865.00	1,110.00
	Report was unsubmitted during	this print-out.		

< END OF ESTIMATES >