

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20007815/R1VF3E2

Date: 24/08/2020

REFERENCE

Insured/Claimant: PETER MILTON SIVATHASAN Policy No: DMPCSNW00072222000

Date of Loss: 24/07/2020

Nature of Claim: OD

Claim No: SNM20D202582C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGD8688J**

Make & Model: VOLKSWAGEN SHARAN, 2.0 TSI (A)

Engine No: DED012455

Reg. Date: 30/06/2017 (Man. Year: 2017)

Chassis No: WVWZZZ7NZHV236734

Colour: Grey

Odometer: 53551 km

Engine Capacity: 1984 cc

Market Value/New Car Price: S\$98,000.00

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R18

Rear Tyre Size:

225/45 R18

Front Left Side: Michelin 6 mm

Rear Left Side:

Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side:

Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,456.78	9,159.07	6,297.71	40.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,940.00	3,410.00	4,530.00	57.05
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	23,396.78	12,569.07	10,827.71	46.28
- Excess (S\$)	750.00	750.00	0.00	0.00
(S\$)	22,646.78	11,819.07	10,827.71	47.81
+ GST 7.00/7.00% (S\$)	1,585.27	827.33	757.94	47.81
Nett Amount (S\$)	24,232.05	12,646.40	11,585.65	47.81

INSPECTION

Date of Assignment: 29/07/2020

Date Inspected: 30/07/2020 Inspected At:

Volkswagen Centre Singapore (HQ)
NO 17 TUAS AVE 9
SINGAPORE 639197

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2020)
Parts:	M1-MPV	VOLKSWAGEN SHARAN 2.0 TSI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGD8688J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TYRE MICHELIN PRIMACY 4 225/45/18 (70%)	Cut	780.00 FS	*546.00 FS
2	1		*SOUND BAFFLE ENGINE LOWER COVER	Deformed	259.80 FS	*259.80 FS
3	1		*PLUG	Missing	6.08 FS	*6.08 FS
4	1		*OLWANNE-UNTERTELL OIL SUMP	Cracked	367.17 FS	*367.17 FS
5	1		*GASKET FOR OIL PAN	Necessary	44.60 FS	*44.60 FS
6	2		*SEAL RING	Necessary	17.44 FS	*17.44 FS
7	1		*SILICONE ADHESIVE SEALANT	Necessary	51.02 FS	*51.02 FS
8	5		*ENGINE OIL 5W40 1LITRE B	Necessary	160.50 FS	*160.50 FS
9	1		*FILTER ELEMENT WITH GASKET OIL FILTER	Necessary	37.30 FS	*37.30 FS
10	1		*DEGREASER CLEANER 500ML	Necessary	38.22 FS	*38.22 FS
11	1		*KRAFTSTOFFBEHALTER FUEL TANK	Scratched	1,940.08 FS	*1,940.08 FS
12	1		*ENTLUFTUNGSLEITUNG BREATHER LINE	Necessary	115.53 FS	*115.53 FS
13	1		*SEAL RING	Necessary	23.80 FS	*23.80 FS
14	2		*ALLOY WHEEL GREY-METALLIC	Serviceable	4,814.66 FS	*- FS
15	2		*RUBBER VALVE	Not Necessary	6.58 FS	*- FS
16	1		*TRACK CONTROL ARM	Scratched	484.88 FS	*484.88 FS
17	1		*GUIDE JOINT	Bent	141.20 FS	*141.20 FS
18	1		*WHEEL BEARING WITH MOUNTI	Bent	588.71 FS	*588.71 FS
19	1		*WHEEL BEARING HOUSING	Bent	700.72 FS	*700.72 FS
20	1		*GAS-FILLED SHOCK ABSORBER	Bent	404.48 FS	*404.48 FS
21	1		*BALL BEARING TOP BEARING	Necessary	31.76 FS	*31.76 FS
22	1		*SUSPENSION STRUT MOUNTING TOP MTG	Necessary	93.93 FS	*93.93 FS
23	1		*TIE ROD	Bent	102.45 FS	*102.45 FS
24	1		*TIE ROD END	Bent	140.95 FS	*140.95 FS
25	2		*RETAINING CLIP	Necessary	9.72 FS	*9.72 FS
26	1		*DRIVE SHAFT WITH CONSTANT	Scratched	2,814.51 FS	*2,814.51 FS
27	1		*WHEEL BEARING WITH MOUNTI REAR WHEEL BEARING	Serviceable	502.27 FS	*- FS
28	1		*WHEEL BEARING HOUSING REAR WHEEL BEARING HOUSING	Serviceable	740.20 FS	*- FS
29	1		*DEGREASER CLEANER 500ML	Necessary	38.22 FS	*38.22 FS
Total Parts (\$\$)						15,456.78 9,159.07

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	CHECK SHORT CIRCUIT / HARNESS REPAIR	New	280.00	0.00
2	DIAGNOSTIC AND PROGRAMMING	New	480.00	480.00
3	R&R RIM & BALANCE	New	100.00	50.00
4	R&R FRT U/CARRIAGE	New	2,520.00	1,260.00
5	R&R OIL SUMP	New	840.00	420.00
6	R&R REAR U/CARRIAGE	New	1,680.00	0.00
7	R&R FUEL TANK	New	1,680.00	840.00
8	WHEEL ALIGNMENT	New	360.00	360.00
Gross Labour Cost (S\$)			7,940.00	3,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >