

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

Vehicle & Document Information

WIP No 44027

Reg No/Reg Date SLA3132K / 03/02/2015

30/07/2020/ 107436 Date In/Mileage

WDD2050402R034410 Chassis No

27491030263073 Engine No

Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A

027 755 Tenorite Gr/ 041 101 ARTICO Blac Colour/Trim

Accoun	nt No Terms	Dat	e/Time Prin	ted	CSE	Operator				
CS1000	003 Cash	12/	08/2020/	16:46	VS	356 / Vincent	Seah			
la E			Descriptio	n of Goods /	Services		Qty	Unit Price	Disc%	Amount
DAT	LICY NO/ACC D W IN/EXCESS TE IN/DATE SU /AUTHRIZED ON	RVEY: 29	9.07.2020	11801/// // \$750 // 29.0 LKK // 29	7.2020 RA	20	2 000	AX II		OICE
	BBER BEARING						2.00	26.73		53.46
	PNEUMATIC SP	RING					(1.00	108.38	00.00	108.38
X RH	PNEUMATIC SP	RING				پانس <i>ی</i>	1.00	108.38	00.00	108.38
X SCF	REW						\2,00	4.59	00.00	9.18
X HEX	KAGON HEAD BO	_T					, 4√00	4.27	00.00	17.08
X AIR	R DUCT SEGMEN	Γ .				100000	1.00	170.11	00.00	170.11
X LH	HINGE				ノつヽ	UZREZE	1.00	190.53	00.00	190.53
X RH	HINGE		(a)	<i>(</i> 50)		$M_{D_{\alpha}}$	1.00	190.53	00.00	190.53

Confirmed & accepted by

Nett

868.63

7% GST on

868.63

60.80

Total Payable

929.43

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

Vehicle & Document Information

WIP No 44027

/ 03/02/2015 Reg No/Reg Date SLA3132K

Date In/Mileage

30/07/2020/ 107436 WDD2050402R034410

Chassis No Engine No

27491030263073

Make/Model

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A

Colour/Trim

027 755 Tenorite Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Prin	ited	CSE	Operator	J. J. S. S. S. S.		101	100	
CSI00003	Cash	12/08/2020/	16:52		356 / Vincent Se	ah				
		findings and some problems and a some some	n of Goods	/ Services		Decree Configuration	Qty Unit	Price	Disc%	Amount
M BPNSUN						December 1990 - L		EC EA	m va zo	
		E:DHOM1200357			= FICIA	\				(0)(C)
DATE IN	/DATE SURVI	: 29.07.2020 EY: 29.07.2020	*// \$*/30** ⊧ // 29.0	7.2020 RASUL		ok terenera		***	West 2007	
BY/AUTH	RIZED ON	:shiau chan-	LKK // 29	.07.2020			بالخبير			
S BPNTOW	T TOWING E	R TAMPINES AVE	10 TO DI	sc.						150.00
	ING DOLLEY	TAMPINES AVE	10 10 PL	3C						
WO: 177	854					" \\\	11/2			
A BPILAB	אדפע דה ראו	ECK CONTROL UN	TTC & DEC	ET MEMODY TO	$A \mid A \mid$				0.10	380.00
	D SETTINGS.		IIS & KES	ET MEMORT TO	ヘハルニ	3				
S BPNSUB					MAN HAD	. 202-				60.00
SUPPLY A BPILAB	1 PC NO PLA	ATE	J.,	$\Delta N = N N$						120.00
	REPLACE H	HEADLAMP WITH	FOCUS ADJ	USTMENT.NETT						120.00
A BPILAB	0 DEDI 4.0E	DADIATOR SOOF	Puo overe) DONNEHCED					İ	600.00
		RADIATOR, COOL SE OF REFRIGER			MIIH					
A BPILAB		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	and the same of th							3840.00
REMOVE & SUPPORT		N FRONT BUMPÉ	R, RHF/LHI	F FENDER, BO	NNET, FRONT					
A BPIRES	PANEL									2400.00
		UMPER, BONNET	,RHF/LHF F	ENDER						
	IMPER COVER							8.52 0		28.52
X RIVET	OUSE COVERI	NG						7.51 0 5.87 0		127.51 23.48
	NT FENDER							9.45 0		929.45
X FRONT BU		ĆDILLE.						0.69 0		1580.69
	IMPER LOWER PLATE MOLD							0.49 0 0.49 0		130.49 130.49
	STANCE SEN							8.75 0		715.00
X BOTTOM B	ASIC MOUNT	ING FRT BUMP	ER			1.	00 14	4.28 0	0.00	144.28

Confirmed & accepted by

Authorized signatory and company stamp

Rinalization . Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.







Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X


Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

	Vehicle & Document Information
WIP No	44027
Reg No/Reg Date	SLA3132K / 03/02/2015
Date In/Mileage	30/07/2020/ 107436
Chassis No	WDD2050402R034410
Engine No	27491030263073
Make/Model	MB/MB C 180 SEDAN (W205) "AVANTGARDE / A
Colour/Trim	027 755 Tenorite Gr/ 041 101 ARTICO Blac

Account No Terms	Date/Time Printed	CS	E Operator			
CSI00003 Cash	12/08/2020/ 16	:52	356 / Vincent Se	eah		
	Description o	f Goods / Sen	ices	Qty	Unit Price Disc%	Amount
X TOP BASIC MOUNTING	FOR BUMPER	ABB		1.00	89.03 00.00	89.03
X IMPACT ABSORBER	FOR BUMPER		OFFICIA	1.00	164.30 00.00	164.30
X LHF BASIC MOUNTING	FOR BUMPER				83.81 00.00	83.81
X RIVET				4.00	4.59 00.00	18.36
X LHF FOGLAMP COVER	DNAMENTAL MOLDE	10		1.00	85.07 00.00	85.07
X TOP LEFT FOGLAMP O				1.00	71.47 00.00	71.47
X BOTTOM LEFT FOGLAM X HOOD	P ORNAMENTAL MU	_DING		1.00	59.56 00.00 2114.35 00.00	59.56 2114.35
X COMPANY SIGN				1.00	77.91 00.00	77.91
X LH/RH BONNET ACTUA	T∩D			2.00	190.15 00.00	380.30
X AIR DUCT	TOK			1.00	129.77 00.00	129.77
X RADIATOR PROTECTIV	F GRILLE		- < < < < < < < < < < < < < < < < < < <	1.00	136.40 00.00	136.40
X STAR CARRIER BEAM-			>Ω////////////////////////////////////	1.00	215.44 00.00	215.44
X TOP LEFT ORNAMENTA		-		1.00	68.20 00.00	68.20
X BOTTOM LEFT ORNAME		/ [/] /		1.00	84.28 00.00	84.28
X TOP RIGHT ORNAMENT		É L		1.00	68.20 00.00	68.20
X BOTTOM RIGHT ORNAM		Company of the Compan		1.00	84.28 00.00	84.28
X MERCEDES STAR CARR				1.00	77.44 00.00	77.44
X MERCEDES STAR		No.		1.00	136.49 00.00	136.49
X LHF HEADLAMP UNIT				1.00	3280.44 00.00	3280.44
X RHF HEADLAMP UNIT				1.00	3280.44 00.00	3280.44
X CROSS MEMBER				1.00	438.32 00.00	438.32
X LHF STRUT				1.00	48.09 00.00	48.09
X LHF BRACKET				1.00	75.93 00.00	75.93
X RHF BRACKET				1.00	73.70 00.00	73.70
X FRONT SUPPORT CONS				1.00	224.99 00.00	224.99
X FRONT SUPPORT PANEL	SILVER			1.00	743.26 00.00	743.26
X LHF/RHF ABSORBER				1.00	99.58 00.00	99.58
X COVER F ENGINE COM				1.00	195.74 00.00	195.74
X RH ENGINE COVER BRA				1.00	27.86 00.00	27.86
X REFIGERANT CONDENSE	ER .			1.00	1472.72 00.00	1472.72
X PRESSURE SENSOR				1.00	191.59 00.00	191.59
X ELECTRICAL WIRING H	1ARNESS			1.00	152.55 00.00	152.55
Confirmed & accepted by						
				\%\		
				\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\		
				/8	.x.	
Authorized signatory and o	company stamp			rinaliz.	(O)	
- Totalonzou organicory and c						

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

Vehicle & Document Information

WIP No 44027 Reg No/Reg Date SLA3132K / 03/02/2015

Date In/Mileage 30/07/2020/-107436 WDD2050402R034410 Chassis No

27491030263073 Engine No

Make/Model MB/MB C 180 SEDAN (W205) "AVANTGARDE / A Colour/Trim 027 755 Tenorite Gr/ 041 101 ARTICO Blac

Account No Terms Date/Time Printed CSE Operator CSI00003 Cash 12/08/2020/ 16:52 356 / Vincent Seah Description of Goods / Services Qty Unit Price Disc% Amount BPNEXC 750.00 INSURANCE EXCESS 20.98 CLIP 2.00 RUBBER BEARING 26.73 00.00 53.46 LH PNEUMATIC SPRING 1.00 108.38 00.00 108.38 RH PNEUMATIC SPRING 108.38 00.00 108.38 FRONT BUMPER CHROME MOULDING 186.41 00.00 186.41 4.59 00.00 9.18 SCREW 2.00 HEXAGON HEAD BOLT 4.00 4.27 00.00 17.08 AIR DUCT SEGMENT 170.11 00.00 170.11 Χ 1,00 1.00 χ LH HINGE 190.53 00.00 190.53 RH HINGE 190.53 00.00 190.53

Confirmed & accepted by

7% GST on

Nett 26114.82

26,114.82 1828.04

Total Payable

27,942.86

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.