Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

Mobile: +6590991236

Vehicle & Document Information

44027 WIP No

SLA3132K / 03/02/2015 Reg No/Reg Date

1107436 Date In/Mileage WDD2050402R034410 Chassis No

27491030263073 Engine No

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A Make/Model

027 755 Tenorite Gr/ 041 101 ARTICO Blac Colour/Trim

Account No CS100003 M BPNSUN POLICY NO	Cash	29/07/2020/ 10:28 Description of Goods	VS	356 / Vincent Seah				The second secon
M BPNSUN		Description of Goods	1020				D1 -0/	Amount
POLICY NO			/ Services		Qty	Unit Price	Disc%	Amount
POLICY NO			THE SALE OF SALES	FFIOIAL	TA	VIA	17/1	DICE
一 中野中、韓国野 YE、YA	ACC DATE	:DHOM120035711801 //	29.07.202	FFICIAL	IA		AA	UIUL
I TOWIN EXC	FSS V	29.07.2020 4//						
DATE IN/DA	ATE SURVE	Y: 29.07.2020 //			1			150.00
BY/AUTHRIZ	ZED ON	•			The same of the sa		3	/ 150.00/
BPNTOW TOWING					211		0.10	380.00
RPTI AR					115	0	0.10	7 500.007
"USE XENTE	RY TO CHE	CK CONTROL UNITS & RE	SET MEMORY	10	1 1			
STANDARD S	SETTINGS.	NETT"		7 11/1	17			60.00
BPNSUB		THE WITH HOUSTNE N	ICTT	011111111111111111111111111111111111111				
	PC NUMBER	PLATE WITH HOUSING.	77	THAMILIA				
FRONT			1	111/1/17				/ 120.00/
BPILAB	DEDLACE H	EADLAMP WITH FOCUS AL	JUSTMENT . NE	44 17 0				X10 ? 540.00
BPILAB	ALI LAGE II	100	11	D				X/10 . 540.00
INSPECT &	CONDUCT	WHEEL ALIGNMENT NETT	7) 1					600 960.00
RDTI AR		1100	11	IN LUTE				/
"REMOVE &	REPLACE	RADIATOR COOLING SYS	FEM, CONDENSE	K MITH				/
	D RECHARG	E OF REFRIGERANT NET				7	3840	4520 5280.00
BPILAB	DEDLACE O	N FRONT BUMPER, RHF/	HE FENDER.	BONNET, FRONT				
SUPPORT P		in I Kolet Dotti Elky kim /						-1500 2000 00
RPIRES							/	2400 3000.00
RESPRAY OF	N FRONT B	UMPER, BONNET, RHF/LHI	F FENDER		1.00	127.51	00.00	127.51
RHF FENDE	R OUTER L	INEAR X >VC			1.00	28.52		28.52
UPPER BUMP	PER COVER	SEALING ALL			1.00	127.51	00.00	127.51
LHF FENDER	R OUTER L	INEAR CONT			4.00	5.87	00.00	23.48
RIVET	T CENDED	4/			1.00	929.45	00.00	929.45
LEFT FRONT	I FENDEK UT EENDED	Rescie			1.00	929.45		929.45
FRONT BUMF	PER TORAL	7			1.00	1580.69		1580.69
RADAR SENS		ч			1.00	1231.65	00.00	1231.65


Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

Mobile: +6590991236

Vehicle & Document Information

WIP No 44027

Reg No/Reg Date SLA3132K / 03/02/2015

Date In/Mileage Chassis No

1107436 WDD2050402R034410

Engine No

27491030263073 MB/MB C 180 SEDAN (W205) "AVANTGARDE / A

Make/Model Colour/Trim

027 755 Tenorite Gr/ 041 101 ARTICO Blac

Account No	Terms	Date/Time Printed	CSE	Operator				
CS100003	Cash	29/07/2020/ 10:28	VS	356 / Vincent	Seah			
		Description of Goo	ds / Service	S	Qty	Unit Price	Disc%	Amount
		R GRILLE CVA	IN II	001	1.00	130.49	00.00	130.49
M LIGENSE	PLATE MOLI	DING CAST	ANI O	OFFICIA	1.00	130.49		130.49
4 PRONT BU	MPER CHRON	ME MOULDING THE	dia a		1.00	186.41	00.00	cra 186.41×
RH/LH DI	STANCE SEI	NSOR ? KSUL			2.00	178.75	00.00	357.50 >
		NSOR NW/			4.00	178.75	00.00	715.00-
	ING ASSA	700	. /		6.00	6.35	00.00	38.10×
	ASIC MOUN		h'		1.00	144.28	00.00	144.28
TOP BAST	L MUUNIIN	G FOR BUMPER 7 11/			[1.00]	89.03	00.00	89.03 136.37
PELECIKIC	AL WIKING	HARNESS CUIT		0	1.00	136.37	00.00	101.50
	SENSOR ?			0 10	1,00	191.59	00.00	191.59 164.30
IMPACI A	NTING DAI	18vc		01111	1.00	164.30 12.63	00.00	12.63
LEFT MOU	NITING KAI	11 7 180	>	AIMINIO.	1.00	12.03	00.00	12.94
RIGHT MO	C MOUNTING	IL 7.48N G FOR BUMPER 7.CM		11111111111111	1.00	83.81	00.00	83.81
		G FOR BUMPER ? XSM	~~11	11110.	1.00	83.25	00.00	83.25
RIVETAL		G TON BOTTER	~ /1	1 Dr	4.00	4.59	00.00	18.36
	AMP COVER	MUS	1	7	1.00	85.07	00.00	85.07
RHF FOGL	AMP COVER	# SXANE	))		1.00	85.07	00.00	85.07×
TOP LEFT	FOGL AMP	ORNAMENTAL MOLDING	ue		1.00	71.47	00.00	71.47 -
TOP RIGH	T FOGLAMP	ORNAMENTAL MOLDING	7.Xsvc		1.00	71.47	00.00	71.47×
A BOTTOM I	FFT FOGLA	MP ORNAMENTAL MOLDIN	GMIS -		1.00	59.56	00.00	59.56
BOTTOM R	IGHT FOGL	AMP ORNAMENTAL MOLDI	NG 7 XSU		1.00	59.56	00.00	59.56×
1 HOOD 6+ .					1.00	2114.35	00.00	2114.35
	SIGN ME.				1.00	77.91	00.00	77.91
A LUE COOT	NC CLEMEN	T . X/ C			1.00	33.17	00.00	33.17 X
A RHF SPRI	NG ELEMEN	I. Muc			1.00		00.00	33.17⋉
4 RETAININ	G HOOK	1-30-0			1.00	70.81		70.81×
M BONNET C	ATCH !	, ac			2.00		00.00	68.68×
I THE HING	F (X)~				1.00	190.53	00.00	190.53
A RHF HING	E . Alm				1.00	190.53	00.00	190.53
1 LH/RH BO	NNET ACTU	ATOR ACI			2.00		00.00	380.30
4 HOOD CAB	LE 3 XJU	~			1.00	62.26		62.26
M AIR DUCT	?un/				1.00	129.77	00.00	129.77

Confirmed & accepted by

or No


esa

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg





Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

Mobile: +6590991236

Vehicle & Document Information

44027 WIP No

/ 03/02/2015 SLA3132K Reg No/Reg Date

Date In/Mileage

1107436 WDD2050402R034410 Chassis No

Engine No

27491030263073

Make/Model Colour/Trim

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A

027 755 Tenorite Gr/ 041 101 ARTICO Blac

Accoun	nt No	Terms	Date/Time Printed	CSE		Operator				
CS1000	003	Cash	29/07/2020/ 10:28	VS		356 / Vincent Seah		AND DATE: 100 SAND		
			Description of Good	ls / Servi	ces		Qty	Unit Price	Disc%	Amount
M DAI	DIATOR	DDOTECTI	VE GRILLE				1.00	136.40	00.00	136.40
M RAI	AD CAD	RIER BEAM	-STIVER - D			EEICIAI	1.00	215.44	00.00	215.44
1.00	O DECT	OTHER STATE ALT	AL MOUDING		VI	INCIPLE	= 1.00	68.20	00.00	84.28
M RO	TTOM I	FFT ORNAM	ENTAL MOLDING ?CM				1.00	84.28	00.00	68.20
м то	P RIGH	T ORNAMEN	ITAL MOLDING ?CA				1.00	68.20	00.00	84.28
M B0	TTOM R	IGHT ORNA	AMENTAL MOLDING	./			1.00	84.28	00.00	77.4
M ME	RCEDES	STAR CAR	RRIER ? New/				100	77.44	00.00	136.49
M ME	RCEDES	STAR MI					[1.00]	136.49	00.00	250.8
M WA	ASHER V	IPER COV	VERING PANEL				1.00	250.81	00.00	148.5
M FI	HITD CO	NTAINER	Ksuc			111	1,00	148.53	00.00	3280.4
M LI	HF HEAL	DLAMP UNI	T con /			~ [1] 1D	1.00	3280.44	00.00	3280.4
M RI	HF HEAL	DLAMP UNI	T 7500 7 KSU		-	0/11/11/1	1.00	3280.44	00.00	608.1
300		OL TOUT CO	NITOOL LINITY .	-	211	INVIII	1.00	608.18	00.00	608.1
M R	HE HEA	DLIGHT CO	NTROL UNIT	5	1	111/12	1.00	608.18	00.00	279.0
M S	RS ACC	ELERATION	SENSOR ? FEW	2 1	1 1	1177	2.00	139.51	00.00	438.3
M C	ROSS M	EMBER 54.	/	-	11		1.00	438.32	00.00	48.0
	HF STR			)	1		1.00	48.09	00.00	48.0
	RHF STR			1)			1.00	48.09 75.93	00.00	75.9
M L	HF BRA	CKET ~	- 11.3				1.00	73.70	00.00	73.7
M R	RHF BR	ACKET ~	7.0				1.00	224.99	00.00	224.9
			CONSOLE -				1.00	743.26	00.00	743.2
			NEL-SILVER 54				1.00	209.63	00.00	209.6
		M ABSORBE					1.00	209.63	00.00	209.6
M R	RIGHT A	RM ABSORE	7 104				2.00	12.94	00.00	25.8
M T	THREADE	D HOLE PL	ATE				1.00	83.69	00.00	83.69
		D STRIKER					1.00	99.58	00.00	99.58
M L	HF/RHF	ABSORBER	in				1.00	68.61	00.00	68.6
M L	LHF HOC	D LOCK ?	Live				1.00	68.61	00.00	68.63
1000	till Hot	D LOCK	7 xsv				1.00	42.38	00.00	42.38
		TCH SWITC					1.00	42.38	00.00	42.38
MF	HOUD LA	TCH SWITC	H -KH				1.00	195.74	00.00	195.74
M C	LOVER	ENGINE (	COMP. BM CARRON BRACKET 7 Kgm				1.00		00.00	34.8

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383

Cycle & Carriage Industries Pte Limited Authorised Dealer Company No. 196400367W GST Reg No. MR-8500111-X

Mr Chua

15 Tampines Central 7 #03-11 The Tampines Trillant Singapore 528771

Mobile: +6590991236

M OIL COOLER ? KSVL

Vehicle & Document Information

WIP No 44027

SLA3132K / 03/02/2015 Reg No/Reg Date

1107436 Date In/Mileage

Chassis No WDD2050402R034410

27491030263073 Engine No

MB/MB C 180 SEDAN (W205) "AVANTGARDE / A Make/Model 027 755 Tenorite Gr/ 041 101 ARTICO Blac Colour/Trim

Account No	Terms	Date/Time Printed	CSE	Operator	- 10 m			
CS100003	Cash	29/07/2020/ 10:2	8 VS	356 / Vincent Seah				
COTCOCC		Description of G	oods / Service	ces	Qty	Unit Price	Disc%	Amount
M RH ENGINE M REFIGERAL M BOTTOM AT M CENTRAL M COLD AIR	T CONDEN R DUCT S AIR DUCT INDUCTIO	SER SER SEGMENT	AN	OFFICIAL	1.00 1.00 1.00 1.00 1.00	27.86 1472.72 170.11 67.79 43.82 646.28	00.00 00.00 00.00 00.00 00.00 00.00	27.86 1472.72 170.11 × 67.79 × 43.82 × 646.28 ×

KK Auto Consultants hence notify the Repairer of the following:

· To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

. Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Hp 90010068 8 days 29/07/2020@1600 Excess: 750

571.61 00.00

Confirmed & accepted by

Nett

36,806.33

7% GST on 36806.33

2576.44

571.61

**Total Payable** 

39,382.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50's of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

> Pandan Loop Service Center 188 Pandan Loop Singapore 128378 Tel: 6777 8388 Fax: 6779 5383 www.mercedes-benz.com.sg