

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Low

Date: 04 Aug 2020

Preliminary Advice

Insured Vehicle No	: GBD9341L	Accident Date	: 29/07/2020
TP Vehicle No	: SGN5973C	Assignment Date	: 30/07/2020
Make	: TOYOTA COROLLA	Est. Duration of Repair	: 10 Days
Date of Inspection	: 29/07/2020		
Inspection At	: Tan Lim Motor Pte Ltd (Defu) 1 Defu Lane 6 Singapore 539365		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the n/s rear & o/s rear portion and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross)	:S\$	15,296.03
Revised Amount	:S\$	9,528.73
Check Items (Estimated)	:S\$	994.35
Total	:S\$	10,523.08
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : TP : WP