

ASS. REC. BY:

REF:

FCZ/20007824/KD

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

8215K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLU 5007X

Yr Regn:

12 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mw E220C

c.c

1950

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

52524

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDD-213042A-177693

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

23/7/20

D.O.I.

11/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

18/8

8960L Car frame

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + R.S. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

LIM YEW BOO SPRAY PAINT CO.

BLK 10, SIN MING INDUSTRIAL ESTATE, SECTOR C, #01-10 S'575645
NO. 176, SIN MING DRIVE, #03-05, SIN MING AUTOCARE, S'PORE 575721
Tel No. : 64534177 Fax No. : 64593724
E-Mail : limyewboo@singnet.com.sg
Website : www.limyewboo.com.sg
Buss. Reg. No. : 200514/00L

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD #16-01
CITYHOUSE SINGAPORE 068877

Attention : Motor Claim Department
Contact : 65073848 Fax No. : 65073849

Estimate : TP20/026

Date : 01/08/2020
Vehicle Num. : SLU 5007X
Make/Model : MERCEDES E220d SE AUTO-2017
Chassis/Eng# : WDD2132042A177693/65492080075673
Accident Date : 23/07/2020
Claim No. :
Reference : LYB/SLU5007X/MS/tp/sl
Policy No. :

Not with work
Resurvey After Paint
3 days

S/N	Quantity	Particular	Unit Price	Amount S\$
-----	----------	------------	------------	------------

LABOUR :
TO REPAIR & SPRAY RIM

120.00 X

TO REPAIR, PANEL BEAT ON RIGHT REAR FENDER & AFFECTED
DOOR IN ORDER TO FACILITATE RESPRAY JOB

400.00 3000

TO PUTTY, PRIMER & SPRAY PAINT ON RIGHT FRT DOOR, REAR
DOOR, REAR FENDER & REAR BUMPER USING 2K PAINT

1,100.00 6600

Labour Total S\$:

1,620.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company


Acknowledged by Repairer

Signature:

Date: E. & O.E.

Total S\$: 1,620.00

=====



for LIM YEW BOO SPRAY PAINT CO.