

...CLAIM SUBFOLDER...(Pending for Survey Report)

Revoked / No settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	28 Jul 2020 Edit Reg		29 Jul 2020 00:00 Edit Adj Rpt	S\$9,800.00 Edit Estimates	S\$9,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LIM LAM SEN LARRY , ID: S1765453E									
Main Claimant: TW PREMIUM AUTOMOBILE PTE LTD									
Vehicle Reg. No.: SLR4523U		Date of Loss: 24/07/2020 00:00 - :59 [35 Months and 8 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / 5088436627SG		Policy/Cover Note No.: 2100098322 (Comprehensive)							
Vehicle Reg. No. (Insured): SFJ7887M		Policy No. (Claimant): Excess:							
Repairer: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay, 417883 Kaki Bukit - Tel: 68869097									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/08/2020]									
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLR4523U (5088436627SG)
[SFJ7887M]**

TP

TW PREMIUM AUTOMOBILE PTE LTD

Jul 24 2020 12:00AM

[LIM LAM SEN LARRY]

Focus Auto Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)
[Upload Video](#)
[Upload Audio](#)

View
[View in Browser](#)

Photos/Images			3 per page	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/07/20 16:23	Chassis Number	 Load JPG	
2	30/07/20 16:23	Odometer Reading	 Load JPG	
3	30/07/20 16:27	General View	 Load JPG	
4	30/07/20 16:27	General View	 Load JPG	
5	30/07/20 16:27	General View	 Load JPG	
6	30/07/20 16:27	General View	 Load JPG	
7	30/07/20 16:27	General View	 Load JPG	
8	30/07/20 16:27	General View	 Load JPG	
9	30/07/20 16:27	General View	 Load JPG	
10	30/07/20 16:27	General View	 Load JPG	
11	30/07/20 16:27	General View	 Load JPG	
12	30/07/20 16:27	General View	 Load JPG	
13	30/07/20 16:27	General View	 Load JPG	
14	30/07/20 16:27	General View	 Load JPG	
15	30/07/20 16:27	General View	 Load JPG	
16	30/07/20 16:27	General View	 Load JPG	
17	30/07/20 16:27	General View	 Load JPG	
18	30/07/20 16:27	General View	 Load JPG	
19	30/07/20 16:27	General View	 Load JPG	
20	30/07/20 16:27	General View	 Load JPG	
21	30/07/20 16:27	General View	 Load JPG	
22	30/07/20 16:27	General View	 Load JPG	
23	30/07/20 16:27	General View	 Load JPG	
24	30/07/20 16:27	General View	 Load JPG	
25	30/07/20 16:27	General View	 Load JPG	
26	30/07/20 16:27	General View	 Load JPG	
27	30/07/20 16:27	General View	 Load JPG	
28	30/07/20 16:27	General View	 Load JPG	
29	30/07/20 16:27	General View	 Load JPG	
30	30/07/20 16:27	General View	 Load JPG	
31	30/07/20 16:27	General View	 Load JPG	
32	30/07/20 16:27	General View	 Load JPG	
33	30/07/20 16:27	General View	 Load JPG	
34	30/07/20 16:27	General View	 Load JPG	
35	30/07/20 16:27	General View	 Load JPG	
36	30/07/20 16:27	General View	 Load JPG	
37	30/07/20 16:27	General View	 Load JPG	
38	30/07/20 16:27	General View	 Load JPG	
39	30/07/20 16:27	General View	 Load JPG	
40	30/07/20 16:27	General View	 Load JPG	

Photos/Images			3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
41	30/07/20 16:27	General View	 Load JPG	☒
42	30/07/20 16:27	General View	 Load JPG	☒
43	30/07/20 16:27	General View	 Load JPG	☒
44	30/07/20 16:27	General View	 Load JPG	☒
45	30/07/20 16:27	General View	 Load JPG	☒
46	30/07/20 16:27	General View	 Load JPG	☒
47	30/07/20 16:27	General View	 Load JPG	☒
48	30/07/20 16:27	General View	 Load JPG	☒
49	30/07/20 16:27	General View	 Load JPG	☒
50	30/07/20 16:27	General View	 Load JPG	☒
51	30/07/20 16:27	General View	 Load JPG	☒
52	30/07/20 16:27	General View	 Load JPG	☒
53	30/07/20 16:27	General View	 Load JPG	☒
54	30/07/20 16:27	General View	 Load JPG	☒
55	30/07/20 16:28	General View	 Load JPG	☒
56	30/07/20 16:28	General View	 Load JPG	☒
57	30/07/20 16:28	General View	 Load JPG	☒
58	30/07/20 16:28	General View	 Load JPG	☒
59	30/07/20 16:28	General View	 Load JPG	☒
60	30/07/20 16:28	General View	 Load JPG	☒
61	30/07/20 16:28	General View	 Load JPG	☒
62	30/07/20 16:28	General View	 Load JPG	☒
63	30/07/20 16:28	General View	 Load JPG	☒
64	30/07/20 16:28	General View	 Load JPG	☒
65	30/07/20 16:28	General View	 Load JPG	☒
66	30/07/20 16:28	General View	 Load JPG	☒
67	30/07/20 16:28	General View	 Load JPG	☒
68	30/07/20 16:28	General View	 Load JPG	☒
69	30/07/20 16:28	General View	 Load JPG	☒
70	30/07/20 16:28	General View	 Load JPG	☒
71	30/07/20 16:28	General View	 Load JPG	☒
72	30/07/20 16:28	General View	 Load JPG	☒
73	30/07/20 16:28	General View	 Load JPG	☒
74	30/07/20 16:28	General View	 Load JPG	☒
75	30/07/20 16:28	General View	 Load JPG	☒
76	30/07/20 16:28	General View	 Load JPG	☒
77	30/07/20 16:28	General View	 Load JPG	☒
78	30/07/20 16:28	General View	 Load JPG	☒
79	30/07/20 16:28	General View	 Load JPG	☒
80	30/07/20 16:28	General View	 Load JPG	☒
81	30/07/20 16:28	General View	 Load JPG	☒
82	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
83	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
84	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
85	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
86	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
87	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
88	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
89	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
90	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
91	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
92	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
93	03/08/20 17:40	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page ▼		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
94	03/08/20 17:40	Reinspection Photo		Load JPG	☒
95	03/08/20 17:40	Reinspection Photo		Load JPG	☒
96	03/08/20 17:40	Reinspection Photo		Load JPG	☒
97	03/08/20 17:40	Reinspection Photo		Load JPG	☒
98	03/08/20 17:40	Reinspection Photo		Load JPG	☒
99	03/08/20 17:40	Reinspection Photo		Load JPG	☒
100	03/08/20 17:40	Reinspection Photo		Load JPG	☒
101	03/08/20 17:40	Reinspection Photo		Load JPG	☒
102	03/08/20 17:40	Reinspection Photo		Load JPG	☒
103	03/08/20 17:40	Reinspection Photo		Load JPG	☒
104	03/08/20 17:40	Reinspection Photo		Load JPG	☒
105	03/08/20 17:40	Reinspection Photo		Load JPG	☒
106	03/08/20 17:40	Reinspection Photo		Load JPG	☒
107	03/08/20 17:40	Reinspection Photo		Load JPG	☒
108	03/08/20 17:40	Reinspection Photo		Load JPG	☒
109	03/08/20 17:40	Reinspection Photo		Load JPG	☒
110	03/08/20 17:40	Reinspection Photo		Load JPG	☒
111	03/08/20 17:40	Reinspection Photo		Load JPG	☒
112	03/08/20 17:40	Reinspection Photo		Load JPG	☒
113	03/08/20 17:40	Reinspection Photo		Load JPG	☒
114	03/08/20 17:40	Reinspection Photo		Load JPG	☒
115	03/08/20 17:40	Reinspection Photo		Load JPG	☒
116	03/08/20 17:40	Reinspection Photo		Load JPG	☒
117	03/08/20 17:40	Reinspection Photo		Load JPG	☒
118	03/08/20 17:40	Reinspection Photo		Load JPG	☒
119	03/08/20 17:40	Reinspection Photo		Load JPG	☒
120	03/08/20 17:40	Reinspection Photo		Load JPG	☒
121	03/08/20 17:40	Reinspection Photo		Load JPG	☒
122	03/08/20 17:40	Reinspection Photo		Load JPG	☒
123	03/08/20 17:40	Reinspection Photo		Load JPG	☒
124	03/08/20 17:40	Reinspection Photo		Load JPG	☒
125	03/08/20 17:40	Reinspection Photo		Load JPG	☒
126	03/08/20 17:40	Reinspection Photo		Load JPG	☒
127	03/08/20 17:40	Reinspection Photo		Load JPG	☒
128	03/08/20 17:40	Reinspection Photo		Load JPG	☒
129	03/08/20 17:40	Reinspection Photo		Load JPG	☒
130	03/08/20 17:40	Reinspection Photo		Load JPG	☒
131	03/08/20 17:40	Reinspection Photo		Load JPG	☒
132	03/08/20 17:40	Reinspection Photo		Load JPG	☒
133	03/08/20 17:40	Reinspection Photo		Load JPG	☒
134	03/08/20 17:40	Reinspection Photo		Load JPG	☒
135	03/08/20 17:40	Reinspection Photo		Load JPG	☒
136	03/08/20 17:40	Reinspection Photo		Load JPG	☒
137	03/08/20 17:40	Reinspection Photo		Load JPG	☒
138	03/08/20 17:40	Reinspection Photo		Load JPG	☒
139	03/08/20 17:40	Reinspection Photo		Load JPG	☒
140	03/08/20 17:40	Reinspection Photo		Load JPG	☒
141	03/08/20 17:40	Reinspection Photo		Load JPG	☒
142	03/08/20 17:40	Reinspection Photo		Load JPG	☒
143	03/08/20 17:40	Reinspection Photo		Load JPG	☒
144	03/08/20 17:40	Reinspection Photo		Load JPG	☒
145	03/08/20 17:40	Reinspection Photo		Load JPG	☒
146	03/08/20 17:40	Reinspection Photo		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
147	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
148	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
149	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
150	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
151	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
152	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
153	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
154	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
155	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
156	03/08/20 17:40	Reinspection Photo	 Load JPG	☒
157	12/08/20 18:12	After Repair Photo	 Load JPG	☒
158	12/08/20 18:12	After Repair Photo	 Load JPG	☒
159	12/08/20 18:12	After Repair Photo	 Load JPG	☒
160	12/08/20 18:12	After Repair Photo	 Load JPG	☒
161	12/08/20 18:12	After Repair Photo	 Load JPG	☒
162	12/08/20 18:12	After Repair Photo	 Load JPG	☒
163	12/08/20 18:12	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/07/20 17:36	ACKNOWLEDGEMENT EMAIL TO AIG DD29072020	 Load PDF	
2	29/07/20 17:36	EMAIL FROM AIG DD29072020	 Load PDF	
3	30/07/20 16:36	TP GIA REPORT	 Load PDF	
4	08/09/20 14:58	EMAIL FROM AIG TO REPUDIATED LIABILITY	 Load PDF	
5	08/09/20 14:58	EMAIL WSP TO REPUDIATED LIABILITY	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	30/07/20 17:16	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007837/UES3S2**Date:** 16/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100098322
Claimant Vehicle No :	SLR4523U	Insured Vehicle No :	SFJ7887M
Date of Loss:	24/07/2020	Nature of Claim:	TP
		Claim No:	5088436627SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR4523U	Engine No:	P520454474
Make & Model:	MAZDA 3, 1.5 SEDAN AT EU6 (A)	Chassis No:	JM6BN22A8H0162240
Reg. Date:	16/08/2017 (Man. Year: 2017)	Odometer:	113326 km
Colour:	Brown		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,678.56	8,969.60	2,708.96	23.20
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,990.00	3,320.00	670.00	16.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,668.56	12,289.60	3,378.96	21.57
Approved Total (Overridden) (S\$)		9,800.00		
(S\$)	15,668.56	9,800.00	5,868.56	37.45
+ GST 7.00/7.00% (S\$)	1,096.80	686.00	410.80	37.45
Nett Amount (S\$)	16,765.36	10,486.00	6,279.36	37.45

INSPECTION

Date of Assignment:	29/07/2020	
Date Inspected:	30/07/2020	Inspected At: Focus Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #02-48/50 Autobay Singapore 417883
Estimated Period of Repair:	12.0 days	

Adjuster: MARCUS CHUA**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER REFLECTOR - LH	Not Necessary	56.00 FL	*- FL
2	2		*REAR BUMPER TOWING COVER	Missing	35.60 FL	*35.60 FL
3	1		*REAR BUMPER CENTRE BRACKET	No such part	35.60 FL	*- FL
4	4		*REAR BUMPER LOWER CLIPS	Necessary	22.00 FL	*22.00 FL
5	1		*SET REAR EXHAUST SILENCER	Repair	654.00 FL	*- FL
6	2		*REAR EXHAUST RUBBER	Serviceable	96.00 FL	*- FL
7	1		*REAR EXHAUST TOP HEATER COVER PLATE	Bent	112.00 FL	*112.00 FL
8	1		*FRONT SUPPORT PANEL	Repair	569.70 FL	*- FL
9	1		*FRONT TOP PANEL	Not Necessary	110.20 FL	*- FL
10	1		*FRONT TOP GARNISH	Dented / Deformed	368.40 FL	*368.40 FL
11	6		*FRONT TOP GARNISH CLIPS	Not Necessary	33.00 FL	*- FL
12	1		*FRONT TOP GARNISH INNER SUPPORT	Not Necessary	298.40 FL	*- FL
13	2		*FRONT HEADLAMP	Cracked	1,547.40 FL	*1,547.40 FL
14	1		*FRONT GRILLE	Cracked	450.40 FL	*450.40 FL
15	2		*FRONT GRILLE INNER BRACKET	Cracked	120.80 FL	*76.00 FL
16	2		*FRONT GRILLE MOULDING	Cracked	353.40 FL	*353.40 FL
17	1		*FRONT GRILLE LOGO	Scratched	58.00 FL	*58.00 FL
18	1		*FRONT BUMPER	Dented / Deformed	925.20 FL	*925.20 FL
19	1		*FRONT BUMPER REINFORCEMENT	Bent	565.10 FL	*444.50 FL
20	2		*FRONT BUMPER REINFORCEMENT GARNISH	Torn	84.40 FL	*84.40 FL
21	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	79.40 FL	*- FL
22	1		*FRONT BUMPER TOWING COVER - RH	Not Necessary	30.40 FL	*- FL
23	1		*FRONT BUMPER LOWER COVER - RH	Missing	18.00 FL	*18.00 FL
24	1		*FRONT NUMBER PLATE SUPPORT	Torn	52.20 FL	*52.20 FL
25	1		*REAR BOOT	Badly Dented	1,004.00 FL	*1,004.00 FL
26	1		*REAR DOOR HINGES	Not Necessary	152.00 FL	*- FL
27	1		*REAR BOOT EMBLEM (MAZDA 3)	Necessary	55.00 FL	*55.00 FL
28	1		*REAR BOOT EMBLEM (SKYACTIV)	Necessary	52.00 FL	*52.00 FL
29	1		*REAR BOOT CENTRE LOGO	Necessary	77.00 FL	*77.00 FL
30	1		*REAR BOOT REFLECTOR LAMP - LH	Cracked	278.00 FL	*278.00 FL
31	1		*REAR BOOT INNER COVER	Not Necessary	264.00 FL	*- FL
32	1		*REAR BOOT INNER COVER CLIPS	Not Necessary	5.50 FL	*- FL
33	1		*REAR BOOT LOCK	Bent	185.00 FL	*185.00 FL
34	1		*REAR BOOT LOCK CATCH	Not Necessary	48.00 FL	*- FL
35	1		*REAR BOOT RUBBER	Twisted	135.00 FL	*135.00 FL
36	1		*REAR FENDER - LH	Badly Dented / Buckled	1,233.00 FL	*1,129.30 FL
37	1		*REAR FENDER INNER SIDE GARNISH	Not Necessary	268.00 FL	*- FL
38	12		*REAR FENDER INNER SIDE GARNISH CLIPS	Not Necessary	66.00 FL	*- FL
39	1		*REAR TOOLS SPONGE TRAY	Torn	264.10 FL	*264.10 FL
40	1		*REAR WINDSCREEN MOULDING	Necessary	77.00 FL	*77.00 FL
41	1		*REAR TAIL LAMP - LH	Cracked	534.00 FL	*534.00 FL
42	3		*REAR TAIL LAMP CLIPS - LH	Not Necessary	25.50 FL	*- FL
43	1		*REAR TAIL LAMP PANEL - LH	Bent	126.00 FL	*126.00 FL
44	1		*REAR END PANEL	Badly Dented	530.00 FL	*530.00 FL
45	1		*REAR END PANEL TOP GARNISH	Deformed / Twisted	120.00 FL	*120.00 FL
46	4		*REAR END PANEL TOP GARNISH CLIPS	Not Necessary	22.00 FL	*- FL
47	1		*REAR BUMPER	Distorted	1,127.00 FL	*1,074.80 FL
48	1		*REAR BUMPER REINFORCEMENT	Bent	563.00 FL	*537.30 FL
49	1		*REAR BUMPER SIDE RETAINER	N/s Bent	76.00 FL	*38.00 FL
50	1		*REAR BUMPER DUST COVER - LH	Torn	98.00 FL	*98.00 FL
51	1		*REAR WINDSCREEN GUM	Necessary	80.00 FS	*40.00 FS
52	1		*SET REAR BUMPER SENSOR	Damaged	300.00 FS	*200.00 FS
53	1		*FRONT NUMBER PLATE	Bent	50.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 14,490.70 11,142.00

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
- List Item Discount on L Items 20.00/20.00% (S\$)					2,812.14	2,172.40
Total Parts (S\$)					11,678.56	8,969.60
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING.	New	50.00	0.00
2	CHECK WIRING.	New	80.00	30.00
3	RUST PROOFING.	New	80.00	80.00
4	TO REMOVE & REFIT REAR WINDSCREEN.	New	160.00	120.00
5	TO REMOVE & REPLACE BUMPER SENSOR.	New	80.00	50.00
6	TO REMOVE & REPLACE EXHAUST.	New	80.00	60.00
7	TO REMOVE & REFIT REAR SEAT AND UPHOLSTERY.	New	160.00	80.00
8	TO SPRAY PAINTING.	New	1,100.00	1,100.00
9	PANEL BEATING.	New	2,200.00	1,800.00
Gross Labour Cost (S\$)			3,990.00	3,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >