

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CC4/FC120007841/UKS3

ASSIGNMENT

From:

Date:

Veh No:

SMG4227X

Yr Regn:

12/18

Estimated Cost:

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or

To Inspect Vehicle No:

SMG4227X

Make:

KIA carens

c.c

1685

at Workshop m/s

7an Lim

Colour

Red

A/C:

Insured / Std / NI / NA

of

Sp. Reading

134946

T/Radio:

Insured / Std / NI / NA

Insured:

SH 9180L

Eng/No:

C/No:

KNAHU8/5VJ7211460

Policy No.

Gen. Cond: Good / Fair / Poor / Burnt

Claims No.

Steering: Good / Jammed / Leaked / Burnt or

Sum Insured:

Excess:

Brake: Good / Jammed / Leaked / Burnt or

(Client's Record)


Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$80k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

131

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

C 24HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Achilles

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

28/7/20

D.O.I.

13/8/20

Survey held at

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

N/S Fr

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

have video LTA 541942

18/8/20 confirmed final by \$4105.00 with willan.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS S

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐


: Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



GST Regn. No. : M2-8922054-2

Date : 27 July 2020

Chassis No : KNAHU815VJ7211460

S/No	Quantity	Description	Amount
		<u>LIST ITEMS</u>	
01	1 pc	front bumper DIS	\$ 695.00
02	1 pc	front bumper side retainer n/s Bery	\$ 23.00
03	1 pc	front bumper centre grille 11	\$ 428.00
04	1 pc	front bumper lower grille R	\$ 159.00
05	1 pc	front bumper parking sensor - inner NF	\$ 162.00
06	1 pc	front bumper parking sensor holder NF	\$ 23.00
07	1 pc	front bumper top rubber seal 11	\$ 28.00
08	1 pc	radiator grille 11	\$ 428.00
09	1 pc	front bumper reinforcement 11	\$ 389.00
10	1 pc	front bumper foam 11	\$ 68.00
11	2 ps	aircon condenser air guide @ \$24.00 11	\$ 48.00
12	1 pc	n/s headlamp CMC	\$ 1,558.00
13	1 pc	n/s headlamp bracket CMC	\$ 23.00
14	1 pc	front support panel top garnish 11	\$ 58.00
15	1 pc	n/s front fender R	\$ 425.00
16	1 pc	n/s front fender inner cowling TWIN	\$ 75.00
17	6 ps	n/s front fender inner cowling clips @ \$4.50 CMC	\$ 27.00
18	1 pc	front bumper fog lamp n/s CMC	\$ 206.00
19	1 pc	front bumper fog lamp cover n/s CMC	\$ 115.00
		Less 10 %	\$ 4,938.00
			\$ 493.80
			\$ 4,444.20
		<u>SPECIAL NETT ITEMS</u>	
20	1 pc	n/s front wheel rim R	\$ 750.00
21	1 pc	n/s front wheel tyre 11	\$ 250.00
			\$ 1,000.00
		<u>LABOUR & MISC. CHARGES</u>	
01		To transfer of tyre, rim and on wheel balancing.	\$ 50.00
02		To check steering geometry and computer wheel alignment.	\$ 80.00
03		To rust-proofing of the affected areas. 11	\$ 150.00
04		To check electrical lighting concerned.	\$ 80.00
05		To reinstall of front bumper parking sensor. 11	\$ 80.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 550.00



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

1 Defu Lane 6 Singapore 539365
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

MS FCIL Insured's Veh No : SH9180L

Date of Accident : 25 July 2020

Messrs BIS Motoring Pte Ltd

Date : 27 July 2020

Estimate To Repair SMG4227X - KIA CARENS 1.7 DCT DIESEL 5DR FWD
Chassis No : KNAHU815VJ7211460

S/No	Quantity	Description	Amount
07		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 750.00
			\$ 1,740.00
		Total	\$ 7,184.20
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:			

460

1090

2-3350
1072
3015
1090
4105



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

MS FCIL Insured's Veh No : SH9180L

Date of Accident : 25 July 2020

1 Defu Lane 6 Singapore 539365

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs BIS Motoring Pte Ltd

Date : 18 August 2020

Supplementary To Repair SMG4227X - KIA CARENS 1.7 DCT DIESEL 5DR FWD

Chassis No : KNAHU815VJ7211460

S/No	Quantity	Description	Amount
01	1 pc	<u>LIST ITEMS</u> front support panel <i>CNE</i>	\$ 628.00
			\$ 628.00
		Less 10 %	\$ 62.80
			\$ 565.20
		Total	\$ 565.20