



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGU 4436G

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|------------------------------------|--|----------------------|---------------------------|-------------------|
| <u>REPLACEMENT OF PARTS</u> | | | | |
| 1 | FRT BUMPER (CONSISTENT) | BUCKLED / DENTED | 792.06 | 601.90 |
| 2 | FRT BUMPER RETAINER @\$80.72 (CONSISTENT) | SERVICEABLE | 161.44 | - |
| 1 | FRT BUMPER REINFORCEMENT (CONSISTENT) | TO REPAIR SEE LABOUR | 386.76 | - |
| 1 | FRT FOG LAMP R/H (CONSISTENT) | CRACKED | 321.66 | 236.70 |
| 1 | FRT FOG LAMP COVER -R/H (CONSISTENT) | NO SUCH PARTS | 64.99 | - |
| 1 | FRT GRILLE (CONSISTENT) | DENTED | 260.85 | 260.85 |
| 3 | FRT GRILLE CLIPS @\$12.50 (CONSISTENT) | NECESSARY | 37.50 | 37.50 |
| 1 | FRT BONNET (CONSISTENT) | TO REPAIR SEE LABOUR | 510.70 | - |
| 1 | FRT BONNET MOULDING (CONSISTENT) | DENTED | 243.86 | 243.86 |
| 1 | FRT BONNET EMBLEM (CONSISTENT) | NECESSARY | 88.72 | 88.72 |
| 1 | FRT HEADLAMP -RH (CONSISTENT) | MTG CRACKED | 1,095.61 | 1,095.61 |
| | LESS 25% DISCOUNT | | -991.04 | -641.29 |
| | | | 2,973.11 | 1,923.85 |
| 12 | FRT BUMPER CLIPS @\$12.50 (SN) (CONSISTENT) | NECESSARY | 150.00 | 50.00 |
| 12 | FRT BUMPER LOWER LIP CLIPS @\$12.50 (SN) (CONSISTENT) | NECESSARY | 150.00 | 60.00 |
| | LESS 25% DISCOUNT | | -75.00 | - |
| | | | 225.00 | 110.00 |
| <u>SPECIAL NETT ITEMS</u> | | | | |
| 1 | FRT BUMPER LOWER LIP (SN) (CONSISTENT) | TO REPAIR SEE LABOUR | 480.00 | - |
| | | | 480.00 | - |
| <u>LABOUR</u> | | | | |
| | TO PULL ,KNOCK ON ACCIDENT PORTION & CHANGE ABOVE PART.INCLUSIVE OF THE REPAIR OF FRT BUMPER REINFORCEMENT ,FRT BONNET AND FRT BUMPER LOWER LIP. | | 750.00 | 400.00 |
| | TO SPRAY & PAINT ON ACCIDENT PORTION. | | 950.00 | 600.00 |
| | TO CHECK WIRING FUNCTIONS. | | 50.00 | 20.00 |

Report Ref No. CC4/ASM20007842/Kps3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|---|----------------------------------|---------------|---------------------------|-------------------|
| | TO ANTI-RUST FRT AFFECTED AREAS. | NOT NECESSARY | 50.00 | - |
| | | | 1,800.00 | 1,020.00 |
| GRAND TOTAL | | | 5,478.11 | 3,053.85 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | | 2,450.00 |

Report Ref No. CC4/ASM20007842/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.