

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	30 Jul 2020 Edit Reg		30 Jul 2020 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
CLAIM SUBFOLDER DETAILS [Created by adjuster]				
Insured: ONG DIANA , ID: S7625845G				
Main Claimant: LIM TRADERS PTE LTD				
Vehicle Reg. No.: YP4402S		Date of Loss:	24/07/2020 16:00 - :59 [45 Months and 17 Days From LTA Reg Date (Man Yr)]	
Claim Type: TP / 1740439545SG		Policy/Cover Note No.:	2070037755 (Comprehensive)	
Vehicle Reg. No. (Insured): SMF9380H		Policy No. (Claimant):		
		Excess:		
Repairer: Power Fook Vehicle Service (HQ) 7 SOON LEE STREET, #01-19 ISPACE, 627608 Jurong West - Tel: 62506760 / 83034569 / 62506761				
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Yong, Joanne] Joanne-LF.yong@aig.com				
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 12/08/2020]				
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail
There are no mail for this case.				
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 				
Due Date	Priority	Type	Task Group	Subject
				Handler
				Assigned By
				Completed On
				Created On
				Done?
No results.				

Claim Documents

***YP4402S (1740439545SG)**
[SMF9380H]
TP
LIM TRADERS PTE LTD
Jul 24 2020 4:00PM
[ONG DIANA]
Power Fook Vehicle Service

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser		
Photos/Images			3 per page		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	30/07/20 15:39	Chassis Number		Load JPG	
2	30/07/20 15:39	General View		Load JPG	
3	30/07/20 15:39	General View		Load JPG	
4	30/07/20 15:39	General View		Load JPG	
5	30/07/20 15:39	General View		Load JPG	
6	30/07/20 15:39	General View		Load JPG	
7	30/07/20 15:39	General View		Load JPG	
8	30/07/20 15:39	General View		Load JPG	
9	30/07/20 15:39	General View		Load JPG	
10	30/07/20 15:39	General View		Load JPG	
11	30/07/20 15:39	General View		Load JPG	
12	30/07/20 15:39	General View		Load JPG	
13	30/07/20 15:39	General View		Load JPG	
14	30/07/20 15:39	General View		Load JPG	
15	30/07/20 15:39	General View		Load JPG	
16	30/07/20 15:39	General View		Load JPG	
17	30/07/20 15:39	General View		Load JPG	
18	30/07/20 15:39	General View		Load JPG	
19	30/07/20 15:39	General View		Load JPG	
20	30/07/20 15:39	General View		Load JPG	
21	30/07/20 15:39	General View		Load JPG	
22	30/07/20 15:39	General View		Load JPG	
23	30/07/20 15:39	General View		Load JPG	
24	30/07/20 15:39	General View		Load JPG	
25	30/07/20 15:39	General View		Load JPG	
26	30/07/20 15:39	General View		Load JPG	
27	30/07/20 15:39	General View		Load JPG	
28	30/07/20 15:39	General View		Load JPG	
29	30/07/20 15:39	General View		Load JPG	
30	30/07/20 15:39	General View		Load JPG	
31	30/07/20 15:39	General View		Load JPG	
32	30/07/20 15:39	General View		Load JPG	
33	30/07/20 15:39	General View		Load JPG	
34	30/07/20 15:39	General View		Load JPG	
35	30/07/20 15:39	General View		Load JPG	
36	30/07/20 15:39	General View		Load JPG	
37	30/07/20 15:39	General View		Load JPG	
38	30/07/20 15:39	General View		Load JPG	
39	30/07/20 15:39	General View		Load JPG	
40	30/07/20 15:39	General View		Load JPG	

Photos/Images				3 per page ▾	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
41	30/07/20 15:39	General View		Load JPG	☒
42	30/07/20 15:39	General View		Load JPG	☒
43	30/07/20 15:39	General View		Load JPG	☒
44	30/07/20 15:39	General View		Load JPG	☒
45	30/07/20 15:39	General View		Load JPG	☒
46	30/07/20 15:39	General View		Load JPG	☒
47	30/07/20 15:39	General View		Load JPG	☒
48	30/07/20 15:39	General View		Load JPG	☒
49	30/07/20 15:39	General View		Load JPG	☒
50	30/07/20 15:39	General View		Load JPG	☒
51	30/07/20 15:39	General View		Load JPG	☒
52	30/07/20 15:39	General View		Load JPG	☒
53	30/07/20 15:39	General View		Load JPG	☒
54	30/07/20 15:39	General View		Load JPG	☒
55	30/07/20 15:39	General View		Load JPG	☒
56	30/07/20 15:39	General View		Load JPG	☒
57	30/07/20 15:39	General View		Load JPG	☒
58	30/07/20 15:39	General View		Load JPG	☒
59	30/07/20 15:39	General View		Load JPG	☒
60	30/07/20 15:39	General View		Load JPG	☒
61	30/07/20 15:39	General View		Load JPG	☒
62	30/07/20 15:39	General View		Load JPG	☒
63	30/07/20 15:39	General View		Load JPG	☒
64	30/07/20 15:39	General View		Load JPG	☒
65	30/07/20 15:39	General View		Load JPG	☒
66	30/07/20 15:39	General View		Load JPG	☒
67	30/07/20 15:39	General View		Load JPG	☒
68	30/07/20 15:39	General View		Load JPG	☒
69	30/07/20 15:39	General View		Load JPG	☒
70	30/07/20 21:39	General View		Load JPG	☒
71	30/07/20 21:39	General View		Load JPG	☒
72	30/07/20 21:39	General View		Load JPG	☒
73	30/07/20 21:39	General View		Load JPG	☒
74	30/07/20 21:39	General View		Load JPG	☒
75	30/07/20 21:39	General View		Load JPG	☒
76	30/07/20 21:39	General View		Load JPG	☒
77	30/07/20 21:39	General View		Load JPG	☒
78	30/07/20 21:39	General View		Load JPG	☒
79	30/07/20 21:39	General View		Load JPG	☒
80	30/07/20 21:39	General View		Load JPG	☒
81	30/07/20 21:39	General View		Load JPG	☒
82	30/07/20 21:39	General View		Load JPG	☒
83	30/07/20 21:39	General View		Load JPG	☒
84	30/07/20 21:39	General View		Load JPG	☒
85	30/07/20 21:39	General View		Load JPG	☒
86	30/07/20 21:39	General View		Load JPG	☒
87	30/07/20 21:39	General View		Load JPG	☒
88	30/07/20 21:39	General View		Load JPG	☒
89	30/07/20 21:39	General View		Load JPG	☒
90	30/07/20 21:39	General View		Load JPG	☒
91	30/07/20 21:39	General View		Load JPG	☒
92	30/07/20 21:39	General View		Load JPG	☒
93	30/07/20 21:39	General View		Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
94	30/07/20 21:39	General View		Load JPG	☒
95	30/07/20 21:39	General View		Load JPG	☒
96	30/07/20 21:39	General View		Load JPG	☒
97	30/07/20 21:39	General View		Load JPG	☒
98	30/07/20 21:39	General View		Load JPG	☒
99	30/07/20 21:39	General View		Load JPG	☒
100	30/07/20 21:39	General View		Load JPG	☒
101	30/07/20 21:39	General View		Load JPG	☒
102	30/07/20 21:39	General View		Load JPG	☒
103	30/07/20 21:39	General View		Load JPG	☒
104	30/07/20 21:39	General View		Load JPG	☒
105	30/07/20 21:39	General View		Load JPG	☒
106	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
107	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
108	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
109	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
110	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
111	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
112	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
113	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
114	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
115	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
116	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
117	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
118	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
119	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
120	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
121	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
122	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
123	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
124	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
125	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
126	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
127	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
128	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
129	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
130	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
131	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
132	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
133	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
134	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
135	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
136	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
137	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
138	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
139	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
140	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
141	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
142	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
143	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
144	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
145	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
146	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
147	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
148	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
149	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
150	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
151	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
152	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
153	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
154	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
155	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
156	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
157	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
158	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
159	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
160	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
161	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
162	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
163	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
164	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
165	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
166	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
167	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
168	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
169	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
170	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
171	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
172	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
173	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
174	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
175	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
176	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
177	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
178	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
179	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
180	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
181	11/08/20 08:57	Photographs of Damaged Parts		Load JPG	☒
182	28/08/20 09:12	Reinspection Photo		Load JPG	☒
183	28/08/20 09:12	Reinspection Photo		Load JPG	☒
184	28/08/20 09:12	Reinspection Photo		Load JPG	☒
185	28/08/20 09:12	Reinspection Photo		Load JPG	☒
186	28/08/20 09:12	Reinspection Photo		Load JPG	☒
187	28/08/20 09:12	Reinspection Photo		Load JPG	☒
188	28/08/20 09:12	Reinspection Photo		Load JPG	☒
189	28/08/20 09:12	Reinspection Photo		Load JPG	☒
190	28/08/20 09:12	Reinspection Photo		Load JPG	☒
191	28/08/20 09:12	Reinspection Photo		Load JPG	☒
192	28/08/20 09:12	Reinspection Photo		Load JPG	☒
193	28/08/20 09:12	Reinspection Photo		Load JPG	☒
194	28/08/20 09:12	Reinspection Photo		Load JPG	☒
195	28/08/20 09:12	Reinspection Photo		Load JPG	☒
196	28/08/20 09:12	Reinspection Photo		Load JPG	☒
197	28/08/20 09:12	Reinspection Photo		Load JPG	☒
198	28/08/20 09:12	Reinspection Photo		Load JPG	☒
199	28/08/20 09:12	Reinspection Photo		Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
200	28/08/20 09:12	Reinspection Photo	Load JPG	☒
201	28/08/20 09:12	Reinspection Photo	Load JPG	☒
202	28/08/20 09:12	Reinspection Photo	Load JPG	☒
203	28/08/20 09:12	Reinspection Photo	Load JPG	☒
204	28/08/20 09:12	Reinspection Photo	Load JPG	☒
205	28/08/20 09:12	Reinspection Photo	Load JPG	☒
206	28/08/20 09:12	Reinspection Photo	Load JPG	☒
207	28/08/20 09:12	Reinspection Photo	Load JPG	☒
208	28/08/20 09:12	Reinspection Photo	Load JPG	☒
209	28/08/20 09:12	Reinspection Photo	Load JPG	☒
210	28/08/20 09:12	Reinspection Photo	Load JPG	☒
211	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
212	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
213	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
214	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
215	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
216	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
217	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
218	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
219	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
220	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
221	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
222	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
223	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
224	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
225	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
226	02/09/20 16:21	Photographs of Damaged Parts	Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/08/20 10:04	TP GIA & POLICE REPORT	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	03/08/20 16:23	OI GIA REPORT	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS3/AIG20007847/R1QF3S2**Date:** 08/09/2020REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070037755
Claimant Vehicle No :	YP4402S	Insured Vehicle No :	SMF9380H
Date of Loss:	24/07/2020	Nature of Claim:	TP
		Claim No:	1740439545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	YP4402S		
Make & Model:	MITSUBISHI CANTER, 3.0 D FEB21ER4SDEB (CBU) (M)	Engine No:	4P10C34946
Reg. Date:	07/10/2016 (Man. Year: 2016)	Chassis No:	FEB21EA20937
Colour:	White	Odometer:	0 km
Engine Capacity:	2998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/85 R15	Rear Tyre Size:	195/85 R15 (D)
Front Left Side:	Bridgestone 7 mm	Rear Left Side:	Bridgestone 7/7 mm
Front Right Side:	Bridgestone 7 mm	Rear Right Side:	Bridgestone 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	30/07/2020	
Date Inspected:	30/07/2020	Inspected At: Power Fook Vehicle Service (HQ) 7 SOON LEE STREET, #01-19 ISPACE Singapore 627608
Estimated Period of Repair:	20.0 days	

Adjuster: MOHD RASUL**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE	Bent	0.00 F	*- F
2	1		*FRT BUMPER	Bent	0.00 F	*- F
3	1		*FRT BUMPER SIDE COVER	Missing	0.00 F	*- F
4	1		*FRT BUMPER SIDE GARNISH	Cracked	0.00 F	*- F
5	1		*FRT BUMPER BRACKET	Bent	0.00 F	*- F
6	1		*FRT BUMPER REINFORCEMENT	Bent	0.00 F	*- F
7	1		*FRT GRILLE	Broken	0.00 F	*- F
8	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
9	1		*FRT PANEL	Bent	0.00 F	*- F
10	1		*FRT PANEL EMBLEM	Necessary	0.00 F	*- F
11	1		*FRT CORNER PANEL RH	Cracked	0.00 F	*- F
12	1		*FRT SIGNAL LAMP LH	Cracked	0.00 F	*- F
13	1		*FRT SIGNAL LAMP RH	Cracked	0.00 F	*- F
14	1		*FRT LH HEADLAMP ASSY	Cracked	0.00 F	*- F
15	1		*FRT RH HEADLAMP ASSY	Cracked	0.00 F	*- F
16	1		*FRT WINDSCREEN SEALANT	Necessary	0.00 F	*- F
17	1		*ERP BRACKET	Necessary	0.00 F	*- F
18	1		*AIR CON CONDENSER	Bent	0.00 F	*- F
19	1		*AIR CON LIQUID PIPE	Bent	0.00 F	*- F
20	1		*RADIATOR	Bent	0.00 F	*- F
21	1		*RADIATOR COWLING	Cracked	0.00 F	*- F
22	1		*OIL COOLER	Bent	0.00 F	*- F
23	1		*FRT CABIN ASSY	Repair	0.00 F	*- F
24	1		*FRT CABIN MOUNTING	Repair	0.00 F	*- F
25	1		*FRT LH CHASSIS MEMBER	Repair	0.00 F	*- F
26	1		*FRT RH CHASSIS MEMBER	Repair	0.00 F	*- F
27	1		*AIR CON EVAPORATOR ASSY	Cracked	0.00 F	*- F
28	1		*AIR CON BLOWER	Cracked	0.00 F	*- F
29	1		*BRAKE BOOSTER PUMP ASSY	Bent	0.00 F	*- F
30	1		*DASHBOARD ASSY	Cracked	0.00 F	*- F
31	1		*GLOVE BOX COVER	Cracked	0.00 F	*- F
32	1		*GLOVE BOX COMPARTMENT	Cracked	0.00 F	*- F
33	1		*FRT WHEEL ARCH PANEL GARNISH	Cracked	0.00 F	*- F
34	1		*FRT STEP PANEL	Cracked	0.00 F	*- F
35	1		*FRT STEP PANEL TOP GARNISH	Cracked	0.00 F	*- F
36	1		*STEERING BOX	Cracked	0.00 F	*- F
37	1		*FREEZER BOX	Cracked	0.00 F	*- F
38	1		*STEERING COMPLETE	Bird Droppings	0.00 F	*- F
39	1		*TORSION BAR	Bent	0.00 F	*- F
40	1		*TORSION BAR BRACKET	Bent	0.00 F	*- F
41	1		*AIR-CON UNIT DUCT	Bent	0.00 F	*- F
42	1		*METER ASSY	Cracked	0.00 F	*- F
43	1		*RADIO CONSOLE	Cracked	0.00 F	*- F
44	1		*CABIN AIR-DUCT	Deformed	0.00 F	*- F
45	1		*FLOOR PANEL	Repair	0.00 F	*- F

F=Franchise part.

Total Parts (\$\$)**0.00****0.00**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >