

## View Sent Message

This mail is associated with :

**\*SDP5550P (2278724035SG)**

OD

Jul 22 2020 1:00PM

[ONG THIAN HOCK]

Premium Automobiles Pte Ltd

[Resend](#)[View Recipients](#)[Print Message](#)[Delete Message](#)[Forward](#)

**From** LKK Auto Consultants Pte Ltd (LKK\_HQ), sent on **11/08/2020 16:25 PM.**

**To** Victor-CK.Koh@aig.com

**CC** denisetay@lkkauto.com

**Subject** \*SDP5550P (2278724035SG) OD

Dear Victor,

According to our surveyor, after rear exhaust been replaced, the centre exhaust could not be properly aligned. It was observed that the centre exhaust mountings and brackets were out position.

it was subsequently determined that the centre exhaust was also bent as a result of the accident(Please see uploaded).

As the centre exhaust is currently unavailable and to save rental cost, vehicle is currently released back to owner

For your approval.

Regards,  
Denise Tay  
LKK Auto

### DOCUMENTS SUMMARY

There are no documents.

