

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20007863/ATF3E2

Date: 05/02/2021

REFERENCE

Insured/Claimant:	DISHA SINGHVI KHOSLA	Policy No:	1800042897		
Date of Loss:	23/07/2020	Nature of Claim:	OD	Claim No:	9820814538SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ2507M		
Make & Model:	AUDI Q5, 2.0 TFSI Quattro (A)	Engine No:	DAX030922
Reg. Date:	26/04/2018 (Man. Year: 2018)	Chassis No:	WAUZZZF9J2129663
Colour:	Grey	Odometer:	12513 km
Engine Capacity:	1984 cc		
Market Value/New Car Price:	S\$150,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,715.00	2,138.80	5,576.20	72.28
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,552.00	2,552.00	2,000.00	43.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,267.00	4,690.80	7,576.20	61.76
- Excess (S\$)	1,000.00	1,000.00	0.00	0.00
(S\$)	11,267.00	3,690.80	7,576.20	67.24
+ GST 7.00/7.00% (S\$)	788.69	258.36	530.33	67.24
Nett Amount (S\$)	12,055.69	3,949.16	8,106.53	67.24

INSPECTION

Date of Assignment:	30/07/2020		
Date Inspected:	30/07/2020	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	3.0 days		

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER - UPPER	Repair	1,724.00 FS	*- FS
2	1		*REAR BUMPER - LOWER	Repair	1,182.00 FS	*- FS
3	1		*REAR BUMPER SPOILER	Cut	830.00 FS	*663.60 FS
4	1		*REAR BUMPER TOWING EYE COVER - RH	Not Necessary	29.00 FS	*- FS
5	1		*REAR BUMPER CLOSING ELEMENT - RH	Not Necessary	95.00 FS	*- FS
6	1		*REAR BUMPER TRIM - RH	Not Necessary	234.00 FS	*- FS
7	1		*TAIL LIGHT - RH	Cut	691.00 FS	*552.80 FS
8	1		*BOOT LID CONTROL UNIT	Not Necessary	399.00 FS	*- FS
9	1		*REAR BUMPER CARRIER	Not Necessary	911.00 FS	*- FS
10	1		*REAR BUMPER HOLDING STRAP	Not Necessary	166.00 FS	*- FS
11	2		*REAR PARKING AID SENSOR (NPA)	Not Necessary	0.00 FS	*- FS
12	2		*REAR WHEEL COVER - LH / RH	Necessary	1,154.00 FS	*922.40 FS
13	1		*SUNDRIES	Not Necessary	300.00 FS	*- FS
Total Parts (S\$)					7,715.00	2,138.80

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	360.00	360.00
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	1,200.00	500.00
3	TO RESPRAY REAR TOP BUMPER, REAR LOWER BUMPER AND BOTH REAR WHEEL ARCH TRIMS	New	2,800.00	1,500.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			4,552.00	2,552.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >