

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20007867/T1ES3Q2
Date: 10/09/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100284313
Claimant Vehicle No :	SHC8983A	Insured Vehicle No :	SGK106M
Date of Loss:	29/07/2020	Nature of Claim:	TP
		Claim No:	1209681595SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC8983A	Engine No:	D4FDGU624925
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU089815
Reg. Date:	19/05/2016 (Man. Year: 2016)	Odometer:	385507 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,922.16	11,094.04	3,828.12	25.65
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,100.00	3,150.00	950.00	23.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	19,022.16	14,244.04	4,778.12	25.12
Approved Total (Overridden) (S\$)		11,400.00		

(S\$)	19,022.16	11,400.00	7,622.16	40.07
+ GST 7.00/7.00% (S\$)	1,331.55	798.00	533.55	40.07
Nett Amount (S\$)	20,353.71	12,198.00	8,155.71	40.07
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (S\$)		402.33		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		12,707.82		

INSPECTION

Date of Assignment: 30/07/2020

Date Inspected: 30/07/2020

Estimated Period of Repair: 7.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,106.00 FL	*1,106.00 FL
2	1		*REAR BUMPER CENTRE MOULDING ASSY	Not Necessary	451.25 FL	*- FL
3	1		*REAR BUMPER REFLECTOR LAMP (LH)	Cracked	31.90 FL	*31.90 FL
4	1		*REAR BUMPER TOWING COVER	Missing	98.80 FL	*98.80 FL
5	1		*REAR BUMPER LOWER CENTRE MOULDING ASSY	Deformed	155.00 FL	*155.00 FL
6	1		*REAR BUMPER REINFORCEMENT BRACKET	Not Necessary	80.30 FL	*- FL
7	1		*REAR BUMPER REINFORCEMENT	Cracked	428.40 FL	*428.40 FL
8	10		*REAR BUMPER CLIP	Necessary	22.00 FL	*22.00 FL
9	1		*REAR BUMPER BRACKET	Necessary	35.60 FL	*35.60 FL
10	1		*REAR BUMPER SPONGE	Deformed	119.50 FL	*119.50 FL
11	1		*REAR BUMPER UNDER COVER	Not Necessary	228.00 FL	*- FL
12	1		*REAR BUMPER PROTECTOR (LH)	Not Necessary	33.20 FL	*- FL
13	1		*TAIL LAMP (LH)	Cracked	697.80 FL	*697.80 FL
14	1		*TAIL LAMP QUARTER PANEL (LH)	Bent	226.50 FL	*226.50 FL
15	1		*TAIL LAMP PANEL TOP (LH)	Bent	545.90 FL	*545.90 FL
16	1		*TAIL LAMP LOWER PANEL (LH)	Bent	225.60 FL	*225.60 FL
17	1		*REAR FENDER (LH)	Bent	2,171.40 FL	*2,171.40 FL
18	1		*EXHAUST SILENCER (LH)	Bent	967.70 FL	*967.70 FL
19	1		*EXHAUST PIPE CENTRE	Bent	730.10 FL	*730.10 FL
20	1		*REAR WINDSCREEN MOULDING	Necessary	51.80 FL	*51.80 FL
21	1		*FRONT DOOR (RH)	Repair	2,256.40 FL	*- FL
22	1		*FRONT BUMPER COVER	Deformed	1,052.20 FL	*1,052.20 FL
23	1		*FRONT BUMPER SPONGE	Not Necessary	99.20 FL	*- FL
24	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	438.40 FL	*- FL
25	1		*FRONT BUMPER GRILLE (RH)	Cut	93.60 FL	*93.60 FL
26	1		*FRONT BUMPER CENTRE GRILLE	Cut	114.00 FL	*114.00 FL
27	1		*FRONT BUMPER LIP	Not Necessary	54.00 FL	*- FL
28	1		*FRONT FENDER (RH)	Bent	663.00 FL	*663.00 FL
29	1		*HEADLAMP SUPPORT PANEL ASSY	Not Necessary	907.40 FL	*- FL
30	1		*HEADLAMP (RH)	Cracked	1,388.00 FL	*1,388.00 FL
31	1		*HEADLAMP SUPPORT TOP COVER	Not Necessary	222.60 FL	*- FL
32	1		*HEADLAMP HALOGEN BULB (RH)	Not Necessary	14.40 FL	*- FL
33	1		*REAR BUMPER RUBBER MAT	Cut	50.00 FS	*50.00 FS
34	1		*REAR BUMPER REVERSE SENSOR	Not Working	180.00 FS	*180.00 FS
35	1		*REAR BUMPER ADVERTISEMENT LOGO	Necessary	50.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*REAR WINDSCREEN SEALANT	Necessary	46.00 FS	*46.00 FS
37	1		*FRONT DOOR COMFORTDELGRO STICKERS (RH)	Necessary	75.00 FS	*75.00 FS
38	1		*BOOTLID	Bent	2,174.90 FL	*2,174.90 FL
39	1		*BOOTLID -CRDI PLATE	Necessary	27.90 FL	*27.90 FL
40	1		*BOOTLID I40 EMBLEM (I40)	Necessary	27.90 FL	*27.90 FL
41	1		*BOOTLID H EMBLEM	Necessary	28.70 FL	*28.70 FL
42	1		*WHEEL CAP FRT RH	Deformed	107.10 FL	*107.10 FL
43	1		*BOOTLID COMFORTDELGRO STICKER	Necessary	30.00 FS	*30.00 FS
44	1		*BOOTLID TEL NO.STICKER	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)**18,537.45****13,752.30****- List Item Discount on L Items 20.00/20.00% (S\$)**

3,615.29

2,658.26

Total Parts (S\$)**14,922.16****11,094.04**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	2,000.00	1,400.00
2	SPRAY PAINTING	New	1,500.00	1,400.00
3	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
4	TOWING FEE	New	60.00	60.00
5	REMOVE/REFIX UPHOLSTERY ETC	New	150.00	60.00
6	REMOVE/REFIX REAR WINDSCREEN	New	150.00	120.00
7	4 WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (S\$)			4,100.00	3,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >