

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007871/QVF3E2

Date: 26/08/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00037912000
Claimant Vehicle No :	SGN4639A	Insured Vehicle No :	GBD8430U
Date of Loss:	27/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202662/C02/THAMYL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN4639A	Engine No:	3ZZ4614339
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053ZEC107135087
Reg. Date:	17/11/2006 (Man. Year: 2006)	Odometer:	216176 km
Colour:	Silver		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	395.00	395.00	0.00	0.00
Miscellaneous Items	50.00	30.00	20.00	40.00
Labour	247.80	205.80	42.00	16.95
Paintwork Labour	385.02	385.02	0.00	0.00
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	1,077.82	1,015.82	62.00	5.75
Approved Total (Overridden) (S\$)		800.00		
(S\$)	1,077.82	800.00	277.82	25.78
+ GST 7.00/7.00% (S\$)	75.45	56.00	19.45	25.78
Nett Amount (S\$)	1,153.27	856.00	297.27	25.78

INSPECTION

Date of Assignment:	30/07/2020	Present Location:	Auto Insure Pte Ltd (HQ) (Woodlands)
Date Inspected:	30/07/2020	Inspected At:	Auto Insure Pte Ltd (HQ) (Woodlands) 6 Marsiling Lane Singapore 739145
Estimated Period of Repair:	3.0 days		

Adjuster: OI SUN PIN**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Aug 2020)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN4639A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SPARE PARTS		395.00 F	*395.00 F
						F=Franchise part.
Total Parts (S\$)					395.00	395.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	EXTRA	50.00	30.00
Sub Total (\$\$)			50.00	30.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	TOTAL PAINT INCLUDING MATERIALS	New	385.02	385.02
<u>Labour Items</u>				
2	TOTAL OF LABOUR	New	247.80	205.80
Gross Labour Cost (\$\$)			632.82	590.82

Report was unsubmitted during this print-out.

< END OF ESTIMATES >