

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20007873/AQF3Q2

Date: 29/10/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSNW00052982000
Claimant Vehicle No :	GBA1242H	Insured Vehicle No :	SGQ1488Y
Date of Loss:	24/07/2020	Nature of Claim:	TP
		Claim No:	SNM20D202596/C02/LOWCT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA1242H	Engine No:	1KD1583981
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Chassis No:	JTFHT02PX00002298
Reg. Date:	01/03/2007 (Man. Year: 2007)	Odometer:	469135 km
Colour:	White		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	CST 6 mm	Rear Left Side:	CST 6 mm
Front Right Side:	CST 6 mm	Rear Right Side:	CST 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,299.93	3,664.42	1,635.51	30.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,640.00	1,720.00	920.00	34.85
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,939.93	5,384.42	2,555.51	32.19
Approved Total (Overridden) (\$\$)		4,300.00		
(\$\$)	7,939.93	4,300.00	3,639.93	45.84
+ GST 7.00/7.00% (\$\$)	555.80	301.00	254.80	45.84
Nett Amount (\$\$)	8,495.73	4,601.00	3,894.73	45.84

INSPECTION

Date of Assignment:	30/07/2020	
Date Inspected:	30/07/2020	Inspected At:
		KAI MOTOR TRADING (HQ)
		BLK 3007 UBI ROAD 1, #01-440
		Singapore 408701
Estimated Period of Repair:	6.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Oct 2020)	
Parts:	N/A	TOYOTA HIACE 3.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA1242H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT COVER	Distorted	2,110.10 FL	*1,855.00 FL
2	1		*REAR BOOT COVER RUBBER	Cut	321.30 FL	*321.30 FL
3	1		*REAR RUBBER BRACKET	Not Necessary	201.00 FL	*- FL
4	1		*REAR BOOT COVER 70KM/H	Necessary	23.33 FS	*10.00 FS
5	1		*REAR BOOT COVER 7 PAX	Necessary	22.73 FS	*10.00 FS
6	1		*REAR BOOT COVER INNER LOCK	Jammed	213.40 FL	*213.40 FL
7	1		*REAR BOOT COVER GARNISH	Repair	148.30 FL	*- FL
8	2		*REAR LAMP ASSY	Cut	595.00 FL	*595.00 FL
9	1		*REAR PANEL OUTER	Dented	251.30 FL	*251.30 FL
10	1		*REAR PANEL INNER	Dented	296.30 FL	*296.30 FL
11	1		*REAR BUMPER	Distorted	415.30 FL	*415.30 FL
12	10		*REAR BUMPER CLIPS	Necessary	60.00 FL	*30.00 FL
13	2		*REAR BUMPER SIDE RETAINER	Necessary	130.60 FL	*130.60 FL
14	1		*SET REVERSE SENSOR	Damaged	369.45 FS	*200.00 FS
15	1		*REAR BOOT COVER MIRROR	Not Necessary	396.30 FL	*- FL
16	1		*REAR SPARE TYRE BRACKET	Bent	299.60 FL	*299.60 FL
17	1		*REAR SPARE TYRE RIM	Not Necessary	200.00 FL	*- FL
18	1		*REAR BOOT COVER INNER TRIM BOX	Not Necessary	301.30 FL	*- FL
19	1		*REAR BOOT COVER LOGO	Necessary	78.10 FL	*78.10 FL
20	2		*REAR LAMP LOWER GARNISH	Repair	226.60 FL	*- FL
21	2		*REAR LAMP LOW GARNISH RETAINER	Not Necessary	121.40 FL	*- FL
22	1		*REAR WINDSCREEN GLASS INNER SEAL	Necessary	55.00 FS	*40.00 FS
23	1		*REAR WINDSCREEN SEALANT	Necessary	55.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,891.41	4,785.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,591.48	1,121.48
Total Parts (\$\$)	5,299.93	3,664.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACE DAMAGED PARTS ,PANEL BEAT WHERE NECESSARY	New	1,250.00	800.00
2	TO PUTTY ,APPLY PRIMER & SPRAY PAINT ON THE AFFECTE PORTION	New	1,250.00	800.00
3	LABOUR CHARGE TO REMOVE & REFIX WINDSCREEN	New	140.00	120.00
Gross Labour Cost (\$\$)			2,640.00	1,720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >