



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL
(BUDGET DIRECT INSURANCE)
190 CLEMENCEAU AVENUE #03-01
SINGAPORE SHOPPING CENTRE
SINGAPORE 239924

INV No. AC2005858
INV Date 26/08/2020
Reference CS/AGI20007880/Uvf3n2
Code AGI



PROFESSIONAL SERVICE FEE

Vehicle No. SLB 29R
Insured Veh. SGS 2364D
Claim No. C10006852
Policy No.
Accident Date 28/07/2020
Inspection Date 01/08/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI20007880/Uvf3n2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 26-08-2020



Code : AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGS 2364D	Veh. Inspected	SLB 29R
Policy No.		Coverage (\$)	0.00
Claim No.	C10006852	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	30/07/2020

2. Vehicle Particulars & Condition

Make & Model	LEXUS NX200T (A)	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JTJBARBZ502038184	Colour	BLUE
Odometer	177139	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/55 R18	MICHELIN	6 mm
L/H Front Tyre	235/55 R18	MICHELIN	6 mm
R/H Rear Tyre	235/55 R18	MICHELIN	6 mm
L/H Rear Tyre	235/55 R18	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/07/2020	Inspection Date	01/08/2020
Survey held at	23 KAKI BUKIT AVE 4 #04-01 (SOUTH WING)		
Repairer	AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD (AIM)		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLB 29R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	DENTED / BENT	2,340.89	2,340.89
1	TAILGATE GLASS	NOT NECESSARY	1,483.59	-
1	SET TAILGATE GLASS MOULDING	NECESSARY	120.65	120.65
1	TAILGATE LOGO	NECESSARY	173.70	145.00
1	TAILGATE EMBLEM "LEXUS"	NECESSARY	110.22	110.22
1	TAILGATE EMBLEM "NX 200T"	NECESSARY	110.22	110.22
1	TAILGATE INNER LOCK	NOT NECESSARY	1,229.75	-
1	TAILGATE W/STRIP	NOT NECESSARY	311.43	-
1	REAR BUMPER	DISTORTED	899.65	899.65
2	REAR BUMPER LOWER EXTENSION	DISTORTED	561.23	561.23
2	REAR REFLECTORS-L/R @\$89.95	NOT NECESSARY	179.90	-
4	REAR BUMPER PDC SENSORS @\$414.73	SHORTED (1 PC ONLY)	1,658.92	342.11
1	REAR BUMPER PDC SENSOR WIRE HARNESS	NOT NECESSARY	281.95	-
1	REAR BUMPER SPONGE	NO SUCH PARTS	230.11	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	757.60	-
2	REAR BUMPER REINFORCEMENT STAYS-L/R @\$115.20	NOT NECESSARY	230.40	-
2	REAR BUMPER SIDE RETAINERS-L/R @\$64.43	NOT NECESSARY	128.86	-
1	REAR BUMPER UNDERCOVER	NOT NECESSARY	191.63	-
1	REAR END PANEL	DENTED	811.50	811.50
1	REAR END PANEL GARNISH	NOT NECESSARY	413.35	-
1	REAR EXHAUST SILENCER-RH	NOT NECESSARY	891.90	-
1	REAR EXHAUST CHROME PIPE-RH	NOT NECESSARY	361.50	-
1	REAR SMART KEYLESS ANTENNA	NOT NECESSARY	211.30	-
	LESS 10% DISCOUNT		-1,369.03	-544.15
			12,321.22	4,897.32
	<u>SPECIAL NETT ITEMS</u>			
1	SET TAILGATE GLASS SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	45.00	45.00

Report Ref No. CS/AGI20007880/Uvf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET TAILGATE OUTER GARNISH CLIP (SN)	NOT NECESSARY	80.00	-
			205.00	85.00
	<u>LABOUR</u>			
	TO CHECK REAR ELECTRICAL WIRING.		80.00	20.00
	TO REMOVE,REFIX TAILGATE GLASS.		180.00	120.00
	TO RESPRAY UNDERCOATING.		120.00	60.00
	TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR.		180.00	80.00
	REINSTALL TAILGATE ELECTRICAL & MECHANICAL TO NEW TAILGATE.		150.00	60.00
	TO RESPRAY PAINTING AND ETC.		1,200.00	800.00
	PANEL BEATING,CUT,WELD REMOVE & REPLACING ABOVE PARTS.		1,200.00	600.00
			3,110.00	1,740.00
GRAND TOTAL			15,636.22	6,722.32
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,350.00

Report Ref No. CS/AGI20007880/Uvf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 29R

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 29R

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLB 29R

RE-INSPECTION

