

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 04 Aug 2020

## **Preliminary Advice**

Vehicle No	: SMU243B	Accident Date	: 29/07/2020
Make	: HONDA SHUTTLE HYBRID	Policy No.	: DMPCSNW00094252000
Assignment Date	: 03/08/2020	Excess	: S\$800.00
Date of Inspection	: 03/08/2020	Est. Duration of Repair	: 10 days
Inspection At	: Xin Yun Auto Private Limited (HQ) 1 Kaki Bukit Avenue 6, #01-59 Autobay @ Kaki Bukit Singapore 417883		

### **Point of Impact / General Description of Damages**

The vehicle sustained impact / damages at the front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	29,865.80
Revised Amount	:S\$	14,535.00
Check Items (Estimated)	:S\$	6,233.90
Total	:S\$	20,768.90

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	79,000.00
COE / PARF Rebate	:S\$	45,884.00
Salvage Value	:S\$	
Margin for Repair	:S\$	33,116.00

### **Remarks**

- ( X ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Repairer do not want to put up cost prices, the vehicle repair on part by part basis.