

PRIORITY SERVICES

Insurance Loss Adjusters And Motor Appraisers
Block 779 Yishun Avenue 2 #01-1545 Singapore 760779
Tel : 62934822 Fax : 62963283

VEHICLE INSPECTION REPORT

Report No. TP/0130/19	Date of Report	: 24 December 19
To : Pang Siew Choon	Date of Request	: 9 December 19
Block 782A Woodlands Crescent	Report requested by	: Pang Siew Choon
#07-303	Date of Accident	: 6 December 19
Singapore 731782	Date of Inspection	: 9 December 19
	Claim No.	: Third Party Claim

PARTICULARS OF DAMAGED VEHICLE

Registration Plate No	: SMG 2878 E	Odometer Reading	: 107,829 km
Make	: Nissan	Carrying Capacity	: 4
Model	: Sylphy (A)	Radio / Cassette / CD	: Yes
Year of Manufacture	: 2018	Air-Conditioner	: Yes
Colour	: Met. Grey	Wing Mirror	: Yes
Engine Capacity	: 1,598 cc	Clock	: Yes
Engine No	: --	Seat Belts	: Yes
Chassis / Frame No	: MNTBBAB17Z0033835	Others	: Nil

TYRE CONDITION

Front Left	: 6mm	Front Right	: 6mm
Make	: Bridgestone	Make	: Bridgestone
Rear Left	: 6mm	Rear Right	: 6mm
Make	: Bridgestone	Make	: Bridgestone
Spare	:	Road Wheels Type	: Alloy

(The above represents the approximate remaining life of tyre treads)

Jack & Tools	: Intact	Spare Tyre	: -
--------------	----------	------------	-----

PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Body Work	: Good
Paint Work	: Good
Handbrake	: Serviceable
Footbrake	: Serviceable
Steering	: Serviceable
Apparent engine modification	: Nil

This report is confidential and is given for the use of clients and their agents and any disclosure or publication of it or parts thereof shall be the responsibility of such person and no liability shall be attached to us therefore.

ASSESSMENT

	<u>Repairer's Estimate (S \$)</u>	<u>Our Recommendation (S \$)</u>
Spare Parts :	8,613.00	6,418.10
Labour Charges :	1,910.00	1,350.00
Paint Work :	1,450.00	1,200.00
Towing Charges :	0.00	0.00
Others :	0.00	0.00
Totals :	11,973.00	8,968.10

Reduction (S \$) : 3,004.90

Recommended Reserve (S \$) : 8,968.10

Estimated Normal Period of Repairs : 6 working days

CONTRIBUTIONS BY INSURED

Excess (S \$) : N/A

Others : --

LONPAC INTERNAL-CONFIDENTIAL

GENERAL REMARKS

WITHOUT PREJUDICE

Continuation Sheet

The Assignment

The survey was conducted at M/s. MG Solution Pte Ltd, No. 23, Kaki Bukit Avenue 4 (South Wing), #02-03, Singapore 415933.

Follow-up inspection has been conducted.

Point of Impact

At the rear portion.

Damages

The boot lid, boot lid hinges, rear bumper, rear bumper reinforcement, end panel, tail lamps assembly, etc.

Other parts were also found damaged. (see schedule for details)

Adjustment / Recommendation

We have inspected thoroughly each and every item on the repairer's estimate against the actual damages found on the vehicle and we list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is \$8,968.10

Conclusion


The repairer has agreed to undertake repairs at our adjusted amount of \$8,968.10 corresponding to labour charges, spray painting and replacement of parts.

Pre-Accident Market Value : About \$70,000.00
COE and PARF rebate from LTA : \$34,894.00

We now revert to you for your decision on repairs.

Very truly yours

PRIORITY SERVICES



JIMMY S. T. LEE AMSOE, AMIRTE, AMSAE-AUS, MSAAA
Motor Appraiser



LAWRENCE NG
Motor Appraiser

Encl. Photographs of the damaged vehicle taken by us during inspection.

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
To Supply :					
1 pc boot lid	Distorted	1,299.00		1,299.00	10
1 pc boot lid 'Sylphy' emblem	Necessary	72.00		72.00	10
1 pc boot lid centre emblem	Necessary	122.00		122.00	10
1 pc boot lid lock	Bent	105.00		105.00	10
1 pc boot lid lock catch	Bent	78.00		78.00	10
1 pc boot lid RH hinge	Bent	196.00		196.00	10
1 pc boot lid LH hinge	Bent	196.00		196.00	10
1 pc boot lid inner trim	Crumpled	382.00		382.00	10
1 set boot lid inner trim clips	Necessary	50.00		50.00	10
1 pc boot lid RH lamp assy	Cracked	203.00		203.00	10
1 pc boot lid LH lamp assy	Refit	203.00		--	10
1 pc boot lid weatherstrip	Bent	155.00		155.00	10
1 pc rear bumper	Dented	873.00		873.00	10
1 set rear bumper clips	Necessary	50.00		50.00	10
1 pc rear bumper RH side reflector	Cracked	84.00		84.00	10
1 pc rear bumper RH side reflector cover	Refit	132.00		--	10
1 pc rear bumper RH side retainer	Cracked	78.00		78.00	10
1 pc rear bumper LH side retainer	Cracked	78.00		78.00	10
1 pc rear bumper RH bracket arm	Dented	109.00		109.00	10
1 pc rear bumper LH bracket arm	Refit	109.00		--	10
1 pc rear bumper sponge	Cracked	203.00		203.00	10
1 pc RH tail lamp assy	Cracked	338.00		338.00	10
1 set RH tail lamp lock clips	Necessary	28.00		28.00	10
1 pc LH tail lamp assy	Cracked	338.00		338.00	10
1 set LH tail lamp lock clips	Necessary	28.00		28.00	10
1 pc end panel	Dented / Distorted	844.00		844.00	10
1 pc end panel inner trim	Deformed	231.00		231.00	10
1 pc rear keyless sensor	Cracked	187.00		187.00	10
1 pc spare tyre panel top board	Refit	408.00		--	10
1 pc rear RH fender inner trim	Deformed	502.00		502.00	10
1 set rear RH fender inner trim clips	Necessary	40.00		40.00	10
1 pc rear LH fender inner trim	Refit	502.00		--	10
1 set rear LH fender inner trim clips	Necessary	40.00		40.00	10
Sub-Total :-		8,263.00		6,909.00	
Total Discount :-		--		690.90	
		8,263.00		6,218.10	
Special Nett Items :-					
1 set rear bumper reverse sensor	Dented / Malfunctioned	350.00		200.00	
Total For Parts :-		8,613.00		6,418.10	
Labour Charges :					

Vehicle No : SMG 2878 E Nissan Sylphy (A)

TP/0130/19

Workshop : MG Solution Pte Ltd

Replacement of Parts	Condition	Repairer's Estimate (S \$)	Dist. %	Our Recommendation (S \$)	Dist. %
Remove and replace the above listed parts, knock straighten and reshape, cut and weld body panel parts where necessary, reposition and realign, replacement parts to the original position including adjustment.		1,300.00		1,000.00	
Apply rust coating on repaired and replaced panels.		100.00		60.00	
Check wiring and lighting system.		70.00		40.00	
Remove, reinstall and replace rear inner fenders, boards and trims to assist repairs.		240.00		150.00	
Remove, reinstall and replace rear bumper reverse sensors and wire harness to assist repairs.		100.00		40.00	
Remove, reinstall and adjust boot lid reverse camera.		100.00		60.00	
Spray Painting :					
Putty and spray repaired and replaced body panels.		1,450.00		1,200.00	
Grand Total :-		11,973.00		8,968.10	

Surveyed By : Lawrence Ng