

National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5636C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	EMBLEM, SIDE PANEL (HYBRID) (DISC 25%)	NECESSARY	54.60	40.95
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH (DISC 25%)	SCRATCHED	100.40	75.30
1	COVER, OUTER MIRROR, LH (DISC 25%)	CRACKED	108.60	81.45
1	MIRROR ASSY, OUTER REAR VIEW, LH (DISC 10%)	CRUMPLED	1,339.30	1,205.37
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
1	LINER, FR FENDER, LH	SERVICEABLE	210.30	-
1	PILLAR, FRONT BODY, LH	SERVICEABLE	350.00	-
1	TYRE	SERVICEABLE	126.74	-
2	HUB & BEARING ASSY, RH & LH	SERVICEABLE	668.90	-
1	GLASS, FRONT DOOR FIX WINDOW, LH	SERVICEABLE	69.90	-
1	WEATHERSTRIP, FRONT DOOR FIX WINDOW, LH	SERVICEABLE	76.40	-
1	FENDER SUB-ASSY, FR, LH	TO REPAIR SEE LABOUR	977.80	-
1	WHEEL, DISC FRONT	TO REPAIR SEE LABOUR	1,879.40	-
1	PANEL SUB-ASSY, FRONT DOOR LH	TO REPAIR SEE LABOUR	1,300.70	-
			7,323.04	1,463.07
	<u>LABOUR</u>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF FENDER SUB-ASSY, FR, LH, WHEEL, DISC FRONT AND PANEL SUB-ASSY, FRONT DOOR LH.		507.00	200.00
	SPRAY PAINT.		1,296.00	530.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO REMOVE AND REFIX WING MIRROR.		120.00	30.00
	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).		120.00	30.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-
			2,403.00	810.00
	GRAND TOTAL		9,726.04	2,273.07

Report Ref No. NS/INC20007932/Qqf3e2





2,273.07

Report Ref No. NS/INC20007932/Qqf3e2

Ja

OI SUN PIN

Asst. Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser