

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20007937/QES3Q2
Date: 30/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800020813
Claimant Vehicle No :	SG5930X	Insured Vehicle No :	SJT781E
Date of Loss:	14/07/2020	Nature of Claim:	TP
		Claim No:	0142756849SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SG5930X	Engine No:	50350202315017
Make & Model:	MAN A95, 10.5 D (A)	Chassis No:	WMAA95ZZ7JF006923
Reg. Date:	01/06/2018 (Man. Year: 2018)	Odometer:	110392 km
Colour:	Multi-colour		
Engine Capacity:	10518 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	275/70 R22.5	Rear Tyre Size:	275/70 R22.5
Front Left Side:	Firenza 6 mm	Rear Left Side:	Firenza 6 mm
Front Right Side:	Firenza 6 mm	Rear Right Side:	Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,108.00	1,035.00	3,073.00	74.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,662.00	1,227.00	435.00	26.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	5,770.00	2,262.00	3,508.00	60.80
+ Loss of Use (4.0 x S\$300.00/day) (S\$)		1,200.00		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,469.00		

INSPECTION

Date of Assignment:	28/07/2020		
Date Inspected:	28/07/2020	Inspected At:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4 Singapore 757705
Estimated Period of Repair:	3.0 days		

Adjuster: OI SUN PIN

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*REAR EXIT DOOR GLASS	Not Necessary	2,750.00 F	*- F
2	1		*PRIMER (SIKA 206 G+P)	Not Necessary	80.00 F	*- F
3	4		*ADHESIVE DIRECT GLAZING	Not Necessary	148.00 F	*- F
4	1		*ACTIVATOR	Not Necessary	80.00 F	*- F
5	1		*SMRT STICKER	Necessary	90.00 FS	*75.00 FS
6	2		*ADVERTISEMENT STICKER (SN)	Necessary	960.00 FS	*960.00 FS
Total Parts (S\$)					4,108.00	1,035.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS	New	1,060.00	795.00
2	TO PUTTY & RESPRAY	New	602.00	432.00
Gross Labour Cost (S\$)			1,662.00	1,227.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >