

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/TM120007946/T1TF3E2
Date: 17/08/2020

REFERENCE

Handling Insurer: Tokio Marine Insurance Singapore Ltd	Policy No:	MR003460
Claimant Vehicle No : SHC1037C	Insured Vehicle No :	YP6704H
Date of Loss: 29/07/2020	Nature of Claim:	TP
	Claim No:	M2003719

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC1037C	Engine No:	G4LEKU299281
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Chassis No:	KMHC851CVKU165089
Reg. Date:	01/08/2019 (Man. Year: 2019)	Odometer:	141678 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,266.32	737.60	528.72	41.75
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	720.00	550.00	170.00	23.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,997.32	1,298.60	698.72	34.98
+ GST 7.00/7.00% (S\$)	139.81	90.90	48.91	34.98
Nett Amount (S\$)	2,137.13	1,389.50	747.63	34.98

INSPECTION

Date of Assignment:	12/08/2020	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	30/07/2020	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Aug 2020)
Parts: 192	HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHC1037C)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Repair	459.40 FL	-	*- FL
2	1		*REAR BUMPER CTR MOULDING	Deformed	451.25 FL	-	*451.25 FL
3	1		*REAR BUMPER LWR MOULDING	Deformed	155.00 FL	-	*155.00 FL
4	1		*REAR BUMPER FOGLAMP	Not Necessary	201.50 FL	-	*- FL
5	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
6	1		*REVERSE SENSOR	Not Working	180.00 F	-	*180.00 F
7	1		*REAR NO.PLATE W/TRIM COVER	Cracked	55.00 F	-	*55.00 F

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,524.15	863.25
- List Item Discount on L Items 20.00/20.00% (S\$)	257.83	125.65
Total Parts (S\$)	1,266.32	737.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	350.00	320.00
2	SPRAY PAINTING	New	250.00	200.00
3	R/I REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$)			720.00	550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >