



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

KELVIN C.H.I.A PARTNERSHIP

Ref : CS/LAW20007947/Dsf3e2

6 TEMASEK BOULEVARD 29TH FLOOR SUNTEC
TOWER FOUR SINGAPORE 038986

Date : 18-08-2020



Code : L041

1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)

Insured Veh.	SLP 4412S	Veh. Inspected	GBG 1953H
Policy No.		Coverage (\$)	0.00
Claim No.	2020000138.Sompo(mpd)	Excess (\$)	0.00
Assign From	TEO YI XUAN	Assign Date	01/08/2020

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KDY2318029040	Colour	WHITE
Odometer	48584	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/70 R15C	MICHELIN	5 mm
L/H Front Tyre	195/70 R15C	MICHELIN	5 mm
R/H Rear Tyre	145 R13 (D)	BRIDGESTONE	5/5 mm
L/H Rear Tyre	145 R13 (D)	BRIDGESTONE	5/5 mm

4. Description of Damages

THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.

REPAIR CONDITION SEE DETAILS.

5. General Information

Accident Date	30/04/2019	Inspection Date	11/08/2020
Survey held at	3 MOTORWERKZ 25 KAKI BUKIT ROAD 4 SYNERGY @ KB #01-42 SINGAPORE 417800		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------