

Surveyor: REF: CS/LAW20007947/Dsf3 Special Instruction: LS \$6,700.00

From (Person): Teo Yi Xuan of Kelvin Chia Date/Time: 01/08/2020
 Estimated Cost: Bill to: Third Parties: Claimant: Owner
 Surveyor: Sincere Appraisal
 Workshop: 3 Motorwerkz

OT/TP Re-inspection / Evaluation
 To Inspect Vehicle No: GBG 1953H Insured: SLP 4412S
 at Workshop m/s 3 Motorwerkz Tel: 97972800
 of 25 Kaki Bukit Road 4 #01-42
 Policy No: Claim No: 2020000138.Sompo(mpd)
 Sum Insured: Excess:
 Make of Veh: D.O.A. 30/04/2019
 (Client's Record) day 11.8.2020 2pm H.O.D. Endorsement/Date: SJE

Date/Time: Person Contacted: Vehicle IN / OUT
 Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 07 days)
 Date/Time: 13/08/20 Submit Final Fig 45 \$3,500 / 5 days (Red \$3,200 / 48%; Original 7 days)

Date/Time	Action/Instruction
	GBG 1953H - X Inspection: Primur 704-06
	SLP 4412S - X

13/08/20 To Submit 2/3 3500 - with 5 days of rem.
 Photo by Priority show tailgate not changed.
 Other item indicated HH ros photo show no damage.


Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value	Inspected/ Evaluated by:	Fee Charged:	Date:
Salvage Value		Basic & Add	
Nett Value		Transport	
		Photos	
		Others	
		Total	

1) Date/Time File Pass to 2) Date/Time File Return to
 3) Date/Time File Pass to 4) Date/Time File Return to
 5) Date/Time File Pass to 6) Date/Time File Return to



ASS. REC. BY: _____

ASSIGNMENT

From: _____ Date: _____ Veh No: GBG 1953H Yr Reg: 2017 June
Estimated Cost: _____ Type: M. Car / M. Cycle / Bus / Van / Lorry / Truck / Prime Mover /
CD / TP / WS / TP RES / CD RES / EVA / INV / MV Truck / Trailer or
To inspect Vehicle No: _____ Make: Toyota Dyna CC 2982
at Workshop m/s _____ Colour: white A/C: Insured / Std / Nil / NA
of _____ Sp. Reading: 48584 T/Radio: Insured / Std / Nil / NA
Insured: _____ Eng No: 1KD2702130
Policy No. _____ C/No: KDY2318029040
Claims No. _____ Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: _____ Excess: _____ Steering: Insured / Jammed / Leaked / Burnt or
(Client's Record) Brake: Insured / Jammed / Leaked / Burnt or
Make of Veh: _____ Mod: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 195/70 R15C
R: 145/R13
(Policy Condition)

N/S	O/S
-----	-----

 BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUM /
Remark: The veh had commenced its TOYO / YOKO or
repair at the time of inspection. Front Michelin Rear Bridgestone
Bal. or Market Value: _____ R/Bal. S mm R/Bal. S/S mm
IDAC Accident Report _____ Consistent? : Yes or No L/Bal. S mm L/Bal. S/S mm
GIA / PR Seen: _____ Consistent? : Yes or No D.O.A. _____ D.O.I. 11/08/2020
Est. Repairs: _____ days Res.: Yes or No Survey held at Premix Kaki Bukit #4-06
Lum Sum: _____ % 3 Val.: Yes or No Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or
CA / REV / REP. / 24 HRS Vehicle: IN / OUT
Date: _____ Person Contacted: _____ The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SJB Physical re-inspection</u>

Date/Time, File Pass to? ☐ : Prel. Report Days Of Repair: _____
1) ☐ : Final Report Resurvey No. of Trip: _____
Date/Time, File Return to? Survey Fee: _____
2) _____ Transportation: _____
Add Fee: ☐ : Site Insp (\$) S + RS _____
☐ : Interview (\$) Photos _____
☐ : Tech. Invs (\$) Other _____
☐ : Weekend (\$) _____
Report Format: _____
Lum Sum / L.B.f: (\$) _____
TOTAL



SINCERE
APPRAISAL SERVICES PTE LTD

VEHICLE DAMAGE INSPECTION REPORT

Date: 10/5/2019

Our Ref: 282/TP/2019

REFERENCE

Date of loss: 30/4/2019
Claimant: Greenview Landscape & Construction Pte Ltd

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBG1953H
Reg date: 22/6/2017
Colour: White
Type: Lorry
Type of Claims: Third Party

Make & Model: Toyota Dyna 3.0M
Engine No: 1KD2702130
Chassis No: KDY2318029040
Odometer No: 25953km
Engine Cap: 2982cc

**CONDITION OF VEHICLE AT THE TIME OF SURVEY
(STATIC ONLY)**

General Condition: Good	Steering: Good	Engine Modification: Nil
Paint work: Good	Handbrake: Good	Pre-accident Damage: Nil
	Footbrake: Good	

CONDITION OF TYRES

Front Left Size: Bridgestone 195/70R15 70%
Rear Left Size: Michelin 145/R13 70%

Front Right Size: Bridgestone 195/70R15 70%
Rear Right Size: Michelin 145/R13 70%

The above percentages represent the remaining life of the tyre threads

COST OF REPAIRS

Parts
Labour

Calculated Cost (S\$):


Repairer S\$	Adjuster S\$
\$ 10,007.75	\$ 6,347.75
\$ 2,470.00	\$ 1,970.00
\$ 12,477.75	\$ 8,317.75

Recommended Lump Sum Repair Cost (S\$): **\$ 6,700.00**

Date of Assignment: 2/5/2019
Date Inspected: 2/5/2019
Est. repair Period: 07 days

Inspected At: 3 Motorwerkz Concept Pte Ltd
25 Kaki Bukit Road 4
#01-40
Singapore 417800

POINT OF IMPACT



BRIEF CIRCUMSTANCES OF ACCIDENT

The Insured's vehicle collided onto the Third Party's Vehicle along Upper Thomson Road.

GENERAL DESCRIPTION OF DAMAGES

Our visual inspection of the vehicle revealed that the damages noted are at the rear portion.

SPECIAL REMARKS

We have inspected the actual damages found on the vehicle and recommend the replacement of parts and repairs accordingly. The estimated repair cost is \$12,477.75. The repairer has agreed to undertake the repairs at our adjusted lump sum amount of \$6,700.00.

We have not authorised the repair. Under normal circumstances, estimated 07 working days are required to repair the vehicle.

We are pleased to advise that the inspection work was carried out accordingly, and hereby submit our Inspection Report and photographs.



Dave Chang
Automotive Appraiser
AUTO. ENG. CAE. CGI
MIRTE, MSAAA, MTM

Automotive Appraiser: Dave Chang

Please note that this report is solely based on our findings at the time and place of inspection. This inspection has been carried out to our best knowledge and ability. Any other liability is hereby excluded.

ANNEX A

REPAIR DETAILS

Recommended Parts

No	Qty	Description	Condition	Repairer's Amount	Adjuster's Amount
1	1	Rear tailgate assy	dented/warped/bent	\$ 1,697.00	\$ 1,697.00 R
2	4	Rear tailgate hinges	bent/necessary	\$ 260.00	\$ 130.00 260.00 L
3	2	Rear tailgate reflector	bent/necessary	\$ 166.00	\$ 166.00 NH
4	1	Rear tailgate left lower lock hinge	bent/necessary	\$ 176.00	\$ 176.00 L
5	2	Rear tailgate left rubber stopper	necessary	\$ 28.00	\$ 28.00 L
6	1	Rear tailgate left rubber stopper bracket	necessary	\$ 58.00	\$ 58.00 L
7	1	Rear left taillamp	cracked	\$ 562.00	\$ 562.00 L
8	1	Rear left taillamp bracket	bent/necessary	\$ 114.00	\$ 114.00 L
9	2	Rear taillamp bracket round reflector	bent/necessary	\$ 244.00	\$ 122.00 244.00 L 0/s NH
10	2	Rear no plate lamp	bent/cut	\$ 89.00	\$ 89.00 NH
11	1	Rear no plate support bracket	bent	\$ 120.00	\$ 120.00 L
12	1	Rear lower floor panel	repair	\$ 3,230.00	\$ -
13	1	Rear hook	bent	\$ 180.00	\$ 180.00 L
14	1	Rear spare tyre bracket carrier	bent	\$ 380.00	\$ 380.00 NH
15	1	Rear spare tyre lock holder	bent	\$ 283.00	\$ 283.00 NH
16	1	Rear exhaust pipe assy	repair	\$ 1,650.00	\$ -
				\$ 9,237.00	\$ 4,357.00
				\$ 2,309.25	\$ 1,089.25
				\$ 6,927.75	\$ 3,267.75

Less 25%

<u>Special Nett Items</u>					
1	1	Rear tailgate '70km/h' sticker	necessary	\$ 30.00	\$ 30.00 L
2	1	Rear tailgate '12pax' sticker	necessary	\$ 30.00	\$ 30.00 L
3	1	Rear tailgate '>1500kg' sticker	necessary	\$ 30.00	\$ 30.00 NF
4	1	Rear tailgate 'Dyna' sticker	necessary	\$ 30.00	\$ 30.00 NF
5	1 set	Rear tailgate sticker	necessary	\$ 30.00	\$ 30.00 NF
6	1	Rear tailgate aluminium plate	necessary	\$ 650.00	\$ 650.00 NH
7	1	Rear step panel	bent	\$ 250.00	\$ 250.00 L
8	1	Rear centre towing panel	twisted	\$ 650.00	\$ 650.00 L
9	1	Rear spare tyre	bent/necessary	\$ 450.00	\$ 450.00 NH
10	1	Rear left lower luggage box assy	dented/bent	\$ 650.00	\$ 650.00 L
11	1	Rear left lower luggage box bracket	bent/necessary	\$ 200.00	\$ 200.00 L
12	1	Rear no plate	necessary	\$ 80.00	\$ 80.00 45/-
				\$ 3,080.00	\$ 3,080.00

Total parts

\$ 10,007.75 \$ 6,347.75

ANNEX B

REPAIR DETAILS

Recommended Labour

No	Description	Repairer's Amount	Adjuster's Amount
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,000.00	\$ 800.00 800/-
2	To putty and spray painting rear portion.	\$ 1,000.00	\$ 800.00 500/-
3	To check rear lighting and wiring.	\$ 50.00	\$ 30.00
4	To apply anti rust proofing to rear affected area.	\$ 120.00	\$ 100.00 40/-
5	To remove and install rear left tailgate lock.	\$ 80.00	\$ 60.00 20/-
6	To remove and install rear tailgate aluminium plate.	\$ 120.00	\$ 100.00 NH
7	Towing service.	\$ 100.00	\$ 80.00 NH
Total labour :		\$ 2,470.00	\$ 1,970.00

ANNEX C

REPAIR DETAILS

Adjusted Repair Cost

	Repairer's Amount	Adjuster's Amount
Total parts :	\$ 10,007.75	\$ 6,347.75
Total labour :	\$ 2,470.00	\$ 1,970.00
Total repair cost :	\$ 12,477.75	\$ 8,317.75

Adjusted Repair Cost (Lump Sum Repair)

\$ 6,700.00

15 days

4352.50

L/S 3500/-