

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

EQ Insurance Company Ltd
5 Maxwell Road, #17-00 Tower Block, MND Complex
Singapore 069110

Our File No: CS/EQI20007963/EVF3Q2**Date:** 09/02/2021**REFERENCE**

Insured/Claimant: HO JU HUI JONATHAN Policy No: DMPPHQ20-000972

Date of Loss: 27/07/2020

Nature of Claim: OD

Claim No: DM20HO01098-OD

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMS1059X**

Make & Model: LOTUS ELISE, 1.6 (M)

Engine No: 2ZZ0185026

Reg. Date: 18/11/2009 (Man. Year: 2008)

Chassis No: SCCZC11158HN31928

Colour: Yellow

Odometer: 0 km

Engine Capacity: 1796 cc

Market Value/New Car Price: S\$130,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/45R16

Rear Tyre Size: 205/45R16

Front Left Side: Yokohama 5 mm

Rear Left Side: Yokohama 5 mm

Front Right Side: Yokohama 5 mm

Rear Right Side: Yokohama 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	36,167.50	30,498.00	5,669.50	15.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,200.00	8,150.00	3,050.00	27.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	47,367.50	38,648.00	8,719.50	18.41
- Excess (S\$)	5,000.00	5,000.00	0.00	0.00
(S\$)	42,367.50	33,648.00	8,719.50	20.58
+ GST 7.00/7.00% (S\$)	2,965.73	2,355.36	610.37	20.58
Nett Amount (S\$)	45,333.23	36,003.36	9,329.87	20.58

INSPECTION

Date of Assignment: 03/08/2020

Date Inspected: 04/08/2020 Inspected At:

Etalia Autoworkz Pte Ltd (HQ)
53 UBI AVENUE 1, #01-16 PAYA UBI
IND. PARK
Singapore 408934

Estimated Period of Repair: 10.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 01 Feb 2021)	
Parts:	N/A	LOTUS ELISE 1.6 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS1059X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT CLAM SHELL (WCP)	Broken	8,500.00 F	*8,500.00 F
2	1		*REAR CLAM SHELL (WCP)	Broken	9,000.00 F	*9,000.00 F
3	1		*DOOR HINGE COVER PANEL RH (WCP)	Broken	650.00 F	*650.00 F
4	1		*BRACKET FRONT LINER/ACCESS PANEL MOUNTING (WCP)	Necessary	25.00 F	*25.00 F
5	4		*POP RIVET DOMED BLACK BRACKET TO CLAM SHELL (WCP)	Necessary	46.00 F	*46.00 F
6	1		*GRILLE FRONT INTAKE RH (WCP)	Broken	85.00 F	*85.00 F
7	1		*GRILLE REAR TRANSOM RH (WCP)	Bent	55.00 F	*55.00 F
8	4		*CLIP CENTRAL GRILLE RETENTION (WCP)	Necessary	72.00 F	*72.00 F
9	4		*BRACKET CLIP TO CLAM SHELL (WCP)	Necessary	180.00 F	*180.00 F
10	4		*POP RIVET 3.2MM X 11MM BLACK BRACKET TO CLAM SHELL (WCP)	Necessary	40.00 F	*40.00 F
11	2		*CLIP OUTER GRILES RETENTION (WCP)	Necessary	34.00 F	*34.00 F
12	1		*SEAL NEOPRENE GRILLE TO CLAM SHELL (WCP)	Necessary	13.00 F	*13.00 F
13	1		*GRILLE PERFORATED OVAL HOLES REAR BODY TO DIFFUSER RH (WCP)	Bent	125.00 F	*125.00 F
14	1		*ECE INBOARD LAMP (WCP)	N/s Broken/O/s Not Necessary	1,520.00 F	*760.00 F
15	1		*ECE OUTBOARD LAMP (WCP)	N/s Broken/O/s Not Necessary	1,460.00 F	*730.00 F
16	1		*HEADLAMP ASSEMBLY RH (WCP)	Broken	1,500.00 F	*1,500.00 F
17	1		*HEADLAMP ASSEMBLY LH (WCP)	Not Necessary	1,500.00 F	*- F
18	1		*LAMP FRONT INDICATOR RH (WCP)	Broken	245.00 F	*245.00 F
19	1		*LAMP FRONT INDICATOR LH (WCP)	Not Necessary	245.00 F	*- F
20	2		*SET GLASS,FLAT (WCP)	Broken	290.00 F	*290.00 F
21	1		*DIFFUSER ASSEMBLY SILVER (WCP)	Bent	635.00 F	*635.00 F
22	1		*AEROFOIL ASSEMBLY BODY MOUNTED 10 MY (WCP)	Broken	415.00 F	*415.00 F
23	1		*PLINTH MIRROR MOUNTING (WCP)	Missing	35.00 F	*35.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
24	1		*ENGINE COVERLID NO ANTENNA HOLE (WCP)	Broken	560.00 F	*560.00 F
25	1		*GRILLE FRONT INTAKE CENTRAL WITH DRIVING LAMP (WCP)	Broken	145.00 F	*145.00 F
26	1		*OIL COOLER RH (WCP)	Dented	480.00 F	*480.00 F
27	1		*STUD PLATE BRACKET FIXING REAR (WCP)	Missing	20.00 F	*20.00 F
28	1		*STUD PLATE BRACKET FIXING FRONT (WCP)	Missing	35.00 F	*35.00 F
29	1		*STRIKER/LIFT ASSEMBLY ENGINE COVER LID (WCP)	Bent	610.00 F	*610.00 F
30	1		*BRACKET LATCH RETENTION (WCP)	Not Necessary	75.00 F	*- F
31	1		*LATCH ASSEMBLY (WCP)	Jammed	65.00 F	*65.00 F
32	1		*BADGE LOTUS RAISED CHROME LETTERS (WCP)	Necessary	30.00 F	*30.00 F
33	1		*LOWER ARM FRONT RH (WCP)	Not Necessary	500.00 F	*- F
34	1		*LOWER ARM REAR RH (WCP)	Not Necessary	550.00 F	*- F
35	1		*UPPER ARM FRONT RH (WCP)	Not Necessary	420.00 F	*- F
36	1		*UPPER ARM REAR RH (WCP)	Bent	420.00 F	*420.00 F
37	1		*OIL COOLER HOSE FRONT (WCP)	Not Necessary	150.00 F	*- F
38	2		*MIRROR HOUSING (WCP)	Broken	720.00 F	*720.00 F

F=Franchise part.

Sub Total (\$\$)	31,450.00	26,520.00
+ Margin on L,N Items 15.00/15.00% (\$\$)	4,717.50	3,978.00
Total Parts (\$\$)	36,167.50	30,498.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK ELECTRICAL SYSTEM AND REPAIR WIRE HARDNESS FOR FRONT BUMPER	New	250.00	200.00
2	TO TRANSFER FRONT BUMPER COMPONENT TO NEW FRONT BUMPER	New	300.00	250.00
3	TO REMOVE AND INSTALL FRONT INTERIOR TRIMS,GARNISHES,ETC FOR NECESSARY REPAIRS	New	300.00	250.00
4	TO REMOVE AND INSTALL EXHAUST SILENCER FOR NECESSARY REPAIRS	New	300.00	250.00
5	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS FOR FRONT BUMPER	New	2,400.00	2,000.00
6	TO CHECK ELECTRICAL SYSTEM AND REPAIR WIRE HARDNESS FOR REAR BUMPER	New	250.00	200.00
7	TO TRANSFER TAILGATE COMPONENT PARTS TO NEW TAILGATE	New	250.00	200.00
8	TO REMOVE,REPLACE AND/OR TRANSFER REAR REVERSE SENSORS & CONTRO UNIT	New	300.00	200.00
9	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS FOR REAR BUMPER	New	2,400.00	2,000.00
10	TO CONDUCT CHASSIS ALIGNMENT	New	350.00	0.00
11	TO SPRAY PAINTING,BLENDING ON EFFECTED AND ADJACENT AREA INCLUDING RIGHT HAND SIDE SKIRT	New	2,000.00	1,700.00
12	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS	New	400.00	100.00
13	TO REMOVE,REPLACE AND REINSTALL SUSPENSION FOR FRONT RIGHT HAND AND REAR RIGHT HAND	New	500.00	300.00
14	TO INSPECTION,DIAGNOSIS,RESET AND PERFORM CODING PROGRAMMING ON:1)REAR REVERSE CAMERA AND SENSOR SYSTEMS.SECURITY LOCK AND REAR BOOT SYSTEM	New	500.00	300.00
15	TO REMOVE AND REPAIR DRIVE SHAFT	New	300.00	0.00
16	TO REMOVE AND REPLACE RIM TYRES,INCLUDING TYRES BALANCING	New	400.00	200.00
Gross Labour Cost (\$\$)			11,200.00	8,150.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >