Adjuster Report Page 1 of 4

### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20007972/R1GS3Q2

Date: 24/11/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SLE1924J

Insured Vehicle No: SHC2312B Vehicle No:

Date of Loss: 29/07/2020 Nature of Claim: ΤP Claim No: MCT20070382

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SLE1924J** Reg No:

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGGU194339

Reg. Date: 13/07/2016 (Man. Year: 2016) Chassis No: KMHD841CMHU200451

142996 km Colour: Odometer: Grey

**Engine Capacity:** 1591 cc Market Value/New Car

N/A Price:

Sum Insured (S\$): Market Value/New Car Price

**CONDITION OF VEHICLE AT THE TIME OF SURVEY** 

**General Condition:** Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Yes Engine Modification: Pre-accident Condition: Handbrake (Serviceable):

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Michelin 6 mm Front Left Side: Rear Left Side: Michelin 6 mm Front Right Side: Rear Right Side: Michelin 6 mm Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		5,292.70	2,584.88	2,707.82	51.16
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,350.00	920.00	1,430.00	60.85
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	7,642.70	3,504.88	4,137.82	54.14
	Approved Total (Overridden) (S\$)		2,800.00		
	(S\$)	7,642.70	2,800.00	4,842.70	63.36
	+ GST 7.00/7.00% (S\$)	534.99	196.00	338.99	63.36
	Nett Amount (S\$)	8,177.69	2,996.00	5,181.69	63.36
	+ Car Rental (7.0 x S\$100.00/day + 7.	00% GST) (S\$)	749.00		
	+ Doc/S	earch Fee (S\$)	7.45		
	Ne	tt Liability (S\$)	3,752.45		
	Global Sum Settlement (S\$)		3,700.00		

**INSPECTION** 

Date of Assignment: 05/08/2020

05/08/2020 Inspected At: Cheng Auto Bodyworks (HQ) Date Inspected:

5 Soon Lee Street #01-62 Pioneer

Singapore 627607

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 4

Adjuster: MOHD RASUL Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

### REPAIR DETAILS

Reference

Part Source: MRM SC. Version: 1.0 (Lest Synchronicad: 09 Oct.)

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Oct 2020)

Parts: 143 HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)

**Labour:** Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SLE1924J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

Condition

Total Parts (S\$)

Repairer's

**Amount** 

2,584.88

5,292.70

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

# Recommended Parts No. Qty Part No. Particulars

	~-,		T di diodidio	o o i i a i a i a i	rtopulioi o	, uno and
1	1		*RH FRT DOOR	Bent	1,868.64 FL	*1,350.00 FL
2	1		*RH FRT DOOR HINGE UPPER	Serviceable	32.64 FL	*-FL
3	1		*RH FRT DOOR HINGE LOWER	Serviceable	32.64 FL	*-FL
4	1		*RH FRT DOOR CHECKER	Serviceable	36.72 FL	*-FL
5	1		*RH FRT DOOR RUBBER	Necessary	96.90 FL	*96.90 FL
6	1		*RH FRT DOOR LOCK ASSY	Serviceable	198.90 FL	*- FL
7	1		*RH FRT DOOR CATCH	Serviceable	25.50 FL	*-FL
8	1		*RH FRT DOOR OUTER CHROME HANDLE ASSY	Cracked	209.10 FL	*197.00 FL
9	1		*RH FRT DOOR REGULATOR	Serviceable	260.10 FL	*-FL
10	1		*RH FRT DOOR REGULATOR MOTOR	Serviceable	306.00 FL	*- FL
11	1		*RH FRT DOOR GLASS	Serviceable	219.30 FL	*-FL
12	1		*REAR RH DOOR	Bent	1,810.50 FL	*1,350.00 FL
13	1		*REAR RH DOOR HINGE UPPER	Serviceable	36.72 FL	*-FL
14	1		*REAR RH DOOR HINGE LOWER	Serviceable	32.64 FL	*- FL
15	1		*REAR RH DOOR RUBBER	Necessary	112.20 FL	*112.20 FL
16	1		*REAR RH DOOR OUTER CHROME	Serviceable	96.90 FL	*- FL
17	1		*FRT RH DOOR OUTER CHROME	Serviceable	76.50 FL	*-FL
18	1		*REAR RH DOOR QUARTER GLASS	Serviceable	326.40 FL	*-FL
19	1		*FRT RH DOOR INNER TRIMBOARD	Serviceable	462.57 FL	*-FL
20	1		*FRONT INNER TRIMBOARD RH CLIPS	Necessary	100.00 FS	*50.00 FS
21	1		*REAR DOOR TRIMBOARD RH CLIPS	Necessary	100.00 FS	*50.00 FS
22	1		*SEALANT QUARTER GLASS	Not Necessary	100.00 FS	*-FS
F=Fra	nchise	part. S=Spc	Nett. L=ListItemDisc.	,		
				Sub Total (S\$)	6,540.87	3,206.10
			<ul> <li>List Item Discount on L Items 20</li> </ul>	.00/20.00% (S\$)	1,248.17	621.22

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	LABOUR	New	800.00	400.00
2	SPRAY PAINTING	New	800.00	400.00
3	REMOVE AND REPLACE WINDOW GLASS /QUARTER GLASS	New	150.00	0.00
4	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR /FACILITATE REPAIR	New	300.00	60.00
5	DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM TO NEW DOOR /FACILITATE REPAIR	New	300.00	60.00
	Gross Labour Cost (S\$)		2,350.00	920.00

< END OF ESTIMATES >

Report was unsubmitted during this print-out.