

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20007973/KEA3Q2

**Date:** 08/02/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100449783

**Claimant**  
**Vehicle No :** SLX852P **Insured Vehicle No :** SBJ333M

Date of Loss: 01/08/2020 Nature of Claim: TP Claim No: 3207372671SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLX852P</b>		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB6311404
Reg. Date:	15/03/2018 (Man. Year: 2016)	Chassis No:	GP71109399
Colour:	Metallic Black	Odometer:	181747 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	KAPSEN 8 mm	Rear Left Side:	AGENDA 6 mm
Front Right Side:	KAPSEN 8 mm	Rear Right Side:	AGENDA 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,290.96	3,053.16	1,237.80	28.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,215.00	1,105.00	47.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>6,610.96</b>	<b>4,268.16</b>	<b>2,342.80</b>	<b>35.44</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>(S\$)</b>	6,610.96	3,400.00	3,210.96	48.57
<b>+ GST 7.00/7.00% (S\$)</b>	462.77	238.00	224.77	48.57
<b>Nett Amount (S\$)</b>	<b>7,073.73</b>	<b>3,638.00</b>	<b>3,435.73</b>	<b>48.57</b>
<b>+ Car Rental (4.0 x S\$80.00/day) (S\$)</b>		320.00		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>3,960.00</b>		

### INSPECTION

Date of Assignment: 03/08/2020

Date Inspected: 03/08/2020 Inspected At:

Hui Yang Motor Pte Ltd (HQ)  
176 Sin Ming Drive #04-02, Sin Ming  
AutoCare  
Singapore 575721

Estimated Period of Repair: 4.0 days

---

**Adjuster:** KENNETH KONG**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.70 FL	*1,193.70 FL
2	1		*REAR TAILGATE H LOGO	Necessary	58.00 FL	*58.00 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
4	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	75.00 FL	*75.00 FL
5	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
6	1		*REAR TAILGATE INNER RUBBER	Distorted / Dented	188.50 FL	*188.50 FL
7	1		*REAR TAILGATE INNER LOCK	Dented	389.40 FL	*196.20 FL
8	1		*REAR TAILGATE INNER GARNISH	Mtg Distorted	458.50 FL	*243.80 FL
9	1		*REAR BUMPER	Buckled	1,150.60 FL	*1,072.50 FL
10	2		*REAR BUMPER SIDE RETAINER	Serviceable	77.00 FL	*- FL
11	8		*REAR BUMPER CLIP	Necessary	40.00 FL	*40.00 FL
12	1		*REAR END PANEL	Repair	685.00 FL	*- FL
13	1		*REAR END PANEL INNER GARNISH	Mtg Distorted	285.50 FL	*155.00 FL
14	1		*SET REAR PARKING SENSOR	Cut	280.00 FS	*200.00 FS
15	1		*SET REAR NUMBER PLATE & CASING	Dented	50.00 FS	*35.00 FS
16	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>5,261.20</b>	<b>3,747.70</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	970.24	694.54
<b>Total Parts (S\$)</b>	<b>4,290.96</b>	<b>3,053.16</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	100.00	15.00
3	TUFFKOTE	New	100.00	30.00
4	SPRAY PAINTING	New	1,000.00	600.00
5	LABOUR CHARGES	New	1,000.00	450.00
<b>Gross Labour Cost (\$)</b>			<b>2,320.00</b>	<b>1,215.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >