

ASS. REC. BY:

REF:

AG / 2000 7973 / ke

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4-

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLX 852P

Yr Regn:

03, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Shuttle

c.c

1496

Colour

M. Black

A/C:

Insured / Std / NI / NA

Sp. Reading

181747

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP7

1109399

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F: Haper 185/60R15

R: Apende

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

6

mm

L/Bal.

8

mm

L/Bal.

6

mm

D.O.A.

1/18/20

D.O.I.

3/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1/ GIA not ready

7/8 1/18mp @ 3400l Car Panel

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

GST & Reg No. 201629438M

AlG.
Neh In)
LKK
Kenneth

01/08/2020

Owner: U&G CAR LEASING

Not Authorized
C1Rng 83400h
Purway After Paint
4. day

ESTIMATE TO REPAIR HONDA SHUTTLE HYBRID - SLX852P

1pc	rear tailgate		\$ 1,193.70	✓
1pc	rear tailgate "H" logo		\$ 58.00	—
1pc	rear tailgate "SHUTTLE" emblem		\$ 55.00	—
1pc	rear tailgate "HYBRID" emblem		\$ 75.00	—
1pc	rear tailgate windscreen moulding		\$ 195.00	—
1pc	rear tailgate inner rubber		\$ 188.50	✗ 2
1pc	rear tailgate inner lock	196.20	\$ 389.40	✗ 2
1pc	rear tailgate inner garnish	243.80	\$ 458.50	✗ 2
1pc	rear bumper	1072.50	\$ 1,150.60	✓
2pcs	rear bumper side retainer @\$38.50		\$ 77.00	✗
8pcs	rear bumper clip @\$5.00		\$ 40.00	—
1pc	rear end panel		\$ 685.00	✗
1pc	rear end panel inner garnish	155.00	\$ 285.50	✓
			\$ 4,851.20	
less 20%			\$ 970.24	
			\$ 3,880.96	

1set rear parking sensor
1set rear number plate & casing

Cur s.nett \$ 280.00 200sm
N. S. s.nett \$ 50.00 35sm

remove & refit rear windscreen glass	\$ 120.00	✓
sealant	\$ 80.00	40sm
wiring	\$ 100.00	15h
tuffkote	\$ 100.00	30h
spray painting	\$ 1,000.00	60h
labour charges	\$ 1,000.00	450h
Total	\$ 6,610.96	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: