

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD		Ref : CC4/ASM20007	Ref: CC4/ASM20007993/Aba3q2	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KITTY TEO		Date: 10-11-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Ve	h. GBD 3173U	Veh. Inspected	SCR 21J	
Policy No.	GA393877/1	Coverage (\$)	0.00	
Claim No.	S0M02RJ6	Excess (\$)	0.00	
Assign Fro	om	Assign Date	03/08/2020	
2. Vehicle Particulars & Condition				
Make & Mo	del TOYOTA HARRIER	c.c	1998	
Engine No	. HIDDEN	Year of Reg.	2019	
Chassis No). JTEKB3GH10J004080	Colour	BLACK	
Odometer	15489	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front	-	BRIDGESTONE	6 mm	
L/H Front 1	-	BRIDGESTONE	6 mm	
R/H Rear T	-	BRIDGESTONE	6 mm	
L/H Rear T		BRIDGESTONE	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident D		Inspection Date	03/08/2020	
Survey hel				
BLK C, 1 KAKI BUKIT AVENUE 6 #01-43 SINGAPORE 417883				
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days				