

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20007994/T1RA3Q2
Date: 08/12/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800089582
Claimant Vehicle No :	SHC2001Z	Insured Vehicle No :	GBG4707H
Date of Loss:	30/07/2020	Nature of Claim:	TP
		Claim No:	8264941820SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC2001Z		
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Engine No:	D4FDGU700033
Reg. Date:	20/12/2017 (Man. Year: 2016)	Chassis No:	KMHLB41UMHU100076
Colour:	Blue	Odometer:	389082 km
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	611.00	536.00	75.00	12.27
Miscellaneous Items	0.00	0.00	0.00	
Labour	600.00	230.00	370.00	61.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,211.00	766.00	445.00	36.75
+ GST 7.00/7.00% (S\$)	84.77	53.62	31.15	36.75

Nett Amount (S\$)	1,295.77	819.62	476.15	36.75
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$56.34/day) (S\$)		281.70		
+ Doc/Search Fee (S\$)		7.49		
Nett Liability (S\$)		1,358.81		

INSPECTION

Date of Assignment: 02/08/2020

Date Inspected: 03/08/2020

Estimated Period of Repair: 1.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*MIRROR ASSY -O/S REA	Distorted	670.00 FL	*670.00 FL
2	1		*FRT DOOR LOGO CTPL	Not Necessary	75.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$)					745.00	670.00
- List Item Discount on L Items 20.00/20.00% (\$)					134.00	134.00
Total Parts (\$)					611.00	536.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	300.00	100.00
2	SPRAYPAINT ON AFFECTED AREA	New	250.00	100.00
3	CHECK ALL LIGHTING	New	50.00	30.00
Gross Labour Cost (\$\$)			600.00	230.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >