

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III20007995/R1BA3Q2

Date: 23/09/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SKL551H	Insured Vehicle No :	SHB6202P
Date of Loss: 30/07/2020	Nature of Claim: TP	Claim No: MCT20070414

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKL551H		
Make & Model:	BMW 730LI, 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A)	Engine No:	10487820N52B30AF
Reg. Date:	11/11/2011 (Man. Year: 2011)	Chassis No:	WBAKB22090C951160
Colour:	Grey	Odometer:	109224 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	245/50 R18	Rear Tyre Size:	245/50 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,282.65	3,778.50	4,504.15	54.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,705.20	5,019.00	1,686.20	25.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,987.85	8,797.50	6,190.35	41.30
+ GST 7.00/7.00% (S\$)	1,049.15	615.83	433.32	41.30
Nett Amount (S\$)	16,037.00	9,413.33	6,623.67	41.30
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
		9,913.33		

INSPECTION

Date of Assignment:	17/08/2020	
Date Inspected:	17/08/2020 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	6.0 days	

Adjuster: MOHD RASUL**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Sep 2020)
Parts:	143	BMW 730LI 3.0 AT ABS D/AB 2WD 4DR NAV HID SR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKL551H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*80.00 FS
2	1		*TRIM PANEL	Serviceable	2,945.60 FS	*- FS
3	1		*RR BUMPER CARRIER	Serviceable	870.00 FS	*- FS
4	1		*RR BUMPER RH MOUNT	Cracked	198.30 FS	*198.30 FS
5	1		*RR BUMPER ADAPTER	Cracked	45.75 FS	*45.75 FS
6	1		*REAR BUMPER TRIM PRIMED	Deformed	242.25 FS	*242.25 FS
7	1		*RR BUMPER CTR GUIDE	Serviceable	67.45 FS	*- FS
8	1		*BOOTLID CHROME TRIM STRIP	Serviceable	85.35 FS	*- FS
9	2		*EMBLEM GROMMET	Necessary	1.70 FS	*1.70 FS
10	1		*MODEL LETTERING 730LI	Necessary	64.45 FS	*64.45 FS
11	1		*BMW EMBLEM 82MM	Necessary	71.60 FS	*71.60 FS
12	1		*RR BUMPER RH REFLECTOR	Scratched	37.75 FS	*37.75 FS
13	1		*RR RH FENDER LIGHT	Scratched	788.55 FS	*788.55 FS
14	1		*RR RH BOOTLID LIGHT	Serviceable	465.75 FS	*- FS
15	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.40 FS	*20.40 FS
16	1		*BUMPER PDC SENSOR (A90 SOPHISTOGRAU)	Distorted	370.00 FS	*370.00 FS
17	1		*RR BUMPER (PDC)	Scratched	1,695.75 FS	*1,695.75 FS
18	1		*COVERING REAR RIGHT	Cracked	134.30 FS	*134.30 FS
19	1		*RR BUMPER VENTILATION COVERING	Cracked	27.70 FS	*27.70 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) **8,282.65** **3,778.50**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE OLD PDC ASSEMBLY ,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	150.00	150.00
2	TO REPLACE REAR BUMPER PANEL AND ATTACHMENTS ,REWORK BOOTLID AND TAIL PANEL	New	3,825.00	2,550.00
3	TO RESPRAY REAR BUMPER ,BOOTLID AND TAIL PANEL	New	2,282.20	1,939.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
5	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			6,705.20	5,019.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >