



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD	INV No.	AC2103560
3 ANSON ROAD #16-00	INV Date	19/05/2021
SPRINGLEAF TOWER	Reference	CC6/CTI20007996/Apa3q2
SINGAPORE 079909	Code	CTI

PROFESSIONAL SERVICE FEE

Vehicle No.	SJT 5965J
Insured Veh.	ES 9120T
Claim No.	SNM20D202683/C02
Policy No.	DMPCSN30657819000
Accident Date	29/07/2020
Inspection Date	03/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909		Ref: CC6/CTI20007996/Apa3q2 Date: 19/05/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	ES 9120T	Veh. Inspected	SJT 5965J
Policy No.	DMPCSN30657819000	Coverage (\$)	0.00
Claim No.	SNM20D202683/C02	Excess (\$)	0.00
Assign From		Assign Date	03/08/2020
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA ALTIS	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053ZEE106157899	Colour	WHITE
Odometer	146991 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MICHELIN	6 mm
L/H Front Tyre	195/65 R15	MICHELIN	6 mm
R/H Rear Tyre	195/65 R15	MICHELIN	6 mm
L/H Rear Tyre	195/65 R15	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	29/07/2020	Inspection Date	03/08/2020
Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 5965J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BONNET	DENTED	655.30	655.30
2	BONNET HINGE @\$88.00	NOT NECESSARY	176.00	-
1	BONNET LOCK	DAMAGED	160.00	160.00
1	BONNET LOCK BRACE PANEL	BENT	110.00	110.00
1	FRONT BUMPER	DISTORTED	450.00	450.00
2	FRONT BUMPER SIDE RETAINER @\$62.40	NECESSARY	124.80	124.80
1	FRONT BUMPER WEATHERSTRIP	CUT	90.00	90.00
1	FRONT BUMPER REINFORCEMENT	BENT	388.40	388.40
2	FRONT BUMPER FOG LIGHT @\$190.00	N/S CRACKED	380.00	190.00
2	FRONT BUMPER FOG LIGHT COVER @\$80.00	N/S MISSING	160.00	160.00
1	FRONT BUMPER TOP GRILLE	CRACKED	399.50	399.50
1	FRONT BUMPER LOWER GRILLE	MISSING	160.00	160.00
1	FRONT BUMPER LOGO	NECESSARY	69.30	69.30
2	HEADLAMP @\$455.20	CRACKED	910.40	910.40
2	HEAD LAMP LOWER BRACKET @\$66.40	NOT NECESSARY	132.80	-
2	FRONT FENDER @\$466.70	TO REPAIR SEE LABOUR	933.40	-
2	FRONT FENDER EMBLEM 'VVTI' @\$65.20	NECESSARY	130.40	130.40
2	FRONT FENDER INNER COWLING @\$180.00	NOT NECESSARY	360.00	-
1	SUPPORT PANEL	BUCKLED	950.20	770.80
2	HORN @\$95.20	NOT NECESSARY	190.40	-
1	AIR CONDENSOR	BENT	1,395.00	1,295.00
2	AIR CONDENSOR MOUNTING @\$18.00	NOT NECESSARY	36.00	-
1	AIR CON PIPE (H)	NOT NECESSARY	370.00	-
1	AIR CON PIPE (L)	NOT NECESSARY	370.00	-
1	RADIATOR	DENTED	1,760.00	1,651.00
2	RADIATOR TOP BRACKET @\$50.00	BENT	100.00	100.00
2	RADIATOR TOP MOUNTING @\$60.00	NOT NECESSARY	120.00	-
2	RADIATOR BOTTOM MOUNTING @\$60.00	NOT NECESSARY	120.00	-
1	RADIATOR FAN COWLING	CRACKED	276.00	276.00
1	FRONT WIPER WASHER TANK (UPPER)	NOT NECESSARY	176.00	-

Report Ref No. CC6/CTI20007996/Apa3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT WIPER WASHER TANK (LOWER)	NOT NECESSARY	295.00	-
1	FRONT WIPER WASHER TANK MOTOR	NOT NECESSARY	235.00	-
1	RADIATOR FAN COWLING MOTOR	DAMAGED	230.00	230.00
	LESS 25% DISCOUNT		-3,103.48	-2,080.23
			9,310.42	6,240.67
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT NUMBER PLATE (SN)	CRACKED	50.00	50.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	20.00	20.00
1	SET FRONT BUMPER UNDER COVER GARNISH CLIP (SN)	NECESSARY	20.00	20.00
1	FRONT GRILLE CLIP (SN)	NECESSARY	20.00	20.00
1	SET FRONT FENDER COWLING CLIPS (SN)	NOT NECESSARY	20.00	-
1	SET HEADLAMP CLIP (SN)	NECESSARY	20.00	20.00
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	40.00
1	BATTERY (SN)	CUT	250.00	180.00
			480.00	350.00
	<u>LABOUR</u>			
	PANEL BEATING ,REMOVING AND REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT FENDER.		1,800.00	800.00
	SPRAY PAINTING TO AFFECTED AREA.		1,800.00	800.00
	WIRING CHECK .		150.00	30.00
	REFOCUS HEADLAMP BEAM.	NOT NECESSARY	60.00	-
	REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS.		120.00	60.00
	REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST.		80.00	60.00
			4,010.00	1,750.00
	GRAND TOTAL		13,800.42	8,340.67
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			6,600.00

Report Ref No. CC6/CTI20007996/Apa3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 5965J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 5965J

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJT 5965J

RE-INSPECTION

