

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20008001/EVF3E2

Date: 14/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070037721
Claimant Vehicle No : GBG2138M	Insured Vehicle No : SMJ1818U
Date of Loss: 16/07/2020	Nature of Claim: TP Claim No: 8310419331SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG2138M		
Make & Model:	NISSAN NV350 HR MICROBUS, 2.5 D 2.5 4DR 5AT	Engine No:	YD25419229A
	ABS D/A (A)		
Reg. Date:	27/06/2017 (Man. Year: 2017)	Chassis No:	JN1MC2E26Z0008425
Colour:	White	Odometer:	52904 km
Engine Capacity:	2488 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	04/08/2020	
Date Inspected:	11/08/2020 Inspected At:	Hup Ley Huat Motor Spray Painting Services BLK 1 KAKI BUKIT AVE 6 #01-35 Singapore 409793
Estimated Period of Repair:	4.0 days	

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIP	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Broken	0.00 F	*- F
4	1		*REVERSE SENSOR	Broken	0.00 F	*- F
5	1		*REAR RH TAILLAMP	Cracked	0.00 F	*- F
6	1		*REAR RH TAILLAMP PANEL	Repair	0.00 F	*- F
7	1		*TAILGATE	Dented	0.00 F	*- F
8	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
9	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
10	1		*TAILGATE LOCK	Bent	0.00 F	*- F
F=Franchise part.						
				Total Parts (\$\$)	0.00	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >