



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

SOMPO INSURANCE SINGAPORE PL
50 RAFFLES PLACE
#05-01/06
SINGAPORE LAND TOWER
SINGAPORE 048623

INV No. AC2005864
INV Date 26/08/2020
Reference CS/SMO20008004/Usf3n2
Code SMO



PROFESSIONAL SERVICE FEE

Vehicle No. SLD 1133E
Insured Veh. SME 59B
Claim No. CMTD2002247/GPL
Policy No.
Accident Date 31/07/2020
Inspection Date 04/08/2020

Description	Total
Survey Inspection	450.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	450.00
GST (7%)	31.50
Grand Total	481.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS/SMO20008004/Usf3n2

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERSINGAPORE 048623

Date : 26-08-2020



Code : SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SME 59B	Veh. Inspected	SLD 1133E
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2002247/GPL	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	04/08/2020

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ GLC250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WDC2539462F421662	Colour	WHITE
Odometer	31839	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/60 R18	HANKOOK	6 mm
L/H Front Tyre	235/60 R18	HANKOOK	6 mm
R/H Rear Tyre	235/60 R18	HANKOOK	6 mm
L/H Rear Tyre	235/60 R18	HANKOOK	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	31/07/2020	Inspection Date	04/08/2020
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	10 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 1133E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	TAILGATE	BADLY DENTED	2,999.10	2,999.10
1	TAILGATE REAR LOGO	NECESSARY	105.00	85.00
1	TAILGATE "GLC 250" EMBLEM	NECESSARY	102.00	92.00
1	TAILGATE "4 MATIC" EMBLEM	NECESSARY	110.00	95.00
1	TAILGATE INNER LOCK	TWISTED / SHORTED	498.00	299.20
1	TAILGATE INNER TRIM	CRACKED	665.20	485.25
2	TAILGATE REFLECTORS @\$850.00	NOT NECESSARY	1,700.00	-
1	REAR BUMPER TOP	DISTORTED	2,155.00	1,436.60
1	REAR BUMPER CENTRE PAD	DISTORTED	825.00	592.11
1	REAR BUMPER CHROME MOULDING	CRACKED	995.00	550.00
2	REAR BUMPER SIDE RETAINERS @\$85.00	NOT NECESSARY	170.00	-
2	REAR BUMPER REFLECTORS @\$82.00	NOT NECESSARY	164.00	-
4	REAR BUMPER PDC SENSORS @\$188.00	SHORTED (2 PCS ONLY)	752.00	376.00
1	REAR BUMPER PDC WIRE	SERVICEABLE	315.61	-
2	REAR BUMPER INNER SIDE BRACKETS @\$95.00	CRACKED	190.00	190.00
1	REAR BUMPER INNER KICKING SENSOR	SHORTED	388.20	388.20
1	REAR BUMPER SPONGE	NO SUCH PARTS	288.35	-
1	REAR BUMPER REINFORCEMENT	BENT	815.00	715.00
1	SET REAR BUMPER RIVET	NECESSARY	60.00	60.00
1	REAR WINDSCREEN MOULDING	NECESSARY	945.00	166.00
1	REAR END PANEL	BENT	1,465.00	1,399.22
1	REAR END PANEL TOP GARNISH	TWISTED / CRACKED	493.00	306.00
1	REAR WEATHERSTRIP	TWISTED	399.00	315.42
1	REAR FLOOR PANEL	TO REPAIR SEE LABOUR	1,665.00	-
2	TAILLAMPS @\$1050.00	CRACKED	2,100.00	1,430.00
1	REAR FLOOR PANEL TOP BOARD	NOT NECESSARY	855.00	-
2	REAR FENDERS @\$2450.00	TO REPAIR SEE LABOUR	4,900.00	-

Report Ref No. CS/SMO20008004/Usf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	REAR FENDER INNER TRIM BOARDS @\$650.00	NOT NECESSARY	1,300.00	-
2	REAR FENDER OUTER PROTECTORS @\$399.00	NECESSARY / TORN	798.00	644.00
2	REAR EXHAUST OUTER CHROMES @\$480.00	SERVICEABLE	960.00	-
1	REAR EXHAUST	NOT NECESSARY	1,885.00	-
1	REAR EXHAUST HEAT SHIELD	BENT	466.25	335.25
1	BONNET	BUCKLED	3,611.10	2,115.00
1	BONNET LOGO	NECESSARY	105.00	82.00
2	BONNET HINGES @\$315.00	BENT	630.00	356.00
2	BONNET ACTUATORS @\$650.00	ACTIVATED	1,300.00	590.00
1	BONNET LEVER	BENT / CRACKED	366.00	316.00
1	BONNET INSULATOR	NOT NECESSARY	388.10	-
1	SET BONNET INSULATOR CLIPS	NOT NECESSARY	50.00	-
2	BONNET LOCK SPRINGS @\$105.00	NOT NECESSARY	210.00	-
2	BONNET LOCK HOOKS @\$135.00	NOT NECESSARY	270.00	-
1	FRONT GRILLE INNER	CRACKED	845.00	622.35
1	FRONT GRILLE OUTER	CRACKED	905.00	399.00
1	FRONT GRILLE LOGO	CRACKED	188.00	105.00
1	FRONT BUMPER	DENTED / DEFORMED	2,450.00	1,550.00
1	FRONT BUMPER CHROME MOULDING	CRACKED	925.00	595.22
1	FRONT BUMPER CENTRE GRILLE	TORN	845.00	488.20
2	FRONT BUMPER FOG LAMP COVERS @\$250.00	NOT NECESSARY	500.00	-
1	FRONT BUMPER SPONGE	TORN	292.00	292.00
1	FRONT BUMPER REINFORCEMENT	BENT	845.00	745.00
2	FRONT BUMPER SIDE RETAINERS @\$195.00	NOT NECESSARY	390.00	-
1	SET FRONT BUMPER RIVET	NECESSARY	60.00	60.00
1	FRONT BUMPER LICENCE PLATE GARNISH	DISTORTED	162.00	148.50
4	FRONT BUMPER PDC SENSORS @\$215.00	SHORTED (2 PCS ONLY)	860.00	430.00
1	FRONT BUMPER RADAR SENSOR	NOT NECESSARY	922.00	-
1	FRONT TOWING COVER	NOT NECESSARY	60.00	-
1	FRONT TOP PANEL	BENT / DENTED	615.00	520.00

Report Ref No. CS/SMO20008004/Usf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT TOP PANEL CENTRE GARNISH	DEFORMED / TWISTED	3,111.20	311.00
2	HEADLAMP ASSYS @\$6500.00	HOLDER CRACKED	13,000.00	6,113.90
1	AIR CON CONDENSOR	SERVICEABLE	1,245.00	-
1	RADIATOR	NOT NECESSARY	1,425.00	-
1	RADIATOR FAN ASSY	NOT NECESSARY	1,685.00	-
1	FRONT BRACE PANEL	BENT	115.00	92.00
2	FRONT LOCK CATCHS @\$250.00	O/S TWISTED	500.00	169.00
1	FRONT INNER GARNISH O/S	DEFORMED	82.30	82.30
2	FRONT FENDERS @\$1112.00	TO REPAIR SEE LABOUR	2,224.00	-
2	FRONT FENDER OUTER PROTECTORS @\$450.00	NECESSARY / TORN	900.00	644.00
	LESS 10% DISCOUNT		-	-2,978.58
			73,610.41	26,807.24
	<u>SPECIAL NETT ITEMS</u>			
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR WINDSCREEN INNER SEAL (SN)	NECESSARY	50.00	40.00
1	REAR LICENCE PLATE W/HOLDER (SN)	NOT NECESSARY	50.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	50.00	50.00
1	SET REAR FLOOR PANEL INSULATOR (SN)	NOT NECESSARY	220.00	-
1	FRONT LICENCE PLATE W/HOLDER (SN)	CRACKED	50.00	40.00
1	BOL RADIATOR COOLANT (SN)	NOT NECESSARY	80.00	-
			550.00	170.00
	<u>LABOUR</u>			
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPLACED PDC SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO TRANSFER TAILGATE MECHANISM.		120.00	80.00
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO SET & REPROGRAMME SYSTEM.		300.00	80.00
	TO SPRAY RUST PROOFING.		150.00	100.00

Report Ref No. CS/SMO20008004/Usf3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REFILL AIR CON GAS.		150.00	100.00
	LABOUR FOR PANEL BEATING & REPLACED PARTS.INCLUSIVE OF THE REPAIR OF REAR FLOOR PANEL,REAR FENDERS AND FRONT FENDER.		2,800.00	1,100.00
	TO PUTTY & SPRAY PAINTING.		2,600.00	1,400.00
			6,650.00	3,140.00
GRAND TOTAL			80,810.41	30,117.24
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				23,500.00

Report Ref No. CS/SMO20008004/Usf3n2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.