

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS20008005/UVF3E2

Date: 26/08/2020

REFERENCE

Handling Insurer: ECICS Limited

Policy No:

Claimant Vehicle

No : SGA9038U

Insured Vehicle No :

SFC3188K

Date of Loss: 01/08/2020

Nature of Claim:

TP

Claim No:

DMPC2000118H/NC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SGA9038U

Make & Model:

TOYOTA COROLLA ALTIS, 1.6 (A)

Engine No:

3ZZ4527312

Reg. Date:

01/12/2005 (Man. Year: 2005)

Chassis No:

MR053ZEC107105593

Colour:

Silver

Odometer:

607647 km

Engine Capacity:

1598 cc

Market Value/New Car Price: N/A

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

185/70 R14

Rear Tyre Size:

185/70 R14

Front Left Side:

Firemax 6 mm

Rear Left Side:

Firemax 6 mm

Front Right Side:

Firemax 6 mm

Rear Right Side:

Firemax 6 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 2,795.15 | 883.55 | 1,911.60 | 68.39 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 2,000.00 | 1,000.00 | 1,000.00 | 50.00 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 4,795.15 | 1,883.55 | 2,911.60 | 60.72 |
| Approved Total (Overridden) (S\$) | | 1,500.00 | | |
| Nett Amount (S\$) | 4,795.15 | 1,500.00 | 3,295.15 | 68.72 |

INSPECTION

Date of Assignment:

03/08/2020

Date Inspected:

04/08/2020

Inspected At:

Tony Automotive Pte Ltd (HQ)

8 Kaki Bukit Ave 4, #04-07 Premier

Singapore 415875

Estimated Period of Repair:

3.0 days

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|--|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 26 Aug 2020) |
| Parts: | 143 | TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SGA9038U) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|-------------------|------------|------------|
| 1 | 1 | | *REAR BUMPER | Dented / Deformed | 496.50 FL | *496.50 FL |
| 2 | 1 | | *REAR BUMPER LOWER | Deformed / Torn | 318.40 FL | *318.40 FL |
| 3 | 1 | | *REAR BUMPER SPONGE | No such part | 237.20 FL | *- FL |
| 4 | 2 | | *BRACKET, REAR BUMPER L/R | Not Necessary | 171.20 FL | *- FL |
| 5 | 1 | | *RETAINER, REAR BUMPER L/R | N/S Bent | 208.80 FL | *46.50 FL |
| 6 | 1 | | *SET REAR BUMPER CLIPS | Necessary | 50.00 FL | *50.00 FL |
| 7 | 1 | | *REAR REINFORCEMENT | No such part | 320.00 FL | *- FL |
| 8 | 1 | | *REAR INNER TRIM TOP BOARD | Not Necessary | 276.40 FL | *- FL |
| 9 | 1 | | *REAR END PANEL | Repair | 680.30 FL | *- FL |
| 10 | 1 | | *REAR END PANEL INNER TOP GARNISH | Not Necessary | 232.00 FL | *- FL |
| 11 | 1 | | *SET REAR END PANEL INNER TOP GARNISH CLIPS | Not Necessary | 50.00 FL | *- FL |
| 12 | 1 | | *SET REVERSE SENSORS | Shorted | 300.00 FS | *200.00 FS |
| 13 | 1 | | *REAR END PANEL SEALANT | Not Necessary | 80.00 FS | *- FS |
| 14 | 2 | | *REAR REINFORCEMENT BRACKETS | Not Necessary | 179.40 FL | *- FL |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|-----------------|-----------------|
| Sub Total (\$\$) | 3,600.20 | 1,111.40 |
| - List Item Discount on L Items 25.00/25.00% (\$\$) | 805.05 | 227.85 |
| Total Parts (\$\$) | 2,795.15 | 883.55 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|--------------------------------|----------|-----------------|-----------------|
| <u>Labour Items</u> | | | | |
| 1 | TUFFKOTE | New | 200.00 | 0.00 |
| 2 | TO PUTTY, SPRAY PAINT ETC | New | 1,000.00 | 600.00 |
| 3 | TO PANEL BEAT, WELD, ALIGN ETC | New | 800.00 | 400.00 |
| Gross Labour Cost (S\$) | | | 2,000.00 | 1,000.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >