

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRE SINGAPORE 239924

INV No. AC2005831

INV Date 26/08/2020

Reference CS/AGI20008022/Uvf3n2

Code AGI

PROFESSIONAL SERVICE FEE

Vehicle No. SLS 97D

Insured Veh. SMM 1380Z

Claim No. C10006909

Policy No.

Accident Date 01/08/2020

Inspection Date 04/08/2020

Description	Total
Survey Inspection	350.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	350.00
GST (7%)	24.50
Grand Total	374.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

HYN



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No: 199607198R GST Reg. No. 19-9607198-R						
	Affiliated to Federation Internationale Des Experts En Automobile						
AUTO	UTO & GENERAL INSURANCE (S) PL Ref : CS/AGI20008022/Uvf3n2						
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Date: 26-08-2020					
			Code: AGI				
1.	1	Policy Particulars	:- THIRD PARTY CLAIM				
	Insured Veh.	SMM 1380Z	Veh. Inspected	SLS 97D			
	Policy No.		Coverage (\$)	0.00			
	Claim No.	C10006909	Excess (\$)	0.00			
	Assign From	IVY RATILLA	Assign Date	04/08/2020			
2.		Vehicle Partic	culars & Condition				
	Make & Model	VOLVO V40 CROSS COUNTRY D2 (A)	c.c	1560			
	Engine No.	HIDDEN	Year of Reg.	2014			
	Chassis No.	YV1MZ845BF2067089	Colour	WHITE			
	Odometer	125727	Steering	IN ORDER			
	Brakes	IN ORDER	Modification	SPORTS RIM			
	General	GOOD					
3.		Condition	ons of Tyres				
		Size	Make	Balance			
	R/H Front Tyre	245/35 ZR19	ROADSTONE	6 mm			
	L/H Front Tyre	245/35 ZR19	ROADSTONE	6 mm			
	R/H Rear Tyre	245/35 ZR19	ROADSTONE	6 mm			
	L/H Rear Tyre	245/35 ZR19	ROADSTONE	6 mm			
4.		Description	on of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.						
	DAMAGES SEE D						
5.	T		Information				
	Accident Date	01/08/2020	Inspection Date	04/08/2020			
	Survey held at TONY AUTOMOTIVE PTE. LTD 8 KAKI BUKIT AVENUE 4 #04-07 PREMIER @ KAKI BUKIT SINGAPORE 415875						
				55.11 5112 110010			
5a.			emarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.						
5b.	b. Estimate Days of Repair						

3 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR:



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 97D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	DISTORTED	2,350.00	1,660.00
2	FRONT BUMPER LED FOG LAMP @\$720.00	O/S CRACKED	1,440.00	420.00
2	FRONT BUMPER LOWER CENTRE GARNISH @\$340.00	O/S GRAZED	680.00	340.00
1	FRONT BUMPER BOTTOM COVER GARNISH	NO SUCH PARTS	430.00	-
2	FRONT BUMPER SIDE RETAINER @\$95.00	NOT NECESSARY	190.00	-
2	FRONT BUMPER SIDE BRACKET @\$160.00	NOT NECESSARY	320.00	-
1	FRONT BUMPER TOW HOOK COVER	TORN	154.00	45.00
1	FRONT BUMPER REINFORCEMENT	BENT	860.00	860.00
1	FRONT BUMPER CENTRE FRAME	NOT NECESSARY	325.00	-
1	FRONT HEADLAMP RH	SCRATCHED / CRACKED	1,680.00	1,655.00
1	FRONT HEADLAMP LOWER BRACKET RH	NOT NECESSARY	150.00	-
	LESS 10% DISCOUNT		-857.90	-498.00
			7,721.10	4,482.00
	SPECIAL NETT ITEMS			
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	80.00	50.00
			80.00	50.00
	<u>LABOUR</u>			
	TUFFKOTE.	NOT NECESSARY	200.00	-
	TO PUTTY,SPRAY PAINT ETC.		1,200.00	400.00
	TO PANEL BEAT,WELD,ALIGN ETC.		1,000.00	400.00
			2,400.00	800.00
	GRAND TOTAL		10,201.10	5,332.00

RECOMMENDED COST OF LUMP SUM REPAIRS		4,250.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CS/AGI20008022/Uvf3n2

CHUA KANG SENG

Licensed Appraiser



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 97D

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315








51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 97D

RE-INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 97D

RE-INSPECTION









51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SLS 97D

RE-INSPECTION



