

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008023/KES3Q2
Date: 31/05/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100583104
Claimant Vehicle No :	GBG1420D	Insured Vehicle No :	SGA3983E
Date of Loss:	30/07/2020	Nature of Claim:	TP
		Claim No:	3548678822SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBG1420D		
Make & Model:	FIAT DOBLO CARGO MAXI, 1.6 D MTJ AMT GLAZE (M)	Engine No:	263A50007907900
Reg. Date:	14/06/2017 (Man. Year: 2017)	Chassis No:	ZFA26300006F25019
Colour:	Metallic Grey	Odometer:	54566 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/60R16	Rear Tyre Size:	195/60R16
Front Left Side:	Nexen 8 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Nexen 8 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,557.00	1,625.20	931.80	36.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,370.00	1,130.00	45.20
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,057.00	2,995.20	2,061.80	40.77
+ GST 7.00/7.00% (S\$)	353.99	209.66	144.33	40.77

Nett Amount (S\$)	5,410.99	3,204.86	2,206.13	40.77
		<hr/>		
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
		<hr/>		
Nett Liability (S\$)		3,506.86		
		<hr/>		

INSPECTION

Date of Assignment: 04/08/2020

Date Inspected: 04/08/2020

Estimated Period of Repair: 3.0 days

Inspected At: Goldbell Engineering Pte Ltd (Tuas)
10 Tuas Ave 18
Singapore 638894

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	875.00 F	*875.00 FL
2	1		*REAR BUMPER RETAINER LH	Serviceable	35.00 F	*- FL
3	1		*REAR BUMPER RETAINER RH	Serviceable	35.00 F	*- FL
4	1		*REAR BUMPER STEP	Buckled	175.00 F	*175.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	478.00 F	*478.00 FL
6	1		*REAR BUMPER END PANEL	Repair	579.00 F	*- FL
7	1		*REAR BUMPER TOW COVER	Serviceable	30.00 F	*- FL
8	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
9	1		*REVERSE SENSOR	Shorted	300.00 FS	*200.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$)	2,557.00
					- List Item Discount on L Items 0.00/10.00% (\$)	0.00
					Total Parts (\$)	1,778.00
						1,625.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REFIX & REPAIR AFFECTED DAMAGED PARTS,INCLUDING KNOCK OUT,WELD AND STRAIGHTEN ON THE AFFECTED PARTS	New	1,200.00	600.00
2	TO TRANSFER,CHECK,RECONNECT ALL NECESSARY WIRING SYSTEM AND FUNCTIONALLY	New	100.00	20.00
3	TO REMOVE AND REPLACE REVERSE SENSOR	New	150.00	50.00
4	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC	New	1,050.00	700.00
Gross Labour Cost (\$\$)			2,500.00	1,370.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >