

ASS. REC. BY:

REF:

A/G / 20008023/He

C

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03 days

Res.: Yes or No

Lum Sum:

1-B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

GBG1420D

Yr Regn:

06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Fiat Doblo

c.c.

1598

Colour

M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading

54566

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZFA26300006F25019

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Nexen 195/60R16

R: B.S.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal.

8

mm

Rear

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

30/7/20

D.O.I.

4/8/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/8 8 2995.20 Car frame

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

**Motorviva Pte Ltd**

A member of Goldbell Engineering

**MOTORVIVA PTE LTD**

Main Office: 8 Tuas Ave 18 Singapore 638892 Tel: 6665 2518

Finance: 8 Tuas Ave 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Showroom: 21 Toh Guan Road East #01-15 Toh Guan Centre Singapore 608609 Tel: 6665 2518 Fax: 6561 7956

Iveco: 8 Tuas Ave 18 Singapore 638892 Tel: 6863 6864 Fax: 6861 3676

Website: www.motorviva.com.sg

Co. Reg. No. 1995076142

Page 1 / 2

**ESTIMATE**

Date : 03/08/2020  
 To : AIG ASIA PACIFIC INSURANCE PTE.  
 LTD.

Attn. : *Not Authorised*  
 Office / Mobile : *64888888*  
 Email Address : *Personnel After Paint*  
*B4*

From : MOTORVIVA PTE LTD  
 Attn. : KONYINSIEW  
 Office / Mobile : +65 6861 0007  
 Email / Fax No. : KonYinSiew@goldbell.com.sg

Reg No : GBG1420D  
 Model : 263.216.1 (695 GREY METALLIC)  
 Chassis No : ZFA26300006F25019  
 Engine No : 263A50007907900  
 Quotation No. : 114873  
 Ref. No. : GBE/SVC/SALES-AMK31  
 D.O.A. : 30/07/2020  
 Policy No. : 20-MS006827-R01  
 Claim Type : TP CLAIM - AIG  
 Workshop : 8 TUAS AVE 18

| S/N | Part No | Description               | Qty | U/Price | % | Net Price | Ext Price |
|-----|---------|---------------------------|-----|---------|---|-----------|-----------|
| 1   |         | REAR BUMPER               | 1   | 875.00  | 0 | 875.00    | 875.00 ✓  |
| 2   |         | REAR BUMPER RETAINER LH   | 1   | 35.00   | 0 | 35.00     | 35.00 X   |
| 3   |         | REAR BUMPER RETAINER RH   | 1   | 35.00   | 0 | 35.00     | 35.00 X   |
| 4   |         | REAR BUMPER STEP          | 1   | 175.00  | 0 | 175.00    | 175.00 ✓  |
| 5   |         | REAR BUMPER REINFORCEMENT | 1   | 478.00  | 0 | 478.00    | 478.00 ✓  |
| 6   |         | REAR BUMPER END PANEL     | 1   | 579.00  | 0 | 579.00    | 579.00 X  |
| 7   |         | REAR BUMPER TOW COVER     | 1   | 30.00   | 0 | 30.00     | 30.00 X   |

PARTS TOTAL : *108* 2,207.00**SPECIAL NETT ITEMS**

|   |                         |   |  |
|---|-------------------------|---|--|
| 1 | REAR BUMPER CLIPS (SET) | 1 |  |
| 2 | REVERSE SENSOR          | 1 |  |

PARTS TOTAL: 350.00

**LABOUR CHARGES**

|   |                                                                                                                  |  |
|---|------------------------------------------------------------------------------------------------------------------|--|
| 1 | TO REMOVE, REFIX & REPAIR AFFECTED DAMAGED PARTS. INCLUDING KNOCK OUT, WELD AND STRAIGHTEN ON THE AFFECTED PARTS |  |
| 2 | TO TRANSFER, CHECK, RECONNECT ALL NECESSARY WIRING SYSTEM AND FUNCTIONALLY                                       |  |
| 3 | TO REMOVE AND REPLACE REVERSE SENSOR                                                                             |  |
| 4 | TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC                                                                     |  |

LABOUR TOTAL : 2,500.00

SUB-TOTAL : 5,057.00

GST @ 7% for \$ 5,057.00 353.99

**GRAND TOTAL (\$\$) :** 5,410.99

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

**IVECO**

## ESTIMATE

|                        |                                        |                      |                                 |
|------------------------|----------------------------------------|----------------------|---------------------------------|
| <b>Date</b>            | : 03/08/2020                           | <b>Reg No</b>        | : GBG1420D                      |
| <b>To</b>              | : AIG ASIA PACIFIC INSURANCE PTE. LTD. | <b>Model</b>         | : 263.216.1 (695 GREY METALLIC) |
| <b>Attn.</b>           | :                                      | <b>Chassis No</b>    | : ZFA26300006F25019             |
| <b>Office / Mobile</b> | :                                      | <b>Engine No</b>     | : 263A50007907900               |
| <b>Email Address</b>   | :                                      | <b>Quotation No.</b> | : 114873                        |
|                        |                                        | <b>Ref. No.</b>      | : GBE/SVC/SALES-AMK31           |
| <b>From</b>            | : MOTORVIVA PTE LTD                    | <b>D.O.A.</b>        | : 30/07/2020                    |
| <b>Attn.</b>           | : KONYINSIEW                           | <b>Policy No.</b>    | : 20-MS006827-R01               |
| <b>Office / Mobile</b> | : +65 6861 0007                        | <b>Claim Type</b>    | : TP CLAIM - AIG                |
| <b>Email / Fax No.</b> | : KonYinSiew@goldbell.com.sg           | <b>Workshop</b>      | : 8 TUAS AVE 18                 |

PREPARED BY : KONYINSIEW

DATE / TIME : \_\_\_\_\_

SURVEYOR : \_\_\_\_\_

MOBILE NO : \_\_\_\_\_

OFFICE FAX NO : \_\_\_\_\_

EMAIL ADDRESS : \_\_\_\_\_

EXCESS AMOUNT : \_\_\_\_\_

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED / NOT AUTHORISED

RE-SURVEY : BEFORE PAINT / AFTER PAINT

NO. OF DAYS : \_\_\_\_\_

REMARKS : \_\_\_\_\_