

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC3/AIG20008027/QRS3Q2

**Date:** 18/01/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993970

**Claimant**  
**Vehicle No :** SHB5717C **Insured Vehicle No :** SMP6621E

Date of Loss: 29/07/2020 Nature of Claim: TP Claim No: 4226964904SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHB5717C</b>		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS098118
Reg. Date:	12/10/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU303572967
Colour:	Maroon	Odometer:	403523 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Touring 6 mm	Rear Left Side:	Touring 6 mm
Front Right Side:	Touring 6 mm	Rear Right Side:	Touring 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,067.20	1,418.52	8,648.68	85.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,610.00	450.00	2,160.00	82.76
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>12,677.20</b>	<b>1,868.52</b>	<b>10,808.68</b>	<b>85.26</b>
<b>+ Loss of Use (4.0 x S\$50.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (4.0 x S\$111.82/day) (S\$)</b>		447.28		
<b>+ Doc/Search Fee (S\$)</b>		7.00		
<b>Nett Liability (S\$)</b>		<b>2,522.80</b>		

### INSPECTION

Date of Assignment: 30/07/2020

Date Inspected: 30/07/2020 Inspected At: SMRT Automotive Services Pte Ltd  
(Woodlands)  
60 Woodlands Industrial Park E4  
Singapore 757705

Estimated Period of Repair: 2.0 days

**Adjuster:** OI SUN PIN

**Manager:** Jaslin Kok Chin Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, FR BUMPER (DISC 25%)	Crushed	495.50 F	*371.63 F
2	1		*COVER, FR BUMPER RH (DISC 25%)	Scratched	28.10 F	*21.08 F
3	1		*CLIPS PIECE, FRT & RR BUMPER (DISC 25%) 10pcs	Necessary	15.00 F	*11.25 F
4	1		*SUPPORT, FR BUMPER RH (DISC 25%)	Broken	76.90 F	*57.68 F
5	1		*WIPER WASHER JAR (DISC 25%)	Cracked	183.60 F	*137.70 F
6	1		*LAMP ASSY, FOG RH (DISC 10%)	Cracked	910.20 F	*819.18 F
7	1		*SEAL, HOOD TO FR END	Serviceable	24.40 F	*- F
8	1		*SUPPORT, FR BUMPER RH	Serviceable	76.90 F	*- F
9	1		*ABSORBER, FR BUMPER	Serviceable	70.30 F	*- F
10	1		*REINFORCEMENT FRONT UPPER	Serviceable	691.10 F	*- F
11	1		*ABSORBER, FR BUMPER LOWER	Serviceable	117.00 F	*- F
12	1		*REINFORCEMENT FRONT LOWER	Serviceable	238.50 F	*- F
13	1		*EXTENSION SUBASSY, RH	Serviceable	116.30 F	*- F
14	1		*LAMP ASSY, FOG, RH	Serviceable	910.20 F	*- F
15	1		*GRILLE, RADIATOR	Serviceable	165.00 F	*- F
16	1		*COVER ASSY, ENGINE	Serviceable	180.10 F	*- F
17	1		*HOOD SUB-ASSY	Serviceable	938.40 F	*- F
18	1		*HINGE ASSY, HOOD, RH	Serviceable	57.00 F	*- F
19	1		*SUPPORT, RADIATOR UPPER RH	Serviceable	76.70 F	*- F
20	1		*UNIT, HEADLAMP, RH	Serviceable	2,558.90 F	*- F
21	1		*COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	Serviceable	486.40 F	*- F
22	1		*FENDER SUB-ASSY, FR, RH	Serviceable	933.10 F	*- F
23	1		*LINER, FR FENDER, RH	Serviceable	198.40 F	*- F
24	1		*EMBLEM, SIDE PANEL (HYBRID)	Serviceable	52.90 F	*- F
25	1		*WIPER WASHER JAR	Serviceable	183.60 F	*- F
26	1		*BRACE SUB-ASSY, FENDER APRON, RH	Serviceable	282.70 F	*- F

F=Franchise part.

**Total Parts (\$\$)**    **10,067.20**    **1,418.52**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	PANEL BEATING & BODYWORK.	New	676.00	200.00
2	SPRAY PAINT.	New	1,494.00	200.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	20.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	100.00	30.00
5	TO REMOVE AND REFIT WIRE HARDESS.	New	200.00	0.00
6	TO WASH AND VACUUM.	New	60.00	0.00
<b>Gross Labour Cost (\$)</b>			<b>2,610.00</b>	<b>450.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >