



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2102568

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 14/04/2021
Reference CC3/CTI20008028/Krs3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHF 557J
Insured Veh. GBD 209X
Claim No. SNM20D202681/LKKDS
Policy No. DMCVSN30722919000
Accident Date 29/07/2020
Inspection Date 03/08/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CC3/CTI20008028/Krs3q2 Date: 14/04/2021 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 209X		Veh. Inspected	SHF 557J
Policy No.	DMCVSN30722919000		Coverage (\$)	0.00
Claim No.	SNM20D202681/LKKDS		Excess (\$)	0.00
Assign From			Assign Date	03/08/2020
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)		c.c	1995
Engine No.	HIDDEN		Year of Reg.	2014
Chassis No.	VF1ABL15AUC278108		Colour	METALLIC WHITE / RED
Odometer	659617 KM		Steering	IN ORDER
Brakes	IN ORDER		Modification	NIL
General	GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/60 R16	SAILUN	9 mm
	L/H Front Tyre	215/60 R16	SAILUN	9 mm
	R/H Rear Tyre	215/60 R16	SAILUN	9 mm
	L/H Rear Tyre	215/60 R16	SAILUN	9 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	29/07/2020	Inspection Date	03/08/2020
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 557J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	DOOR PANEL FRT LH	BENT	2,844.66	2,844.66
1	DOOR REGULATOR FRT LH	DISTORTED	501.40	501.40
1	DOOR REGULATOR MOTOR FRT LH	JAMMED	758.10	758.10
1	DOOR REGULATOR GUIDE FRT LH	DISTORTED	69.00	69.00
1	DOOR WEATHERSTRIP FRT LH	SERVICEABLE	316.00	-
1	DOOR SEAL FRONT LH	SERVICEABLE	69.60	-
1	DOOR SEAL LOWER FRT LH	SERVICEABLE	93.90	-
1	DOOR SEAL FRT LH	NECESSARY	63.10	63.10
1	DOOR HINGE UPPER FRT LH	TO REPAIR SEE LABOUR	274.50	-
1	DOOR HINGE LOWER FRT LH	TO REPAIR SEE LABOUR	300.55	-
1	DOOR CHECK FRT LH	SERVICEABLE	90.90	-
1	DOOR LOCK FRT LH	DENTED	453.80	453.80
1	DOOR GLASS FRT LH	SHATTERED	394.00	394.00
1	DOOR MOULDING BLACK FRT LH	NECESSARY	100.50	100.50
1	DOOR FINISHER FRT LH	SERVICEABLE	258.90	-
1	DOOR FINISHER CLIP KIT FRT LH	NOT NECESSARY	94.00	-
1	DOOR CASING FRT LH	DISTORTED	1,509.06	1,509.06
1	DOOR GLASS RUBBER SEAL FRONT LH	SERVICEABLE	332.00	-
1	DOOR HANDLE OUTER FRONT LH	BROKEN	169.50	169.50
1	DOOR HANDLE CAP FRONT LH	MISSING	17.30	17.30
1	DOOR HANDLE SEAL FRT LH	NECESSARY	1.60	1.60
1	DOOR HANDLE COVER FRT LH	NECESSARY	6.10	6.10
1	DOOR HANDLE MODULE FRT LH L70Y	SERVICEABLE	133.40	-
1	DOOR WAIST SEAL OUTER FRT LH (DOOR CHROME)	BENT	92.20	92.20
1	DOOR WAIST SEAL INNER FRT LH	SERVICEABLE	86.30	-
1	DOOR MIRROR ASSY LH	BROKEN	1,483.40	1,483.40
1	DOOR MIRROR GLASS LH	NOT NECESSARY	151.70	-
1	DOOR MIRROR BACK COVER FRT LH	NOT NECESSARY	128.70	-
1	DOOR MIRROR LAMP LH	NOT NECESSARY	134.10	-

Report Ref No. CC3/CTI20008028/Krs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR FINISHER INNER FRT LH	SERVICEABLE	197.10	-
1	DOOR FINISHER BRACKET INNER FRT LH	SERVICEABLE	31.90	-
1	DOOR HARNESS WIRE LH	SERVICEABLE	2,670.00	-
1	DOOR HINGE OUTER PILLAR PANEL FRT LH	TO REPAIR SEE LABOUR	2,896.14	-
1	DOOR HINGE INNER PILLAR PANEL FRT LH	TO REPAIR SEE LABOUR	1,542.15	-
1	VEHICLE HARNESS PASS ROOM	SERVICEABLE	2,170.90	-
1	ROCKER PANEL INNER GARNISH LH	SERVICEABLE	466.51	-
1	ROCKER PANEL OUTER LH	TO REPAIR SEE LABOUR	1,184.99	-
1	DOOR PANEL REAR LH	BENT	2,844.66	2,844.66
1	DOOR HINGE UPPER REAR LH L70Y	TO REPAIR SEE LABOUR	241.60	-
1	DOOR HINGE LOWER REAR LH L70Y	TO REPAIR SEE LABOUR	169.90	-
1	DOOR CHECK REAR LH	SERVICEABLE	114.90	-
1	DOOR REGULATOR REAR LH L70Y	SERVICEABLE	450.60	-
1	DOOR REGULATOR MOTOR REAR LH L70Y	SERVICEABLE	657.10	-
1	DOOR GLASS RUBBER SEAL REAR LH	SERVICEABLE	320.90	-
1	DOOR MOULDING BLACK REAR LH	NECESSARY	100.50	100.50
1	DOOR WAIST SEAL OUTER REAR LH	SERVICEABLE	169.60	-
1	CENTRE PILLAR OUTER	TO REPAIR SEE LABOUR	880.14	-
1	CENTRE PILLAR INNER	TO REPAIR SEE LABOUR	907.76	-
1	CENTRE PILLAR REINFORCEMENT	TO REPAIR SEE LABOUR	1,176.15	-
1	CENTRE PILLAR INNER GARNISH -TOP	SERVICEABLE	168.82	-
1	CENTRE PILLAR INNER GARNISH -LOWER	SERVICEABLE	365.99	-
1	FENDER PANEL FRT LH	TO REPAIR SEE LABOUR	437.10	-
1	WHEELARCH FRT LH	SERVICEABLE	191.40	-
	LESS 10% DISCOUNT		-3,128.51	-1,140.89
			28,156.57	10,267.99

Report Ref No. CC3/CTI20008028/Krs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	DOOR WEATHERSTRIP REAR LH (50%) (SN)	CUT	311.60	155.80
	LESS 10% DISCOUNT		-31.16	-
			280.44	155.80
	<u>SPECIAL NETT ITEMS</u>			
1	FRONT DOOR STICKER 'TRANS-CAB' (SN)	NECESSARY	80.00	60.00
1	FRONT DOOR STICKER 'CLASSIC' (SN)	NECESSARY	80.00	15.00
1	REAR DOOR STICKER '6555-3333' (SN)	NECESSARY	100.00	60.00
1	LH SIDE RENAULT TYRE 215/60/16 (SN)	SERVICEABLE	330.00	-
1	LH SIDE RENAULT TYRE RIM (SN)	SERVICEABLE	380.00	-
1	FRONT WINDSCREEN MOULDING (SN)	SERVICEABLE	200.00	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	150.00	-
1	FRONT WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	130.00	-
1	DOOR CHECK BOLT (SN)	SERVICEABLE	45.00	-
1	DOOR CHECK NUT (SN)	SERVICEABLE	45.00	-
1	DOOR GUIDE SCREW (SN)	SERVICEABLE	45.00	-
1	DOOR HINGE BOLT (SN)	SERVICEABLE	45.00	-
1	DOOR HINGE NUT LH (SN)	SERVICEABLE	45.00	-
1	DOOR LOCK SCREW (SN)	SERVICEABLE	45.00	-
1	DOOR SEAL CLIP LH (SN)	NOT NECESSARY	55.00	-
1	DOOR MOULDING CLIP (SN)	NOT NECESSARY	55.00	-
1	ROCKER PANEL CLIP (SN)	NOT NECESSARY	65.00	-
1	DOOR CASING CLIP (SN)	NOT NECESSARY	55.00	-
2	SEAM SEALANT (SN)	NOT NECESSARY	200.00	-
1	WHEELARCH CLIP FRT LH (SN)	NOT NECESSARY	65.00	-
			2,215.00	135.00
	<u>LABOUR</u>			
	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR.		380.00	60.00

Report Ref No. CC3/CTI20008028/Krs3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER FRT LH,DOOR HINGE LOWER FRT LH,DOOR HINGE OUTER PILLAR PANEL FRT LH,DOOR HINGE INNER PILLAR PANEL FRT LH,ROCKER PANEL OUTER LH,DOOR HINGE UPPER REAR LH L70Y,DOOR HINGE LOWER REAR LH L70Y,CENTRE PILLAR OUTER,CENTER PILLAR INNER,CENTER PILLAR REINFORCEMENT AND FENDER PANEL FRT LH.		3,000.00	500.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		3,000.00	660.00
	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO CHECK STEERING GEOMETRY AND COMPUTERWHEEL ALIGNMENT .	NOT NECESSARY	220.00	-
	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR .	NOT NECESSARY	380.00	-
	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR .	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED .		170.00	20.00
	TO PULL AND JACK OUT BODY PILLAR AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK.	NOT NECESSARY	440.00	-
	TOWING FEES.		150.00	50.00
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		250.00	60.00
			8,670.00	1,470.00
GRAND TOTAL			39,322.01	12,028.79

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			8,100.00
---	--	--	-----------------

Report Ref No. CC3/CT120008028/Krs3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 557J

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R



