

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20008029/AQF3Q2

Date: 30/10/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00044532000	
Claimant Vehicle No : SGW6777Z	Insured Vehicle No : GBB4399P	
Date of Loss: 01/08/2020	Nature of Claim: TP	Claim No: SNM20D202707/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGW6777Z		
Make & Model:	TOYOTA COROLLA AXIO, 1.5 (A)	Engine No:	1NZC641372
Reg. Date:	26/07/2007 (Man. Year: 2007)	Chassis No:	NZE1416038743
Colour:	Grey	Odometer:	0 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/70 R14	Rear Tyre Size:	185/70 R14
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,353.25	5,311.70	8,041.55	60.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	2,630.00	2,370.00	47.40
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,353.25	7,941.70	10,411.55	56.73
Approved Total (Overridden) (S\$)		5,000.00		
(S\$)	18,353.25	5,000.00	13,353.25	72.76
+ GST 7.00/7.00% (S\$)	1,284.73	350.00	934.73	72.76
Nett Amount (S\$)	19,637.98	5,350.00	14,287.98	72.76

INSPECTION

Date of Assignment:	04/08/2020	
Date Inspected:	04/08/2020	Inspected At: Sk Automobile Hub - Kaki Bukit (HQ) 23 KAKI BUKIT AVE 4, #03-01 Singapore 415933
Estimated Period of Repair:	9.0 days	

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 30 Oct 2020)
Parts:	143	TOYOTA COROLLA AXIO 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGW6777Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT DOOR LH	Distorted	1,100.90 FL	*1,100.90 FL
2	1	*FRONT DOOR SIDE MIRROR LH	Cracked	1,215.60 FL	*972.00 FL
3	1	*FRONT DOOR SIDE MIRROR COVER LH	Repair	65.70 FL	*- FL
4	1	*FRONT DOOR HINGE UPPER & LOWER LH	Lower Bent	171.00 FL	*85.50 FL
5	1	*FRONT DOOR MECHANISM LOCK LH	Not Necessary	560.80 FL	*- FL
6	1	*FRONT DOOR WEATHER STRIP LH	Not Necessary	177.40 FL	*- FL
7	1	*FRONT BONNET	Dented	897.60 FL	*897.60 FL
8	2	*FRONT BONNET HINGE LH/RH	Not Necessary	121.00 FL	*- FL
9	4	*FRONT BONNET RUBBER GUIDE STOPPER	Not Necessary	76.80 FL	*- FL
10	1	*FRONT BONNET WEATHERSTRIP	Not Necessary	46.70 FL	*- FL
11	1	*FRONT BONNET MECHANISM LOCK	Not Necessary	118.40 FL	*- FL
12	1	*FRONT GRILLE	Cracked	360.80 FL	*360.80 FL
13	1	*FRONT GRILLE LOGO EMBLEM	Necessary	75.70 FL	*75.70 FL
14	2	*FRONT GRILLE SCREW STOPPER	Not Necessary	59.20 FL	*- FL
15	1	*FRONT HEADLAMP LH/RH	N/s Smashed	1,791.80 FL	*785.00 FL
16	1	*FRONT FENDER LH	Distorted	733.20 FL	*606.00 FL
17	1	*FRONT FENDER SIGNAL LAMP LH	Missing	98.10 FL	*98.10 FL
18	1	*FRONT FENDER INNER SHIELD LH	Deformed	197.90 FL	*197.90 FL
19	1	*FRONT FENDER INNER SHIELD VERTICAL LH	Not Necessary	78.60 FL	*- FL
20	1	*FRONT FENDER INNER PANEL LH	Repair	1,535.10 FL	*- FL
21	1	*FRONT FENDER BRACKET LH	Bent	84.60 FL	*84.60 FL
22	1	*FRONT FENDER QUARTER GARNISH LH	Missing	77.90 FL	*77.90 FL
23	1	*FRONT BUMPER	Distorted	465.50 FL	*465.50 FL
24	1	*FRONT BUMPER SIDE RETAINER LH/RH	O/s Damaged	110.60 FL	*55.30 FL
25	1	*FRONT SUPPORT PANEL	Repair	876.80 FL	*- FL
26	1	*FRONT BRACE PANEL	Not Necessary	234.70 FL	*- FL
27	1	*FRONT WHEEL HOUSE PANEL LH	Repair	550.50 FL	*- FL
28	1	*FUSE BOX COVER TOP	Cracked	110.70 FL	*110.70 FL
29	1	*FUSE BOX COVER CENTER	Cracked	590.40 FL	*590.40 FL
30	1	*FUSE BOX COVER CLOWER	Cracked	100.80 FL	*100.80 FL
31	1	*AIR CLEANER BOX	Not Necessary	780.50 FL	*- FL
32	1	*AIR DUCT	Not Necessary	50.10 FL	*- FL
33	1	*AIR DUCT HOSE	Deformed	105.60 FL	*105.60 FL
34	1	*BATTERY TOP BRACKET	Bent	45.30 FL	*45.30 FL
35	1	*BATTERY LOWER COVER	Not Necessary	70.80 FL	*- FL
36	1	*ENGINE CONTROL UNIT	Not Necessary	3,045.70 FL	*- FL
37	1	*FRONT DOOR CLIPS SET LH	Not Necessary	80.00 FS	*- FS
38	1	*SET FRONT GRILLE CLIPS	Necessary	40.00 FS	*30.00 FS
39	2	*FRONT HEADLAMP CLIPS SET LH/RH	Necessary	80.00 FS	*10.00 FS
40	1	*FRONT FENDER INNER SHIELD CLIPS SET LH	Necessary	60.00 FS	*30.00 FS
41	1	*FRONT FENDER INNER PANEL SEALANT LH	Not Necessary	50.00 FS	*- FS
42	1	*FRONT FENDER QUARTER GARNISH CLIPS SET LH	Necessary	30.00 FS	*10.00 FS
43	1	*SET FRONT BUMPER CLIPS	Necessary	65.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
44	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	40.00 FS	*- FS
45	1		*FRONT WHEEL HOUSE PANEL SEALANT LH	Not Necessary	100.00 FS	*- FS
46	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
47	1		*FRONT DOOR BLACK FRAME STICKER SET LH	Necessary	141.15 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	17,548.95	7,015.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,195.70	1,703.90

Total Parts (\$\$)	13,353.25	5,311.70
---------------------------	------------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	2,000.00	1,200.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,800.00	1,200.00
3	TO APPLY ANTI RUST & TUFF KOTE	New	140.00	80.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	New	280.00	0.00
6	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE COMPONENT LH TO PERFORM FACILITATE REPAIRS	New	280.00	0.00
7	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	0.00
8	TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	New	120.00	60.00
9	TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	New	120.00	60.00
10	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
Gross Labour Cost (\$)			5,000.00	2,630.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >