

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CTI20008030/ASF3Q2

**Date:** 04/11/2020

### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSNA00044532000	
Claimant Vehicle No : SJC2045Z	Insured Vehicle No : GBB4399P	
Date of Loss: 01/08/2020	Nature of Claim: TP	Claim No: SNM20D202707/C03

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJC2045Z		
Make & Model:	TOYOTA ESTIMA, 2.4 (A)	Engine No:	2AZF090990
Reg. Date:	01/02/2008 (Man. Year: 2007)	Chassis No:	ACR500053904
Colour:	White	Odometer:	152036 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,565.30	3,176.80	3,388.50	51.61
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,120.00	1,410.00	2,710.00	65.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>10,685.30</b>	<b>4,586.80</b>	<b>6,098.50</b>	<b>57.07</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>3,650.00</b>		
<b>(\$\$)</b>	10,685.30	3,650.00	7,035.30	65.84
<b>+ GST 7.00/7.00% (\$\$)</b>	747.97	255.50	492.47	65.84
<b>Nett Amount (\$\$)</b>	<b>11,433.27</b>	<b>3,905.50</b>	<b>7,527.77</b>	<b>65.84</b>

### INSPECTION

Date of Assignment:	04/08/2020	
Date Inspected:	04/08/2020 Inspected At:	Sk Automobile Hub - Kaki Bukit (HQ) 23 KAKI BUKIT AVE 4, #03-01 Singapore 415933
Estimated Period of Repair:	4.0 days	

**Adjuster:** ADRIAN LING

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 04 Nov 2020)
<b>Parts:</b>	M1-MPV	TOYOTA ESTIMA 2.4 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJC2045Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*FRONT WIPER GARNISH RH	Deformed	25.60 FL	*25.60 FL
2	1	*FRONT FENDER RH	Dented	685.90 FL	*685.90 FL
3	1	*FRONT FENDER LOWER GARNISH RH	Not Necessary	78.50 FL	*- FL
4	1	*FRONT FENDER INNER SHIELD RH	Torn	270.70 FL	*270.70 FL
5	1	*FRONT FENDER BRACKET RH	Bent	56.40 FL	*56.40 FL
6	1	*FRONT HEADLAMP RH	Cracked	1,000.90 FL	*1,000.90 FL
7	1	*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	44.50 FL	*- FL
8	1	*FRONT GRILLE	Cracked	435.10 FL	*389.00 FL
9	1	*FRONT GRILLE LOGO EMBLEM	Necessary	75.20 FL	*75.20 FL
10	1	*FRONT BUMPER	Deformed	545.90 FL	*545.90 FL
11	1	*FRONT BUMPER FOG LAMP RH	Cracked	425.70 FL	*269.70 FL
12	1	*FRONT BUMPER FOG LAMP GARNISH RH	Deformed	100.50 FL	*100.50 FL
13	1	*FRONT BUMPER LOWER CENTER GRILLE	Not Necessary	120.30 FL	*- FL
14	1	*FRONT BUMPER TOW HOOK COVER RH	Not Necessary	22.10 FL	*- FL
15	1	*FRONT BUMPER LOWER UNDER COVER RH	Not Necessary	223.70 FL	*- FL
16	1	*FRONT BUMPER SIDE RETAINER LH/RH	O/s Damaged	190.60 FL	*95.30 FL
17	1	*FRONT BUMPER TOP BEAM	Not Necessary	138.90 FL	*- FL
18	1	*FRONT BUMPER INNER SPONGE	Not Necessary	80.50 FL	*- FL
19	1	*FRONT BUMPER REINFORCEMENT	Bent	410.70 FL	*410.70 FL
20	1	*WASHER TANK	Deformed	176.60 FL	*176.60 FL
21	1	*FRONT SUSPENSION SHOCK ABSORBER RH	Not Necessary	500.90 FL	*- FL
22	1	*FRONT SUSPENSION KNUCKLE ARM RH	Not Necessary	585.70 FL	*- FL
23	1	*FRONT SUSPENSION KNUCKLE ARM BEARING RH	Not Necessary	579.40 FL	*- FL
24	1	*FRONT SUSPENSION LOWER ARM RH	Not Necessary	815.10 FL	*- FL
25	1	*FRONT SUSPENSION LOWER BALL JOINT RH	Not Necessary	225.30 FL	*- FL
26	1	*FRONT SUSPENSION STABILISER BAR LINK RH	Not Necessary	165.70 FL	*- FL
27	1	*FRONT WIPER GARNISH CLIPS SET RH	Not Necessary	20.00 FS	*- FS
28	1	*FRONT FENDER LOWER GARNISH CLIPS SET RH	Not Necessary	20.00 FS	*- FS
29	1	*FRONT FENDER INNER SHIELD CLIPS SET RH	Necessary	60.00 FS	*30.00 FS
30	1	*FRONT HEADLAMP CLIPS SET RH	Necessary	20.00 FS	*20.00 FS
31	1	*SET FRONT GRILLE CLIPS	Necessary	40.00 FS	*20.00 FS
32	1	*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
33	1	*SET FRONT BUMPER PARKING SENSOR	Not Necessary	280.00 FS	*- FS
34	1	*SET FRONT BUMPER LOWER UNDER COVER CLIPS	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>8,560.40</b>	<b>4,202.40</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,995.10	1,025.60
<b>Total Parts (\$\$)</b>	<b>6,565.30</b>	<b>3,176.80</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	New	1,800.00	600.00
2	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	New	1,600.00	600.00
3	TO APPLY ANTI-RUST & TUFF KOTE	New	100.00	60.00
4	TO PERFORM LIGHTING & WIRING CHECK	New	80.00	30.00
5	TO DISMANTLE & REPLACED FRONT BUMPER REVERSE SENSOR WITH DISTANCE SETTING	New	80.00	40.00
6	TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE COMPONENT RH TO PERFORM FACILITATE REPAIRS	New	280.00	0.00
7	TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	New	100.00	80.00
8	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	New	80.00	0.00
<b>Gross Labour Cost (S\$)</b>			<b>4,120.00</b>	<b>1,410.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >