



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV No. AC2006853
INV Date 06/10/2020
Reference CC6/FCI20008031/Uds3q2
Code FCI2



PROFESSIONAL SERVICE FEE

Vehicle No. SGW 2770T
Insured Veh. SH 9490S
Claim No. D20003060MFSH/1
Policy No. D-20094922MFSH
Accident Date 31/07/2020
Inspection Date 04/08/2020

Description	Total
Third Party Express Settlement	500.00
Subtotal	500.00
GST (7%)	35.00
Grand Total	535.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref : CC6/FCI20008031/Uds3q2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-10-2020	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 9490S	Veh. Inspected	SGW 2770T	
Policy No.	D-20094922MFSH	Coverage (\$)	0.00	
Claim No.	D20003060MFSH/1	Excess (\$)	0.00	
Assign From	VIC	Assign Date	04/08/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA AIRWAVE (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2007	
Chassis No.	GJ11114418	Colour	BLACK	
Odometer	226943	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	175/65 R14	YOKOHAMA	6 mm	
L/H Front Tyre	175/65 R14	YOKOHAMA	6 mm	
R/H Rear Tyre	175/65 R14	YOKOHAMA	6 mm	
L/H Rear Tyre	175/65 R14	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	31/07/2020	Inspection Date	04/08/2020	
Survey held at	QUAN DE MOTOR TRADING BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGW 2770T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	BONNET	BUCKLED	816.90	816.90
1	BONNET CHROME MOULDING	SCRATCHED	285.60	285.60
2	BONNET HINGES @\$65.00	TO REPAIR SEE LABOUR	130.00	-
1	BONNET INSULATOR	DISTORTED	142.50	142.50
1	FRONT GRILLE	BROKEN	240.50	240.50
1	FRONT GRILLE BASE	BROKEN	190.60	190.60
1	FRONT GRILLE LOGO	MISSING	38.00	38.00
1	FRONT SUPPORT PANEL	DISTORTED	665.60	665.60
1	HEADLAMP LH	BROKEN	868.00	868.00
1	HEADLAMP LOWER BRACKET LH	CRACKED	65.00	65.00
1	FRONT BUMPER	DISTORTED	981.00	981.00
1	FRONT BUMPER CENTER GRILLE	TORN	142.50	142.50
1	FRONT BUMPER REINFORCEMENT	DISTORTED	280.90	280.90
1	FRONT BUMPER SIDE RETAINER LH	BENT	32.00	32.00
1	FRONT FENDER LH	BUCKLED	661.20	661.20
1	FRONT FENDER WHEEL HOUSING LH	TO REPAIR SEE LABOUR	756.60	-
1	FRONT LOCK	TWISTED	91.80	91.80
1	AIR-CON CONDENSER	DISTORTED	1,056.00	1,056.00
1	RADIATOR	HOLDER CRACKED	1,422.30	1,422.30
1	RADIATOR FAN MOTOR ASSY	CRACKED / JAMMED	525.20	525.20
1	FRONT DOOR LH	TO REPAIR SEE LABOUR	922.30	-
	LESS 20% DISCOUNT		-2,062.90	-1,701.12
			8,251.60	6,804.48
<u>SPECIAL NETT ITEMS</u>				
1	FRONT LICENSE PLATE (SN)	BROKEN	50.00	40.00
			50.00	40.00

Report Ref No. CC6/FCI20008031/Uds3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>LABOUR</u>			
	TOWING.		60.00	50.00
	TO CHECK WIRING.		100.00	30.00
	TO REMOVE & REFIX AIR-CON & REFILL GAS.		120.00	100.00
	TO SPRAY RUST PROOFING.		200.00	90.00
	LABOUR FOR PANEL BEATING,WELDING & RENEW PARTS.INCLUSIVE OF THE REPAIR OF BONNET HINGES,FRONT FENDER WHEEL HOUSING LH AND FRONT DOOR LH.		1,300.00	1,000.00
	SPRAY PAINTING.		1,250.00	1,000.00
			3,030.00	2,270.00
	GRAND TOTAL		11,331.60	9,114.48
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			4,650.00

Report Ref No. CC6/FCI20008031/Uds3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGW 2770T

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGW 2770T

RE-INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SGW 2770T

RE-INSPECTION

