

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III20008035/KGS3Q2

**Date:** 24/11/2020

#### REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0003256
<b>Claimant Vehicle No :</b>	SHD9410A	<b>Insured Vehicle No :</b>	PA9791X
Date of Loss:	02/08/2020	Nature of Claim:	TP
		Claim No:	MFL2020D0001465

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SHD9410A</b>	Engine No:	2ZR2C25055
Make & Model:	TOYOTA PRIUS, 1.8 (A)	Chassis No:	JTDKB3FU503081140
Reg. Date:	18/06/2019 (Man. Year: 2018)	Odometer:	126538 km
Colour:	Metallic Pearl White/Red		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 8 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 8 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,050.42	6,532.82	11,517.60	63.81
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,820.00	1,350.00	7,470.00	84.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>26,870.42</b>	<b>7,882.82</b>	<b>18,987.60</b>	<b>70.66</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,880.93</b>	<b>551.80</b>	<b>1,329.13</b>	<b>70.66</b>
<b>Nett Amount (S\$)</b>	<b>28,751.35</b>	<b>8,434.62</b>	<b>20,316.73</b>	<b>70.66</b>
<b>+ Loss of Use (5.0 x S\$40.00/day) (S\$)</b>		200.00		
<b>+ Car Rental (5.0 x S\$96.30/day) (S\$)</b>		481.50		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>9,123.57</b>		
<b>Global Sum Settlement (S\$)</b>		<b>9,100.00</b>		

#### INSPECTION

Date of Assignment:	04/08/2020	
Date Inspected:	05/08/2020	Inspected At: Trans-cab Auto Services Pte Ltd (Ang Mo Kio) 2, Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	3.0 days	

---

**Adjuster:** KENNETH KONG

**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2020)
<b>Parts:</b> 144	TOYOTA PRIUS 1.8 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SHD9410A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	516.00 FL	*516.00 FL
2	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Serviceable	103.40 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	80.10 FL	*80.10 FL
4	1		*REINFORCEMENT ,FRONT BUMPER	Repair	716.60 FL	*- FL
5	1		*REINFORCEMENT ,FRONT BUMPER ,NO.2	Repair	246.10 FL	*- FL
6	1		*ABSORBER ,FRONT BUMPER ,LOWER	Serviceable	132.70 FL	*- FL
7	1		*ABSORBER ,FRONT BUMPER ,ENERGY	Serviceable	79.60 FL	*- FL
8	1		*COVER ,FRONT BUMPER HOLE ,RH	Serviceable	29.30 FL	*- FL
9	1		*COVER SUN-ASSY ,ENGINE UNDER ,NO.2	Serviceable	241.90 FL	*- FL
10	1		*COVER ,ENGINE UNDER ,NO.1	Serviceable	472.40 FL	*- FL
11	1		*EXTENSION ,FRONT BUMPER ,RH	Serviceable	120.10 FL	*- FL
12	1		*FRONT LED LAMP (LOWER)RH	Serviceable	951.40 FL	*- FL
13	1		*FRONT HEADLAMP RH	Cracked	2,637.60 FL	*2,637.60 FL
14	1		*COMPUTER SUB-ASSY ,HEADLAMP ,RH NO.1	Serviceable	960.50 FL	*- FL
15	1		*MOTOR ,HEADLAMP LEVELING ,RH	Serviceable	487.50 FL	*- FL
16	1		*FRONT FENDER RH	Bent	977.80 FL	*977.80 FL
17	1		*LINER ,FRONT FENDER ,RH	Distorted	206.70 FL	*206.70 FL
18	1		*FRONT FENDER EMBLEM RH	Not Necessary	54.60 FL	*- FL
19	1		*COVER SUB-ASSY ,FRONT PILLAR ,UPR RH	Serviceable	100.40 FL	*- FL
20	1		*FRONT BONNET	Repair	983.10 FL	*- FL
21	1		*HINGE ASSY ,HOOD,RH	Repair	58.90 FL	*- FL
22	1		*GRILLE SUB-ASSY ,RADIATOR	Serviceable	346.00 FL	*- FL
23	1		*GRILLE, RADIATOR ,LOWER NO.1	Serviceable	170.10 FL	*- FL
24	1		*EMBLEM ASSY ,RADIATOR GRILLE	Serviceable	90.80 FL	*- FL
25	1		*JAR ASSY ,WINDSHIELD WASHER	Serviceable	219.10 FL	*- FL
26	1		*INLET SUB ASSY ,WASHER	Serviceable	67.00 FL	*- FL
27	1		*MOTOR AND PUMP ASSY ,WINDSHIELD WASHER	Serviceable	292.40 FL	*- FL
28	1		*MOULDING ASS ,BODY ROCKER PANEL ,RH	Serviceable	594.80 FL	*- FL
29	1		*PANEL SUB-ASSY ,FRONT DOOR ,RH	Repair	1,300.70 FL	*- FL
30	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Repair	97.50 FL	*- FL
31	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	110.60 FL	*- FL
32	1		*CHECK ASSY ,FRONT DOOR	Serviceable	183.80 FL	*- FL
33	1		*RIGHT SIDE VIEW MIRROR	Broken	1,436.60 FL	*1,436.60 FL
34	1		*TAPE ,BLACK OUT ,NO.1 FRT RH	Necessary	13.30 FL	*13.30 FL
35	1		*TAPE ,BLACK OUT ,NO.2 FRT RH	Necessary	43.50 FL	*43.50 FL
36	1		*TAPE ,BLACK OUT ,NO.3 FRT RH	Necessary	26.30 FL	*26.30 FL
37	1		*WIRE ,FRONT DOOR ,RH	Serviceable	532.80 FL	*- FL
38	1		*PILLAR FRONT BODY ,UPPER OUTER RH	Serviceable	381.60 FL	*- FL
39	1		*SUPPORT ,RADIATOR ,UPPER RH	Serviceable	78.90 FL	*- FL
40	1		*HUB SUB-ASSY ,FRONT AXLE ,RH	Serviceable	668.90 FL	*- FL
41	1		*ARM SUB-ASSY FRONT SUSPENSION ,LOWER NO.1 RH	Serviceable	760.10 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*KNUCKLE STEERING ,RH	Serviceable	663.40 FL	*- FL
43	1		*ABSORBER ASSY ,SHOCK ,FRONT RH	Serviceable	438.30 FL	*- FL
44	1		*SHAFT ASSY ,FRONT DRIVE ,RH	Repair	1,379.50 FL	*- FL
45	1		*FRONT WHEEL RIM	Dented	1,879.40 FS	*1,879.40 FS
46	1		*FRONT WHEEL RIM COVER	Serviceable	211.50 FS	*- FS
47	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
48	1		*SET CLIP ,FRONT FENDER LINER	Necessary	65.00 FS	*65.00 FS
49	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
50	1		*SET BUMPER CLIP FRT	Necessary	75.00 FS	*75.00 FS
51	1		*SET FRONT BUMPER RETAINER CLIP	Not Necessary	65.00 FS	*- FS
52	1		*SET ROCKER PANEL MOULDING CLIP	Not Necessary	65.00 FS	*- FS
53	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	100.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$)</b>	<b>23,063.60</b>	<b>8,017.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$)</b>	5,013.18	1,484.48
<b>Total Parts (\$)</b>	<b>18,050.42</b>	<b>6,532.82</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,800.00	500.00
2	TO TRANSFER OF FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
4	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
5	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
6	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	60.00
7	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	20.00
8	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	2,800.00	720.00
9	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
10	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	250.00	30.00
11	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
12	TO PULL AND JACK OUT BODY PILLAR AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
13	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
14	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>8,820.00</b>	<b>1,350.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >