LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Adeline Chng Pei Wen Date: 31 Aug 2020

Preliminary Advice

Insured Vehicle No : SJL5004A

TP Vehicle No : GBB7053S Accident Date : 01/08/2020

Make : TOYOTA HIACE Assignment Date : 04/08/2020

Date of Inspection : 05/08/2020 Est. Duration of Repair : 3 days

Inspection At : Precise Auto Services (HQ)

NO.1 KAKI BUKIT AVE 6 #02-34/36

Singapore 417883

Point of Impact / General Description of Damages

The vehicle sustained impact / damages at the front o/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,253.84	
Repairer's Estimate (Gross)	.Эф	2,255.04	
Revised Amount	:S\$	1,522.41	
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	1,522.41	
Lump Sum Repair	:S\$	1,200.00	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
()	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: TP: WP