

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20008037/UGA3Q2
Date: 10/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100422958
Claimant Vehicle No :	SMJ7569Z	Insured Vehicle No :	SKU4952K
Date of Loss:	03/08/2020	Nature of Claim:	TP
		Claim No:	3347898321SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ7569Z	Engine No:	L15B5563339
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU11313327
Reg. Date:	19/03/2019 (Man. Year: 2018)	Odometer:	26487 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60R16	Rear Tyre Size:	215/60R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,801.70	5,714.16	12,087.54	67.90
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,780.00	2,050.00	2,730.00	57.11
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,581.70	7,764.16	14,817.54	65.62
Approved Total (Overridden) (S\$)		6,200.00		
(S\$)	22,581.70	6,200.00	16,381.70	72.54
+ GST 7.00/7.00% (S\$)	1,580.72	434.00	1,146.72	72.54
Nett Amount (S\$)	24,162.42	6,634.00	17,528.42	72.54
+ Car Rental (3.0 x S\$100.00/day) (S\$)		300.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,936.00		

INSPECTION

Date of Assignment:	04/08/2020	Inspected At:	Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Date Inspected:	04/08/2020		
Estimated Period of Repair:	5.0 days		

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN MOULDING	Necessary	88.20 F	*88.20 FL
2	1		*REAR WINDSCREEN	Not Necessary	1,650.00 F	*- FL
3	1		*TAILGATE	Badly Dented	1,100.90 F	*953.00 FL
4	1		*TAILGATE OUTER GARNISH	Not Necessary	315.20 F	*- FL
5	1		*TAILGATE H LOGO	Not Necessary	32.50 F	*- FL
6	1		*TAILGATE VEZEL EMBLEM	Necessary	56.50 F	*56.50 FL
7	1		*TAILGATE REFLECTORS	N/S Cracked	729.20 F	*364.60 FL
8	1		*TAILGATE INNER LOCK	Twisted	181.90 F	*181.90 FL
9	1		*TAILGATE LOCK STRIKER	Not Necessary	48.60 F	*- FL
10	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	368.20 F	*368.20 FL
11	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
12	1		*TAILGATE INNER HANDLE HOLDER	Not Necessary	32.00 F	*- FL
13	2		*TAILGATE DAMPERS	Not Necessary	385.00 F	*- FL
14	1		*TAILGATE WEATHERSTRIP	Twisted	199.00 F	*199.00 FL
15	1		*REAR BUMPER	Distorted	863.50 F	*761.00 FL
16	1		*REAR BUMPER SIDES	N/S Dented	790.20 F	*395.10 FL
17	1		*REAR BUMPER REFLECTORS	N/S Cracked	330.00 F	*165.00 FL
18	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
19	1		*REAR BUMPER LOWER UNDER COVER	Deformed / Torn	312.00 F	*312.00 FL
20	1		*SET REAR BUMPER LOWER UNDER COVER CLIPS	Not Necessary	50.00 F	*- FL
21	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	90.00 F	*- FL
22	1		*REAR END PANEL	Badly Dented	517.00 F	*517.00 FL
23	1		*REAR END PANEL TOP GARNISH	Twisted	188.00 F	*188.00 FL
24	1		*TAILLAMPS	N/S Cracked	970.00 F	*460.50 FL
25	2		*TAILLAMP HOUSING PANELS	Repair	700.00 F	*- FL
26	1		*REAR FLOOR PANEL	Repair	1,330.20 F	*- FL
27	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	326.50 F	*- FL
28	1		*REAR FLOOR PANEL TOOLS SPONGE	Torn	688.00 F	*688.00 FL
29	1		*REAR LOCK SENSOR	Cracked	295.00 F	*295.00 FL
30	2		*REAR FENDERS	Repair	1,982.00 F	*- FL
31	1		*REAR FENDER INNER TRIMS	N/S Cracked	900.00 F	*388.20 FL
32	1		*REAR EXHAUST	Not Necessary	785.20 F	*- FL
33	1		*REAR EXHAUST HEATSHIELD	Not Necessary	188.90 F	*- FL
34	1		*REAR FENDER OUTER PROTECTORS	N/S Torn	598.00 F	*299.00 FL
35	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
36	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
37	1		*REAR LICENCE PLATE W/HOLDER	Not Necessary	50.00 FS	*- FS
38	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	180.00 FS	*- FS
39	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,801.70	7,070.20
- List Item Discount on L Items 0.00/20.00% (\$)	0.00	1,356.04
Total Parts (\$)	17,801.70	5,714.16

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
3	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO DISMANTLE & REFIX FUEL TANK	New	100.00	0.00
7	TO SPRAY RUST PROOFING	New	150.00	60.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	LABOUR FOR PANEL BEATING & REOLACED PARTS	New	1,800.00	800.00
10	TO PUTTY & SPRAY PAINTING	New	1,800.00	900.00
Gross Labour Cost (\$\$)			4,780.00	2,050.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >